



Bridge Number : 55C0008
Facility Carried: TRABUCO CANYON RD.
Location : 1.4 mi n/o Santa Margarit
City :
Inspection Date : 12/15/2013
Inspection Type
Routine FC Underwater Special Other
☒

Bridge Inspection Report

STRUCTURE NAME: TRABUCO CREEK

CONSTRUCTION INFORMATION

Year Built : 1980
Year Widened: N/A
Length (m) : 22.3
Skew (degrees): 33
No. of Joints : 2
No. of Hinges : 0

Structure Description: Simply supported 6-span PC/PS concrete deck slab units (7 each) with RC pier walls and RC open end seat abutments, all supported upon spread footings.

Span Configuration : (W) 6 @ 3.3 m (E) c/c

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: MS-18 OR HS-20
Inventory Rating: 32.6 metric tons
Operating Rating: 53.5 metric tons
Permit Rating : PPPPP
Posting Load : Type 3: Legal
Calculation Method: NO RATING ANALYSIS
Calculation Method: NO RATING ANALYSIS
Type 3S2: Legal
Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.1 m br, 7.1 m, 0.1 m br (N)
Total Width: 7.3 m Net Width: 7.1 m No. of Lanes: 2 Speed: 15 mph
Min. Vertical Clearance: Unimpaired

Rail Code: 0000

Rail Type	Location	Length (ft)	Rail Modifications
Miscellaneous	Right/Left	138	

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural cobbled earth trapezoidal with an RC invert through the site.

INSPECTION COMMENTARY

SCOPE AND ACCESS

There channel was dry at the time of the inspection, so all substructure elements were visually inspected. Pedestrian access is from NW corner.

MISCELLANEOUS

Photo underside of this structure was taken and is included with this report.

DECK AND ROADWAY

Few timber posts have splits and checks.

AC overlay exhibits transverse and longitudinal cracks above box walls 2 and 4.

The AC covered the joints, which could not be inspected.

INSPECTION COMMENTARY

SUPERSTRUCTURE

There are 2 spalls 4 ft X 1 ft X 3" with exposed rebars and rusted at the south edge of the deck in spans #5 and #6

SUBSTRUCTURE

There are eroded concrete at the invert with exposed rebars and rusted, where in span 5 the eroded area is 17 ft X 8 ft at the middle, and in span 6 the eroded area is 2 ft X 1 ft in the south end.

SCOUR

The downstream grouted riprap is degraded, and there are holes about 10 ft in diameter by 5 ft deep in the rip rap and the bottom of rip rap is exposed about 1 ft in the spans as follows: in span 4 the holes is 13 ft X 5 ft; in span 5 the holes is 10 ft X 4 ft; and #6 the holes is 7 ft X 4 ft.

<u>ELEMENT INSPECTION RATINGS</u>									
Elem No.	Element Description	Env	Total Qty Units	Qty in each Condition State					
				St. 1	St. 2	St. 3	St. 4	St. 5	
61	PS Conc Slab - Unprotected w/ AC Overlay	2	140 sq.m.	0	140	0	0	0	0
210	Reinforced Conc Pier Wall	2	45 m.	38	0	7	0		
215	Reinforced Conc Abutment	2	18 m.	18	0	0	0	0	
301	Pourable Joint Seal	2	18 m.	18	0	0	0	0	
312	Enclosed/Concealed Bearing	2	7 ea.	7	0	0	0	0	
321	Reinforced Conc Approach Slab w/ or w/o AC Ovly	2	4 ea.	0	4	0	0	0	
333	Other Bridge Railing	2	42 m.	30	12	0			

WORK RECOMMENDATIONS

RecDate: 05/21/2009

Action : Sub-Patch spalls

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Repair the eroded concrete at the invert in spans 5 & 6 with exposed rebars of an area 5 m x 2.5 m in the middle of the span.

RecDate: 05/01/2007

Action : Deck-Patch spalls

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:


EA:

Repair the 2 spalls 4 ft X 1 ft X 3" with exposed rebars at the south edge of the deck in spans #5 and #6.

Team Leader : Ashraf Shenouda
Report Author : Ashraf Shenouda
Inspected By : A. Shenouda/KD. Henderson

Ashraf Shenouda 2/16/14
Ashraf Shenouda (Registered Civil Engineer) (Date)

CC:



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0008
 (5) INVENTORY ROUTE(ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- TRABUCO CREEK
 (7) FACILITY CARRIED- TRABUCO CANYON RD.
 (9) LOCATION- 1.4 mi n/o Snta Margarita
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 39 MIN 33.53 SEC
 (17) LONGITUDE 117 DEG 35 MIN 10.59 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- PRESTRESS CONC
 TYPE- SLAB CODE 501
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 6
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- PRECAST CONC. PA CODE 2
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- NONE CODE 0
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1980
 (106) YEAR RECONSTRUCTED 0000
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 3000
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 10 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 3.4 M
 (49) STRUCTURE LENGTH 22.3 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 7.1 M
 (52) DECK WIDTH OUT TO OUT 7.3 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 7.3 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 33 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 7.1 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 60.7
 STATUS FUNCTIONALLY OBSOLETE
 HEALTH INDEX 88.8
 PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- COLLECTOR URBAN 17
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 6
 (59) SUPERSTRUCTURE 6
 (60) SUBSTRUCTURE 5
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- MS-18 OR HS-20 5
 (63) OPERATING RATING METHOD- NO RATING ANALYSIS 5
 (64) OPERATING RATING- 53.5
 (65) INVENTORY RATING METHOD- NO RATING ANALYSIS 5
 (66) INVENTORY RATING- 32.6
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 5
 (68) DECK GEOMETRY 2
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 4
 (72) APPROACH ROADWAY ALIGNMENT 4
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES 7

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- DECK REHABILITATION CODE 36
 (76) LENGTH OF STRUCTURE IMPROVEMENT 22.3 M
 (94) BRIDGE IMPROVEMENT COST \$163,000
 (95) ROADWAY IMPROVEMENT COST \$32,600
 (96) TOTAL PROJECT COST \$273,840
 (97) YEAR OF IMPROVEMENT COST ESTIMATE 2010
 (114) FUTURE ADT 8270
 (115) YEAR OF FUTURE ADT 2029

***** INSPECTIONS *****

(90) INSPECTION DATE 12/13 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)