



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0059
Facility Carried: SANTIAGO CANYON RD
Location : 0.8 MI N/O MODJESKA RD
City :
Inspection Date : 05/06/2019

Bridge Inspection Report

Inspection Type
Routine ☒ FC ☐ Underwater ☐ Special ☐ Other ☐

STRUCTURE NAME: WILLIAMS CANYON CREEK

CONSTRUCTION INFORMATION

Year Built : 1970 Skew (degrees): 0
Year Modified: 1983 No. of Joints : 0
Length (m) : 10.7 No. of Hinges : 0

Structure Description: Single span CIP/RC rigid frame deck slab supported upon spread footings.

Span Configuration : (S) 33.0 feet (N) .

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: MS-18 OR HS-20
Inventory Rating: 32.6 metric tons Calculation Method: LOAD FACTOR
Operating Rating: 53.5 metric tons Calculation Method: LOAD FACTOR
Permit Rating : PPPPP
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (W) 0.65 feet br, 52.2 feet, 0.65 feet br (E)
Total Width: 16.2 m Net Width: 15.9 m No. of Lanes: 2 Speed: 55 mph
Min. Vertical Clearance: Unimpaired Overlay Thickness: 0.0 inches
Rail Code: 0000

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with a cobbled bottom and with rock slopes upstream.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

A complete routine inspection was performed by walking on and around the bridge to inspect all visible elements of the bridge structure. Bridge deck was inspected by walking on shoulder. Soffit and all substructure were inspected by walking underneath the bridge.

The channel is dry at the time of inspection.

INSPECTION COMMENTARY

There is no need for a special equipment to inspect this structure.

DECK AND ROADWAY

The bridge deck surface has about twenty five percent of abrasion; and also, there are longitudinal and transverse deck cracks at (0.04 inches wide, 2.0 feet in spacing) throughout the entire deck.

The AC roadway is at both of approach and departure lanes with cracks and settlement about 1.0 to 2.0 inches deep mainly at westerly abutment.

SAFE LOAD CAPACITY

The load rating for this structure is being reviewed by SM&I Ratings Branch. An updated Load Rating Summary Sheet will be archived when this review is complete. The current rating is based on BDS computer output dated 10/10/1979.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each Condition State	St. 1	St. 2	St. 3	St. 4
38		Slab-RC	2	160	sq.m	90	70	0	0	0
1130		Cracking (RC and Other)	2	30		0	30	0	0	0
1190		Abrasion (PS Conc./RC)	2	40		0	40	0	0	0
(38)										
There were no significant defects noted.										
(38-1130)										
There are longitudinal and transverse hairline deck cracks at (0.04 inches wide, 2.0 feet in spacing) throughout the entire deck.										
(38-1190)										
The bridge deck surface has about twenty five percent of abrasion throughout the entire deck.										
215		Abutment-RC	2	48	m	47	0	1	0	0
6000		Scour	2	1		0	0	1	0	0
(215)										
There were no significant defects noted.										
(215-6000)										
There is an erosion gully at the southeast wing wall; it is caused by runoff water. The water has been causing this sinkhole at (5.0 feet L X 4.0 feet W X 3.0 feet D) at the easterly end of the southeast wing wall.										
330		Railing-Metal	2	20	m	20	0	0	0	0
(330)										
There were no significant defects noted.										

WORK RECOMMENDATIONS

RecDate: 05/06/2019

Action : Deck-Methacrylate

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Seal deck cracks with Methacrylate.


WORK RECOMMENDATIONS

RecDate: 05/06/2019	EstCost:	Repave Asphalt roadway at both of the
Action : Appr. Roadway-Repair	StrTarget: 2 YEARS	approach and departure lanes due to the
Work By: LOCAL AGENCY	DistTarget:	settlement and potholes.
Status : PROPOSED	EA:	
RecDate: 08/13/2015	EstCost:	Backfill this sinkhole at (5.0 feet L X
Action : Appr. Roadway-Repair	StrTarget: 2 YEARS	4.0 feet W X 3.0 feet D) at the easterly
Work By: LOCAL AGENCY	DistTarget:	end of the southeast wing wall with 90%
Status : PROPOSED	EA:	soil compaction.
RecDate: 05/13/2011	EstCost:	Provide suitable material at the
Action : Drainage Issue	StrTarget: 2 YEARS	southeast slope next to the southeast
Work By: LOCAL AGENCY	DistTarget:	wingwall to prevent future degradation
Status : PROPOSED	EA:	from runoff water.

Team Leader : Edwin Mah

Report Author : Nelson N. Vo

Inspected By : NN.Vo/E.Mah



Edwin Mah (Registered Civil Engineer) (Date)

8/22/2019



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0059
 (5) INVENTORY ROUTE (ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- WILLIAMS CANYON CREEK
 (7) FACILITY CARRIED- SANTIAGO CANYON RD
 (9) LOCATION- 0.8 MI N/O MODJESKA RD
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- PART OF NET 1
 (13) LRS INVENTORY ROUTE & SUBROUTE 000000000000
 (16) LATITUDE 33 DEG 43 MIN 43.55 SEC
 (17) LONGITUDE 117 DEG 39 MIN 01.01 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE
 TYPE- SLAB CODE 101
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 1
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- NONE CODE 0
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1970
 (106) YEAR RECONSTRUCTED 1983
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 8000
 (30) YEAR OF ADT 2019 (109) TRUCK ADT 3 %
 (19) BYPASS, DETOUR LENGTH 22 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 10.1 M
 (49) STRUCTURE LENGTH 10.7 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 15.9 M
 (52) DECK WIDTH OUT TO OUT 16.2 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 15.9 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 15.9 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 75.4
 PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- ROUTE ON NHS 1
 (26) FUNCTIONAL CLASS- OTHER PRIN ART URBAN 14
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 5
 (59) SUPERSTRUCTURE 5
 (60) SUBSTRUCTURE 7
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- MS-18 OR HS-20 5
 (63) OPERATING RATING METHOD- LOAD FACTOR 1
 (64) OPERATING RATING- 53.5
 (65) INVENTORY RATING METHOD- LOAD FACTOR 1
 (66) INVENTORY RATING- 32.6
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 5
 (68) DECK GEOMETRY 9
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 8
 (72) APPROACH ROADWAY ALIGNMENT 8
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES 8

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 12365
 (115) YEAR OF FUTURE ADT 2037

***** INSPECTIONS *****

(90) INSPECTION DATE 05/19 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)