Page 1 of 3



DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

Bridge Number : 55C0103

Facility Carried: HAMILTON-VICTORIA

Location :

: 0.15 MI E/O BROOKHURST S

City

Inspection Date : 05/05/2010

Inspection Type

Bridge Inspection Report

Routine FC Underwater Special Other

STRUCTURE NAME: SANTA ANA RIVER

CONSTRUCTION INFORMATION

 Year Built : 1979
 Skew (degrees): 16

 Year Widened: 1992
 No. of Joints : 3

 Length (m) : 136.6
 No. of Hinges : 1

Structure Description: Continuous 7 span CIP/RC box girder (9 cells) with RC piers and RC open end diaphragm abutments, all supported upon concrete piles.

Span Configuration : (W) 24.4 m, 3 @ 28.8 m, 24.8 m, 28.6 m, 28.2 m (E)

LOAD CAPACITY AND RATINGS

Design Live Load: MS-18+MOD OR HS-20+MOD

Inventory Rating: 32.4 metric tonnes Calculation Method: NO RATING ANALYSIS
Operating Rating: 54.1 metric tonnes Calculation Method: NO RATING ANALYSIS

Permit Rating : PPPPP

Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (N) 0.3 m br, 1.5 m sw, 23.8 m, 1.5 m sw, 0.3 m br (S)

Total Width: 24.4 m Net Width: 23.8 m No. of Lanes: 4
Rail Description: (S) Type 11 in spans 1-5, (s) spans 6-7 and (N) Rail Code : 1000

Type 26 conc.

Min. Vertical Clearance: Unimpaired

DESCRIPTION UNDER STRUCTURE

Channel Description: Santa Ana River: Sandy bottom with grouted rock slopes through the

site.

Greenville-Banning: Sandy bottom with RC vertical walls.

CONDITION TEXT

CONDITION OF STRUCTURE

There are transverse cracks in the deck over the supports moderate in size (0.5-1 mm) and density (less than 300 mm), mostly in eastbound lanes of old structure.

There is damaged section of the south railing metal tube (6 meters long) located 12m from west end.

There is a spall (150 mm \times 75 mm \times 50 mm) with exposed rebar at the south curb 30 from west end.

There was 200 mm water in the deeper section of the channel; all elements were inspected.

Printed on: Monday 08/16/2010 10:27 AM 55C0103/AAAH/18551

| ELE | MENT | INSPECTION RATINGS | | | | | | | | |
|------|------|--------------------------------|-----|-------|-------|-------|---------|----------|----------|-------|
| F#El | em I | Element Description | Env | Total | Units | Qt | y in ea | ch Condi | tion Sta | te |
| | | | | Qty | | St. 1 | St. 2 | St. 3 | St. 4 | St. 5 |
| 101 | 12 | Concrete Deck - Bare | 2 | 3030 | sq.m. | 3030 | 0 | 0 | 0 | 0 |
| 101 | 105 | Reinforced Concrete Closed | 2 | 390 | m. | 390 | 0 | 0 | 0 | 0 |
| | | Webs/Box Girder | 1.4 | | | | | | | |
| 101 | 210 | Reinforced Conc Pier Wall | 2 | 180 | m. | 180 | 0 | 0 | 0 | 0 |
| 101 | 215 | Reinforced Conc Abutment | 2 | 60 | m. | 60 | 0 | 0 | 0 | 0 |
| 101 | 227 | Reinforced Conc Submerged Pile | 2 | 1 | ea. | 1 | 0 | 0 | 0 | 0 |
| 101 | 302 | Compression Joint Seal | 2 | 87 | m. | 87 | 0 | 0 | 0 | 0 |
| 101 | 331 | Reinforced Conc Bridge Railing | 2 | 200 | m. | 200 | 0 | 0 | 0 | 0 |
| 101 | 335 | Other Bridge Railing | 2 | 100 | m. | 94 | 6 | 0 | 0 | 0 |
| 101 | 358 | Deck Cracking | 2 | 1 | ea. | 0 | 0 | 1 | 0 | 0 |

WORK RECOMMENDATIONS

| RecDate: 05/05/2010 Action: Railing-Repair Work By: LOCAL AGENCY Status: PROPOSED | EstCost: StrTarget: 2 DistTarget: EA: | 2 YEARS | Repair the spall (150 mm x 75 mm x 50 mm) with exposed rebar at the south curb 30 from west end. |
|---|---------------------------------------|---------|---|
| RecDate: 06/11/2007 Action : Deck-Methacrylate Work By: LOCAL AGENCY Status : PROPOSED | EstCost: StrTarget: 2 DistTarget: EA: | 2 YEARS | Seal the deck transverse cracks by methacrylate in eastbound lanes of old structure. Most crack are over the supports and are moderate in size (0.5-1mm) and density (less than 300mm). |
| RecDate: 01/30/2003 Action : Railing-Repair Work By: LOCAL AGENCY Status : PROPOSED | EstCost: StrTarget: 2 DistTarget: EA: | 2 YEARS | Replace the damaged 6.1 m of damaged 152 mm structural tube railing in the southerly railing, approximately 12.2 m from its westerly terminus. Remove the fractured concrete at two of the anchor posts, and patch with epoxy bonded cement mortar. |

Inspected By : A.Shenouda/MT.Zaarour

Registered Civil Engineer



STRUCTURE INVENTORY AND APPRAISAL REPORT

| 27.72 | ************************************** | | ************************************** |
|--|--|---|--|
| | STATE NAME- CALIFORNIA 069 | | STATUS |
| | STRUCTURE NUMBER 55C0103 | | HEALTH INDEX 100.0 |
| | INVENTORY ROUTE (ON/UNDER) - ON 1400M0360 | | PAINT CONDITION INDEX = N/A |
| 0.000 | HIGHWAY AGENCY DISTRICT 12 | | ******** CLASSIFICATION ******** CODE |
| 10.00 | COUNTY CODE 059 (4) PLACE CODE 00000 | (212) | NBIS BRIDGE LENGTH- YES Y |
| | FEATURE INTERSECTED- SANTA ANA RIVER | | The state of the s |
| | FACILITY CARRIED- HAMILTON-VICTORIA | | FUNCTIONAL CLASS- MINOR ARTERIAL URBAN 16 |
| | LOCATION- 0.15 MI E/O BROOKHURST ST | | DEFENSE HIGHWAY- NOT STRAHNET 0 |
| (0.000) | MILEPOINT/KILOMETERPOINT 0 | | PARALLEL STRUCTURE - NONE EXISTS N |
| 100000 | BASE HIGHWAY NETWORK- NOT ON NET 0 | | DIRECTION OF TRAFFIC- 2 WAY 2 |
| (13) | LRS INVENTORY ROUTE & SUBROUTE | 100000000000000000000000000000000000000 | TEMPORARY STRUCTURE- |
| (16) | LATITUDE 33 DEG 39 MIN 03 SEC | | FED.LANDS HWY- NOT APPLICABLE 0 |
| | LONGITUDE 117 DEG 57 MIN 07 SEC | | DESIGNATED NATIONAL NETWORK - NOT ON NET 0 |
| (98) | BORDER BRIDGE STATE CODE % SHARE % | | TOLL- ON FREE ROAD 3 |
| (99) | BORDER BRIDGE STRUCTURE NUMBER | | MAINTAIN- COUNTY HIGHWAY AGENCY 02 |
| 1 | ****** STRUCTURE TYPE AND MATERIAL ****** | 0.0000000000000000000000000000000000000 | OWNER- COUNTY HIGHWAY AGENCY 02 |
| | STRUCTURE TYPE MAIN: MATERIAL- CONCRETE CONT | | HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5 |
| (40) | TYPE- TEE BEAM CODE 204 | (37) | TOT BELLEVED |
| (44) | STRUCTURE TYPE APPR:MATERIAL- OTHER/NA | | ********** CONDITION ********** CODE |
| | TYPE- OTHER/NA CODE 000 | (58) | DECK 5 |
| (45) | NUMBER OF SPANS IN MAIN UNIT 7 | (59) | SUPERSTRUCTURE 7 |
| (46) | NUMBER OF APPROACH SPANS 0 | | SUBSTRUCTURE 7 |
| (107) | DECK STRUCTURE TYPE- CIP CONCRETE CODE 1 | | CHANNEL & CHANNEL PROTECTION 9 |
| | WEARING SURFACE / PROTECTIVE SYSTEM: | (62) | CULVERTS |
| 14 C CE C | TYPE OF WEARING SURFACE- NONE CODE O | | ****** LOAD RATING AND POSTING ****** CODE |
| B) | TYPE OF MEMBRANE- NONE CODE 0 | (31) | DESIGN LOAD- MS-18+MOD OR HS-20+MOD 6 |
| C) | TYPE OF DECK PROTECTION- NONE CODE 0 | (63) | OPERATING RATING METHOD- NO RATING ANALYSIS 5 |
| | ******** AGE AND SERVICE ********** | (64) | OPERATING RATING- 54.1 |
| (27) | YEAR BUILT 1979 | (65) | INVENTORY RATING METHOD- NO RATING ANALYSIS 5 |
| (106) | YEAR RECONSTRUCTED 1992 | (66) | INVENTORY RATING- 32.4 |
| (42) | TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5 | (70) | BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5 |
| (00) | UNDER- WATERWAY 5 | (41) | STRUCTURE OPEN, POSTED OR CLOSED- A |
| | LANES:ON STRUCTURE 04 UNDER STRUCTURE 00 AVERAGE DAILY TRAFFIC 24000 | | DESCRIPTION- OPEN, NO RESTRICTION |
| | YEAR OF ADT 2000 (109) TRUCK ADT 1 % | | ****** APPRAISAL ******** CODE |
| | | | OMDITOMINAT BUATUMATON |
| (19) | BIFASS, DETOOK BENCIN | | DECK GEOMETRY 9 |
| | ******* GEOMETRIC DATA ********** | | UNDERCLEARANCES, VERTICAL & HORIZONTAL N |
| | LENGTH OF MAXIMUM SPAN 28.8 M | | WATER ADEQUACY 9 |
| 100000000000000000000000000000000000000 | STRUCTURE LENGTH 136.6 M | (72) | APPROACH ROADWAY ALIGNMENT 8 |
| | CURB OR SIDEWALK: LEFT 1.5 M RIGHT 1.5 M | (36) | TRAFFIC SAFETY FEATURES 1000 |
| | BRIDGE ROADWAY WIDTH CURB TO CURB 23.8 M DECK WIDTH OUT TO OUT 24.4 M | (113) | SCOUR CRITICAL BRIDGES 8 |
| | DECK WIDTH OUT TO OUT 24.4 M APPROACH ROADWAY WIDTH (W/SHOULDERS) 20.4 M | | ****** PROPOSED IMPROVEMENTS ******* |
| | BRIDGE MEDIAN- NO MEDIAN 0 | (75) | TYPE OF WORK- CODE |
| | SKEW 16 DEG (35) STRUCTURE FLARED NO | | LENGTH OF STRUCTURE IMPROVEMENT M |
| | INVENTORY ROUTE MIN VERT CLEAR 99.99 M | 200000000000000000000000000000000000000 | BRIDGE IMPROVEMENT COST |
| | INVENTORY ROUTE TOTAL HORIZ CLEAR 23.8 M | | ROADWAY IMPROVEMENT COST |
| | MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M | / | TOTAL PROJECT COST |
| | MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M | | YEAR OF IMPROVEMENT COST ESTIMATE |
| (55) | MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M | | FUTURE ADT 49459 |
| (56) | MIN LAT UNDERCLEAR LT 0.0 M | | YEAR OF FUTURE ADT 2029 |
| | ************ NAVIGATION DATA ********** | ,/ | |
| (38) | NAVIGATION CONTROL- NOT APPLICABLE CODE N | /001 | ************************************** |
| | PIER PROTECTION- CODE | | INSPECTION DATE 05/10 (91) FREQUENCY 24 MO CRITICAL FEATURE INSPECTION: (93) CFI DATE |
| | NAVIGATION VERTICAL CLEARANCE 0.0 M | | FRACTURE CRIT DETAIL- NO MO A) |
| (116) | VERT-LIFT BRIDGE NAV MIN VERT CLEAR M | | UNDERWATER INSP- NO MO B) |
| (40) | NAVIGATION HORIZONTAL CLEARANCE 0.0 M | | OTHER SPECIAL INSP- NO MO C) |