
Bridge Inspection Records Information System

The requested documents have been generated by the BIRIS.

The documents provided are considered confidential and may only be released outside of the department of transportation upon proper execution of the confidentiality agreement.

State of California
Department of Transportation

**Division of Maintenance
Structures Maintenance & Investigations**



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0121
Facility Carried: BREA BLVD
Location : 0.4 MI N CENTRAL AVE
City :
Inspection Date : 05-JUN-01

Inspection Type

Routine ☒ Group A ☐ Underwater ☐ Special ☐ Other ☐

Bridge Inspection Report**Name : BREA CANYON CHANNEL****CONSTRUCTION INFORMATION**

Year Built : Unknown
Year Widened : 1929
Length (m) : 9.1

Skew (degrees): 32
No. of Joints : 0
No. of Hinges : 0

Description of Structure : Continuous 2-span CIP/RC deck slab with an RC pier and RC closed end backfilled strutted abutments. Foundation type is unknown.

Span Configuration : (S) 2 @ 4.1 m (N) c/c

LOAD CAPACITY AND RATINGS

Design Live Load : OTHER OR UNKNOWN

Inventory Rating : 32.6 metric tons

Operating Rating : 53.5 metric tons

Permit Rating : PPPPP

Posting Load : Type 3 N/A english tons Type 3S2 N/A english tons Type 3-3 N/A english tons

Calculation Method : LOAD FACTOR

Calculation Method : LOAD FACTOR

DESCRIPTION ON STRUCTURE

Bridge width : (W) 3.4 m ea, 2 @ 5.6 m, 0.9 m ea (E)

Total Width : .0 m

Net Width : 11.30 m

No. of Lanes : 2

Rail Description : (E) MBGR (W) None

Rail Code : 0000

Min. Vertical Clearance : Unimpaired

DESCRIPTION UNDER STRUCTURE

Channel Description : Natural earth trapezoidal with heavy bushes and trees in the channel bed.

CONDITION OF STRUCTURE

Because of water in the channel, only a surface inspection was performed.

There is a concrete spall (0.15 m x 0.6 m x 0.1 m) in the upstream nose of the pier. Probably impacted by debris. There are minor cracks in both ends of pier wall. (O)

Otherwise, the structure is in good condition.

MISCELLANEOUS**ELEMENT LEVEL INSPECTION RATINGS**

| F# | Elem | Element Description | Env | Total Units Quantity | Qty in each Condition State | | | | |
|--------|------|--|-----|-------------------------|-----------------------------|-------|-------|-------|-------|
| | | | | | St. 1 | St. 2 | St. 3 | St. 4 | St. 5 |
| 01 39 | | Concrete Slab - Unprotected w/ AC Overlay | 2 | 100 sq.m. | 100 | 0 | 0 | 0 | 0 |
| 01 210 | | Reinforced Conc Pier Wall | 2 | 17m. | 16 | 1 | 0 | 0 | 0 |
| 01 215 | | Reinforced Conc Abutment | 2 | 34m. | 34 | 0 | 0 | 0 | 0 |

WORK RECOMMENDATIONS

Remove the bushes and the trees in the channel bed within 30 meters of the bridge to allow the water to flow properly.

| Item# | Rec. Date | Work By | Work Id. | Prog. Method | Cost |
|-------|-----------|---------|----------|--------------|------|
|-------|-----------|---------|----------|--------------|------|

1

Printed on : 08-JUN-2001 10:20:11 AM

Bridge No.: 55C0121

Location: 0.4 MI N CENTRAL AVE

Inspection Date: 05-JUN-01

05-JUN-2001

County Agency

40121X01156X

Inspected By : M. Ogata

M. Ogata
Registered Civil Engineer



CC : TMRut
Orange County

Bridge No.: 55C0121

Location: 0.4 MI N CENTRAL AVE

Inspection Date: 05-JUN-01

STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME - CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0121
 (5) INVENTORY ROUTE (ON/UNDER) - ON 140 0M003N
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED - BREA CANYON CHANNEL
 (7) FACILITY CARRIED - BREA BLVD
 (9) LOCATION - 0.4 MI N CENTRAL AVE
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK - NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 56 MIN 16 SEC
 (17) LONGITUDE 117 DEG 53 MIN 31 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN: MATERIAL - CONCRETE
 TYPE - SLAB CODE 1 01
 (44) STRUCTURE TYPE APPR: MATERIAL -
 TYPE - CODE
 (45) NUMBER OF SPANS IN MAIN UNIT 2
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE - CONCRETE CODE 1
 B) TYPE OF MEMBRANE - NONE CODE 0
 C) TYPE OF DECK PROTECTION - NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT
 (106) YEAR RECONSTRUCTED 1929
 (42) TYPE OF SERVICE: ON - HIGHWAY 1
 UNDER - WATERWAY 5
 (28) LANES: ON STRUCTURE 02 UNDER STRUCTURE
 (29) AVERAGE DAILY TRAFFIC 15000
 (30) YEAR OF ADT 1999 (109) TRUCK ADT 2%
 (19) BYPASS, DETOUR LENGTH 2 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 4.3 M
 (49) STRUCTURE LENGTH 9.1 M
 (50) CURB OR SIDEWALK: LEFT 0 M RIGHT 0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 11.3 M
 (52) DECK WIDTH OUT TO OUT 0 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 11 M
 (33) BRIDGE MEDIAN - CLOSED (NO BARRIER) 2
 (34) SKEW 32 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 8.5 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF - NOT H/RR 0 M
 (55) MIN LAT UNDERCLEAR RT REF - NOT H/RR 0 M
 (56) MIN LAT UNDERCLEAR LT 0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL - NOT APPLICABLE CODE N
 (111) PIER PROTECTION - NOT REQUIRED CODE 1
 (39) NAVIGATION VERTICAL CLEARANCE 0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR 0 M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0

***** SUFFICIENCY RATING = 93.6 *****

STATUS =

HEALTH INDEX = 99.01

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH - YES Y
 (104) HIGHWAY SYSTEM - NOT ON NHS 0
 (26) FUNCTIONAL CLASS - LOCAL URBAN 19
 (100) DEFENSE HIGHWAY - NOT STRAHNET 0
 (101) PARALLEL STRUCTURE - NONE EXISTS N
 (102) DIRECTION OF TRAFFIC - 2 WAY 2
 (103) TEMPORARY STRUCTURE -
 (105) FEDERAL LANDS HIGHWAY - NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL - ON FREE ROAD 3
 (21) MAINTAIN - COUNTY HIGHWAY AGENCY 2
 (22) OWNER - COUNTY HIGHWAY AGENCY 2
 (37) HISTORICAL SIGNIFICANCE - NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 7
 (59) SUPERSTRUCTURE 7
 (60) SUBSTRUCTURE 7
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD - OTHER OR UNKNOWN 0
 (63) OPERATING RATING METHOD - LOAD FACTOR 1
 (64) OPERATING RATING - 53.5
 (65) INVENTORY RATING METHOD - LOAD FACTOR 1
 (66) INVENTORY RATING - 32.6
 (70) BRIDGE POSTING - Equal to or above legal loads 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED - A
 DESCRIPTION - OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 7
 (68) DECK GEOMETRY 4
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 9
 (72) APPROACH ROADWAY ALIGNMENT 8
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES U

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK - CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 30000
 (115) YEAR OF FUTURE ADT 2019

***** INSPECTIONS *****

(90) INSPECTION DATE 06/01 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL - NO -1 MO A)
 B) UNDERWATER INSP - NO -1 MO B)
 C) OTHER SPECIAL INSP - NO -1 MO C)

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation April 14, 1939

Name BREA CANYON VII-Ora-19-A
Location 4.3 Miles north of junction with Route 2. Sta. 15+48
Dist.-Co.-Rt.-Sec.

Refer to original report dated April 1938 and subsequent supplementary report.

WORK DONE:-

Work Order #07XX19, \$1500, has been issued July 25, 1938 along with a supplement to Work Order #07J1 to:

- (1) Replace the failed original portion with a new RC slab on a central RC wall pier and RC wing abutments.
 - (2) Strengthen the 1929 portion by extending the central RC wall.
- All work in accordance with Drawing # DL-840-2 & 3.

All work has been done properly in accordance with the two previous reports.

PRESENT CONDITION OF STRUCTURE:-

The structure is now in good condition and all members are acting properly.

RECOMMENDATIONS:-

No work is recommended at this time.

Next investigation, April 1940.

Fred M. Barnes

by John L. Beaton JLB-CFH

Investigated 5/13/41 By RAW-

Next Investigation 5/43

Changes Noted None.

cc: District VII (2)
Maintenance Dept.
Mr. Wagner

SEE SUPPLEMENTARY REPORT OF JUN 3 1943 FOLLOWING

Bridge Number 55C-121

Location 12 - Ora - FAS M003-CR
Dist.-Co.-Rte.-City

Date of Investigation September 10, 1997

TYPE OF INVESTIGATION/REPORT

| | | | |
|------------|----------|--------|-----|
| BIENNIAL | <u>X</u> | DAMAGE | ___ |
| CATEGORY A | ___ | OTHER | ___ |
| UNDERWATER | ___ | OFFICE | ___ |

Name BREA CANYON CHANNEL (Brea Boulevard, 0.4 mile north of Central Avenue)

CONDITION RATINGS:

Element Level Inspection (ELI) form attached.

Channel & Channel Protection

8

SCOUR CRITICAL:

A scour rating of A-1 is appropriate.

MISCELLANEOUS DISCUSSION:

The inspection team consisted of Makoto Ogata and Faye Kirchhoff.

CONDITION OF STRUCTURE:

There is a concrete spall (0.15 m x 0.6 m x 0.1 m) in the upstream nose of the pier. Probably impacted by debris. There are minor cracks in both ends of pier wall. (0)

Otherwise, the condition of the structure is good.

WORK RECOMMENDED:

None.

M. Ogata
M. Ogata



MO:cd
c: TMRut
Orange County

INFORMATION ONLY - NOT FOR UPDATE

| | |
|-----------------------------|----|
| SCOUR CRITICAL..... | NO |
| GROUP A INVESTIGATION..... | NO |
| FRACTURE CRITICAL..... | NO |
| ELIGIBLE FOR RAIL UPGRADE.. | NO |
| UNDERWATER INVESTIGATION... | NO |

| | |
|----------|-----|
| DISTRICT | 12 |
| COUNTY | ORA |
| ROUTE | |
| POSTMILE | |
| NAME | |

[illegible]

55C SHAWN ZANGANEH

BY:

no

Bridge Number 55C-121

Location 12 - Ora - FAS M003-CR
Dist.-Co.-Rte.-City

Date of Investigation July 14, 1995

TYPE OF INVESTIGATION/REPORT

| | | | |
|------------|----------|--------|-----|
| BIENNIAL | <u>X</u> | DAMAGE | ___ |
| CATEGORY A | ___ | OTHER | ___ |
| UNDERWATER | ___ | OFFICE | ___ |

Name BREA CANYON CHANNEL (Brea Boulevard, 0.4 mile north of Central Avenue)

CONDITION RATINGS:

Condition ratings of all bridge elements are shown on the PONTIS DATA FORM (Attachment A).

Channel & Channel Protection

8

SCOUR CRITICAL:

A scour rating of A-1 is appropriate.

CONDITION OF STRUCTURE:

Surface inspection only. No access to bottom of river.

There are minor cracks in both ends of pier wall.


Condition of structure is good.

WORK RECOMMENDED:

None.

BY M. Hadi Behrooj ^{MHB}
G. P. Balinghasay

GPB:cd
cc: CDHarris
Orange County
WLindsey



ELEMENT LEVEL INSPECTION - (ELI)

| BRIDGE NUMBER | FRAME | INSPECTION DATE |
|---------------|-------|-----------------|
| 55C0121 | 01 | 071495 |
| 1 | 9 | 11 16 |

INFORMATION ONLY - NOT FOR UPDATE

| | |
|-----------------------------|----|
| SCOUR CRITICAL..... | NO |
| GROUP A INVESTIGATION..... | NO |
| FRACTURE CRITICAL:..... | NO |
| ELIGIBLE FOR RAIL UPGRADE.. | NO |
| UNDERWATER INVESTIGATION... | NO |

DISTRICT _____ 12
COUNTY _____ ORA
ROUTE _____
POSTMILE _____
NAME _____

[illegible]

10. *Chlorophyll a* and *Chlorophyll b* content of the leaves was determined by the method of Arnon and Whistler (1940).

25 SHAWN LANGANEH

22

INFORMATION ONLY - NOT FOR UPDATE

BRIDGE NUMBER FRAME INSPECTION DATE

| | | | | | | |
|---|---|---|---|---|---|---|
| 5 | 5 | C | O | I | Z | I |
|---|---|---|---|---|---|---|

1 8 9 11 16

| | |
|---------------------------|----|
| SCOUR CRITICAL | NO |
| CATEGORY A | NO |
| FRACTURE CRITICAL | NO |
| ELIGIBLE FOR RAIL UPGRADE | NO |
| UNDERWATER INSPECTION | NO |

DISTRICT 12
COUNTY ORA
ROUTE
POSTMILE
NAME

[illegible]

BY: [Signature]

Bridge Number 55C-121

TYPE OF INVESTIGATION/REPORT

| | | | |
|------------|----------|--------|-----|
| BIENNIAL | <u>X</u> | DAMAGE | ___ |
| CATEGORY A | ___ | OTHER | ___ |
| UNDERWATER | ___ | OFFICE | ___ |

Location 12 - Ora - FAS M003-CR
Dist.-Co.-Rte.-City

Date of Investigation April 16, 1993

Name BREA CANYON CHANNEL (Brea Boulevard, 0.4 mile north of Central Avenue)

CONDITION RATINGS:


Condition ratings of all bridge elements are shown on the PONTIS DATA FORM (Attachment A).

Channel & Channel Protection

8

CONDITION OF STRUCTURE:

Condition of the structure is good.


Henry Ma

HM:cd
cc: INagai (2)
County of Orange



(ATTACHMENT A)

INFORMATION ONLY - NOT FOR UPDATE

| BRIDGE NUMBER | FRAME | INSPECTION DATE |
|---------------|-------|-----------------|
| 55C0121 | 01 | 041693 |
| 1 | 9 | 11 |
| 8 | | 16 |

| | |
|---------------------------|----|
| SCOUR CRITICAL | NO |
| CATEGORY A | NO |
| FRACTURE CRITICAL | NO |
| ELIGIBLE FOR RAIL UPGRADE | NO |
| UNDERWATER INSPECTION | NO |

| | |
|----------|-------|
| DISTRICT | 12 |
| COUNTY | ORA |
| ROUTE | *** |
| POSTMILE | ***** |
| NAME | |

[illegible]

BY:

BRIDGE REPORT

DS-M58 (REV. 1/91)

14V32

Bridge No. 55C - 121

Location 12 - Ora - FAS M003-CR
Dist Co Rte City

REVISED ORIGINAL REPORT

Date of Investigation April 12, 1991

Name BREA CANYON CHANNEL (Brea Boulevard, 0.4 mile north of
Central Avenue)

Lat. 33° - 56.3'N Long. 117° - 53.4'W

Custodian County of Orange Owner County of Orange

STRUCTURAL DATA AND HISTORY

Year Built Unknown By County of Orange Contract No. Unknown
See Page 2

Designed by: County Plans Avail. @ None

Description: 2 span CIP RC slab supported by RC pier wall and closed
end backfilled RC strutted abutments under 4'± of fill
and AC surfacing. Foundation unknown.

Spans (S) 2 @ 13.6' (N)

Length 30' NBIS Bridge, Length Yes Skew 32° Left

Number Of Intermediate Joints: @Hinges None @Bents None

Maximum Column/Pier Height: (Less than 20') X (20'-29') (30' & Over)

Design Live Load Unknown Design Method Unknown

DESCRIPTION - ON STRUCTURE

Bridge Width (W) 11'ea, 37', 3'ea, MBGR, 5'± ea (E)

Total Width 56' Net Width 37' Lanes 2 Tracks None

Median None Rail Type (W) None (E) MBGR 0000

Vert. Clearance over deck Unimpaired Appr. Rdwy. Width 36'

Deck Type 1 Wearing Surface/Prot. Sys. 100

Alignment Tangent

DESCRIPTION - UNDER STRUCTURE

Roadway Section None

Clearances: Road: Vert. Horiz.Lt. ; Rt.

Lanes Tracks

Facilities Crossed Brea Canyon Channel (A 04)

April 12, 1991

DESCRIPTION - HYDRAULICS

Channel Natural canyon channel with heavy vegetation growthNavigable: Yes ☐ No ☒ Clearances: Vert. _____ Horiz. _____Pier/Abutment Protection (For Navigation) ☐

TRAFFIC INFORMATION

| | DECK | YEAR | UNDER | YEAR |
|-------------------------------------|-----------------|-----------------------------|-------|------|
| Average Daily Traffic & Year : | 16,000 | 1989 | N | |
| Average Daily Traffic (Future) : | 18,000 Est | 2010 | N | |
| Average Daily Trucks (% OF ADT) : | 1% Est | | N | |
| Bypass Detour Length | 1 mile | | N | |
| Shell Route: | No | | No | |
| Functional Classification : | 09 | | N | |
| LOAD RATINGS: | Inventory HS 20 | Operating HS 33 | | |
| | Permit PPPPP | Computation Method Assigned | | |

CONDITION RATINGS:

| | | | | | |
|------------------------------|---|----------------|---|--------------|-----|
| Deck | N | Superstructure | 7 | Substructure | 7 |
| Channel & Channel Protection | 8 | Culvert | N | Widenable | Yes |

APPRAISAL RATINGS:

| | | | |
|-------------------|---|----------------------------|---|
| Waterway Adequacy | 9 | Approach Roadway Alignment | 8 |
|-------------------|---|----------------------------|---|

Date of Revisions _____

STRUCTURAL DATA AND HISTORY (Con't.)

Date of Revision: 1929, widened
1938, repaired and reconstructed


CONDITION OF STRUCTURE:

There is minor concrete cracking at both ends of the pier wall.
Condition of the structure is good.


Henry Ma

HM:ms

cc: INagai (2)
County of Orange



SUPPLEMENTARY BRIDGE REPORT

DS-M19 (REV. 1/89)

Bridge No. 55C-121

Location 12-Ora - FAS M003 - CR
Dist. Co. Rte. City

Date of Investigation 4-17-89

Name BREA CANYON (Brea Boulevard, 1.1 miles west of Route 57)

CONDITION RATING:

Deck N Superstructure 7 Substr.&Pipes 7

Channel & Channel Protection 5 Culvert N

Widenable? No

TYPE OF INVESTIGATION/REPORT

BIENNIAL X DAMAGE

CATEGORY A OTHER

UNDERWATER OFFICE

CONDITION OF STRUCTURE:

There is a previous broken piece of concrete at the west end (downstream) of the pier.

Condition of the structure is fair.

REVISION:

Location: 12-Ora-FAS M003-CR

ADT: 16,000 (1988)

WORK RECOMMENDED:

None.

RECOMMENDED POSTING:

None.

SUBSTRUCTURE CODING UPDATE:

2 RC open end abutments, foundation unknown.

1 RC pier wall, foundation unknown.

Henry Ma

HM:ms

cc: INagai (2)

County of Orange (2)



STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
SUPPLEMENTARY BRIDGE REPORT
DH-OS M19 (REV. 1/74)

Bridge No. 55C-121
Location 7-Ora-FAS M003-CR
Dist - Co - Rte - PM - City
Date of Investigation April 23, 1987

Name BREA CANYON (Brea Blvd., 1.1 mile west of Rte. 57)

| CONDITION RATING: | | APPRAISAL RATING: | |
|------------------------------|-----------------|-------------------|---------|
| N | 7 | 7 | 7 |
| Deck | Superstructure | Substr. & Pipes | Overall |
| | 5 | N | |
| Channel & Channel Protection | Retaining Walls | | |

Widenable? Yes ☐ No ☒ Conditional ☐

Action Required By County Yes ☐ No ☒

PRIORITY

A - Immediate Action
B - Early Scheduling
C - Routine Maint.
O - For Record Only

REVISION:

Condition Rating: Deck - N

CONDITION OF STRUCTURE:

Overall condition of the structure is good.

RECOMMENDED POSTING:

None


WORK RECOMMENDED:

None

HM:pht

cc: INagai (2)
Orange County (2)

Henry Ma



STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
SUPPLEMENTARY BRIDGE REPORT
DH-05 M19 (REV. 1/74)

Bridge No. 55C-121
Location 7-Ora-FAS M003-CR
Dist - Co - Rte - PG - City (On Deck)
Date of Investigation November 14, 1985

Name BREA CANYON (Brea Blvd., 1.1 mile west of Rte. 57)

CONDITION RATING:

APPRAISAL RATING:

Deck 7 Superstructure 7 Substr. & Pipes 7 Overall 7
Channel & Channel Protection 5 Retaining Walls N

Widenable? Yes ☒ No ☐ Conditional ☐

Action Required by County Yes ☒ No ☐

PRIORITY

A - Immediate Action
B - Early Scheduling
C - Routine Maint.
O - For Record Only

WORK NOT DONE:

Previously recommended work to clean debris and drift from the creek has not been done.

CONDITION OF STRUCTURE:

The overall condition of the structure is good.

RECOMMENDED POSTING:


None

WORK RECOMMENDED:

Clean debris and drift out of the creek.

C

HM:pdh
cc: INagai (2)
Orange County (2)


Henry Ma
C-36817

STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
SUPPLEMENTARY BRIDGE REPORT
DH-05 M19 (REV. 1/74)

14032-
Bridge No. 55C-121
Location 7-Ora-FAS M003-CR
Dist - Co - Rte - PM - City (On Deck)
Date of Investigation July 13, 1983

Name BREA CANYON (Brea Blvd., 1.1 mile west of Rte. 57)

CONDITION RATING:

APPRAISAL RATING:

Deck 7 Superstructure 7 Substr. & Pipes 7 Overall 7
Channel & Channel Protection 5 Retaining Walls N

Widenable? Yes ☒ No ☐ Conditional ☐

Action Required by ~~XXXX~~ County ~~XXXX~~ Yes ☒ No ☐

PRIORITY

A - Immediate Action
B - Early Scheduling
C - Routine Maint.
O - For Record Only

CONDITION OF STRUCTURE:

There is much debris wrapped around the center pier nose.
Several fallen trees are upstream in the creek.

Otherwise, the condition of the structure is good.

RECOMMENDED POSTING:

None

RECOMMENDATION:

Clean the debris and drift out of the creek.

E. L. Neff
E. L. Neff
C-28703

ELN:pdh
cc: DRHiggins (2)
Orange County (2)

STATE OF CALIFORNIA
DEPARTMENT OF TRANSPORTATION
SUPPLEMENTARY BRIDGE REPORT
DH-OS M19 (REV. 1/74)

Bridge No. 55C-121
Location 07-Ora-FAS M003-OR (on deck)
Dist - Co - Rte - PM - City
Date of Investigation July 16, 1981

Name BREA CANYON (Brea Boulevard, 1.1 mi. west of Route 57)

CONDITION RATING:

APPRAISAL RATING:

Deck 7 Superstructure 7 Substr. & Pipes 7 Overall 7
Channel & Channel Protection 5 Retaining Walls N

Widenable? Yes ☒ No ☐ Conditional ☐

Action Required by ~~ENGINEER~~ Yes ☐ No ☐

WORK DONE:

The previously recommended work appears to have been done.

CONDITION OF STRUCTURE:

The overall condition of the structure is good.

RECOMMENDED POSTING:

None.

E. L. Neff
E. L. Neff
C 26703

ELN:ed
cc: DWHiggins (2)
Orange County (2)

REVISED

Bridge No. 55C-121

Other No. _____

P.U.C. No. _____

Location 07-Oran-FAS-M003
Dist - Co - Rte - PM - City

Date of Investigation May 2, 1980

Name BREA CANYON (Brea Blvd.-1.1 mi. W of Route 57)

Lat. N33°-56.3' Long. W117°-53.4'

STRUCTURAL DATA AND HISTORY

Year Built unknown By Orange County Contract No. Unknown

Date of Revisions 1929-Widened, 1938 Repaired and Reconstructed

Designed by: B.D. ☐ Orange County Plans Avail. @ 1929) State
1938)

Description: Two RC slab spans on RC pier and RC wing abutments
(5'± AC and dirt cover)

Spans 2 at 13.6' c/c

Length 30.2' Skew 32° Lt Design LL original-unknown

Ratings: Inventory HS 20/Assigned Operating HS 33/Assigned Permit PPPPP/Assigned

DESCRIPTION - ON STRUCTURE

Bridge Width (W) 18'dirt; 28'; 12'dirt(E)

Total Width None Lanes 2 Tracks None

Median None Rail Type None (0000)

Vert. Clearance over deck Unimpaired Appr. Rdwy. Width 28'

Wearing Surface AC (3"±) Deck Seal None

Alignment Tangent between curves

DESCRIPTION - UNDER STRUCTURE

Roadway Section None

Clearances: Vert. _____ Horiz. _____ Lt. _____ Rt. _____

Lanes _____ Tracks _____ Pumpplant: None ☒ See Br. No. _____

Facilities Crossed Brea Canyon

cc:

Bridge No. 55C-121

Date May 2, 1980

DESCRIPTION - HYDRAULICS

Channel Fairly well defined with sand and rock bottom

Navigable: Yes ☐ No ☒ Clearances: Vert. N Horiz. N

MAINTENANCE

Custodian Orange County

Owner Orange County

**ORIGINAL
CONDITION RATING**

| | |
|------------------------------|-----------|
| Deck | <u>7</u> |
| Superstructure | <u>7</u> |
| Substructure & Pipes | <u>7</u> |
| Channel & Channel Protection | <u>5</u> |
| Retaining Walls | <u>N</u> |
| Approach Rdwy. Alignment | <u>9</u> |
| Estimated Remaining Life | <u>40</u> |

**ORIGINAL
APPRAISAL**

| | |
|--------------------------|-----------------|
| Overall | <u>7</u> |
| Deck Geometry | <u>8</u> |
| Underclearances | Vert. <u>N</u> |
| | Horiz. <u>N</u> |
| Safe Load Capacity | <u>9</u> |
| Waterway Adequacy | <u>5</u> |
| Approach Rdwy. Alignment | <u>7</u> |

Widenable? Yes ☒ No ☐ Conditional ☐

Action Required by ^{County:} ~~District~~ Yes ☒ No ☐

AVERAGE DAILY TRAFFIC - Road closed due to flood damage.

BYPASS DETOUR LENGTH - 5 mile

ENCROACHMENTS - Two-10" ϕ pipes 10' and 15' east of the structure.

CONDITION OF STRUCTURE - There is erosion at the northwest, northeast, and southeast wingwalls. There is a discontinuity in the face of the south abutment.

LOAD CAPACITY - The ratings shown were assigned based on the known factors, the fact that there is 5' \pm of earth over the structure and the condition of the structure.

RECOMMENDATIONS - Repair the erosion at the northwest, northeast and southeast wingwalls.

Original signed by

FRANK J. WALLISER

FJW:11

cc: DRHiggins
Orange County (2)

DIST 07

ROUTE CO RD

COUNTY 55 C

STRU. NO 0121

POSTMILE .

RATING WIDTH-FT 014.8

STRU TYPE CSC RIGID

VR ORIG CONST 29

NOV. 21, 1979

| RATING | ULT MOM CAP | ULT MOM CAP | POS HS20 | NEG HS20 | POS PURP | NEG PURP | DEAD LOAD | SECONDARY | | | |
|--------|-------------|-------------|------------|----------|----------|----------|-----------|-----------|------|-------|-----|
| FACTOR | PT SPAN | TOP IN COM | ROT IN COM | MOMENT | MOMENT | MOMENT | MOMENT | MOMENT | | | |
| INV | 6.61 | 10 | 2 | 0.0 | 85.7 | 0.9 | -3.0 | 1.3 | -5.0 | -33.0 | 0.0 |
| OPER | 10.98 | 10 | 2 | 0.0 | 85.7 | 0.9 | -3.0 | 1.3 | -5.0 | -33.0 | 0.0 |
| PURP | 6.59 | 10 | 2 | 0.0 | 85.7 | 0.9 | -3.0 | 1.3 | -5.0 | -33.0 | 0.0 |

TIME NUMBER OF AXLES ON THE TRUCK THAT CAUSES THE PURPLE RATING FACTOR IS 13.

FC = 1.00 FY = 30.

THE NUMBER OF AXLES ON THE TRUCK THAT CAUSES THE PURPLE RATING FACTOR IS 13.

IF THE REPORTED ULTIMATE MOMENT CAPACITY IS 0, IT WAS DETERMINED NOT TO BE CRITICAL

BREA CANYON WIDENING - W/S FILL
DESIGNED AS 2 SPAN RIGID FRAME SLAB
LL DISTRIBUTED AS UNIFORMED LOAD (250 LBS/SQ FT)

ppppp

HIGH FILL

ASSIGNED RATING

MM 11/26/79

INV = HS 20.0
OP = HS 33.0
R/F = ppppp

③

| DIST | ROUTE | COUNTY | STRU. NO | POSTMILE | RATING | WIDTH-FT | STRU TYPE | YR ORIG | CONST |
|------|-------|--------|----------|----------|--------|----------|-----------|---------|-------|
| 07 | CO RD | 55 C | 0121 | . | 014.8 | | CSC RIGID | 29 | |

NOV. 21, 1979

INFLUENCE LINE FOR CRITICAL INVENTORY RATING POINT SPAN 2 10TH POINT 10

| MEM NO | LEFT | .1 | .2 | .3 | .4 | .5 | .6 | .7 | .8 | .9 | RIGHT |
|--------|------|--------|--------|--------|--------|--------|--------|--------|--------|--------|-------|
| 1 | 0.0 | 0.038 | 0.081 | 0.126 | 0.166 | 0.195 | 0.209 | 0.202 | 0.169 | 0.103 | 0.0 |
| 2 | 0.0 | -0.152 | -0.342 | -0.543 | -0.728 | -0.871 | -0.944 | -0.920 | -0.773 | -0.475 | 0.0 |

THE CRITICAL OPERATING RATING POINT IS THE SAME AS THE CRITICAL INVENTORY RATING POINT

THE CRITICAL PURPLE RATING POINT IS THE SAME AS THE CRITICAL INVENTORY RATING POINT

- 2 BREA CANYON WIDENING - W/5' FILL
- 3 DESIGNED AS 2 SPAN RIGID FRAME SLAB
- 4 LL DISTRIBUTED AS UNIFORMED LOAD (250 LBS/SQ FT)

DIST 07 ROUTE CO RD COUNTY 55 C STRU. NO 0121 POSTMILE . RATING WIDTH-FT 014.8 STRU TYPE CS YR ORIG CONST 20 NOV. 20, 1979

| | RATING FACTOR | PT | SPAN | ULT MOM CAP TOP IN COM | ULT MOM CAP BOT IN COM | POS HS20 MOMENT | NEG HS20 MOMENT | POS PURP MOMENT | NEG PURP MOMENT | DEAD LOAD MOMENT | SECONDARY MOMENT |
|------|------------------|----|------|---------------------------|---------------------------|--------------------|--------------------|--------------------|--------------------|---------------------|---------------------|
| INV | 25.85 | 5 | 1 | 745.0 | 0.0 | 12.0 | 0.0 | 17.9 | 0.0 | 59.5 | 0.0 |
| OPER | 42.94 | 5 | 1 | 745.0 | 0.0 | 12.0 | 0.0 | 17.9 | 0.0 | 59.5 | 0.0 |
| PURP | 28.63 | 5 | 1 | 745.0 | 0.0 | 12.0 | 0.0 | 17.9 | 0.0 | 59.5 | 0.0 |

THE NUMBER OF AXLES ON THE TRUCK THAT CAUSES THE PURPLE RATING FACTOR IS 13.
FC = 1.00 FY = 33.

IF THE REPORTED ULTIMATE MOMENT CAPACITY IS 0, IT WAS DETERMINED NOT TO BE CRITICAL

- 2 BREA CANYON - ORIG PORTION W/B' FILL
- 3 DESIGNED AS SINGLE SPAN RIGID FRAME SLAB - ADDED
- 4 SUPPORT AT CENTER - ASSUMED SLAB HAVE CRACKED AND
- 5 ACTING AS 2 SIMPLE SPAN - LL AS UNIFORMED LOAD

PPPPP

HIGH FILL

ASSIGNED RATING *HM 11/26/79*
INV = HS 20.0
OP = HS 33.0
R/F = PPPPP

③

DIST 07 ROUTE CO RD COUNTY 55 C STRU. NO 0121 POSTMILE . RATING WIDTH-FT 014.8 STRU TYPE CS YR ORIG CONST 20

NOV. 20, 1979

INFLUENCE LINE FOR CRITICAL INVENTORY RATING POINT SPAN 1 10TH POINT 5

| MEM NO | LEFT | .1 | .2 | .3 | .4 | .5 | .6 | .7 | .8 | .9 | RIGHT |
|--------|------|-------|-------|-------|-------|-------|-------|-------|-------|-------|-------|
| 1 | 0.0 | 0.575 | 1.150 | 1.725 | 2.300 | 2.875 | 2.300 | 1.725 | 1.150 | 0.575 | 0.0 |
| 2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |

THE CRITICAL OPERATING RATING POINT IS THE SAME AS THE CRITICAL INVENTORY RATING POINT

THE CRITICAL PURPLE RATING POINT IS THE SAME AS THE CRITICAL INVENTORY RATING POINT

- 2 BREA CANYON - ORIG PORTION W/S: FILL
- 3 DESIGNED AS SINGLE SPAN RIGID FRAME SLAB - ADDED
- 4 SUPPORT AT CENTER - ASSUMED SLAB HAVE CRACKED AND
- 5 ACTING AS 2 SIMPLE SPAN - LL AS UNIFORMED LOAD

PPPPP

SUPPLEMENTARY BRIDGE REPORT

OFFICE REPORT
~~XXXXXXXXXXXX~~

Oct. 1, 1973

Name **BREA CANYON**

OLD 07-Ora-57
NEW 07-Ora-CoRd

OLD 4.35 Miles N. of Jct. Rte. 72

Dist.-Co.-Rte.

Location **NEW .43 M. N. of Central Ave on Brea Blvd**

Post Mile

As a result of action taken by the California Highway Commission on August 22, 1973, Resolution R 2015, this structure was relinquished to the County of Orange.

RECOMMENDATIONS:

Remove from the bridge list, drop from the records, and assign Bridge No. 55C-121.

J. M. Borik

R F Prodoehl
 By R. F. Prodoehl

JMB:RFP:bc
 cc: Dist. 07

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation Oct. 6, 1970

Name BREA CANYON 07-Ora-57
Dist.-Co.-Rte.
Location 4.35 Miles North of Jct. Rte. 72 Post Mile 26.75

CONDITION OF STRUCTURE:

The structure is in good condition throughout.

RECOMMENDATIONS:

None.

Next Investigation: October 1971

P. E. Nelson
P. E. Nelson

PEN:mb
cc:Dist. 07

Investigated 10/20/71 By BB
Changes Noted NR
EQ Rev: Good Stab

Investigated 9/12/72 By WRB
Changes Noted No Chg

Investigated 4/25/73 By JMB
Changes Noted none

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation August 27, 1965Name BREA CANYON

VII-Ora-57

Location 4.35 Miles North of Jct. with Rte. 72Dist.-Co. Rt.
Post Mile 26.75

WORK DONE:

The north bound traffic lane over the bridge has been covered with approximately $\frac{1}{2}$ " of PMS.

CONDITION OF STRUCTURE:

The channel on the east side of the bridge is heavily overgrown with bushes and saplings.

Water has ponded under the east half of structure in the south bay.

Otherwise, the structure is in good condition.

CONDITION OF PAINT:

The screw jacks at the center supplementary bent are completely covered with rust.

RECOMMENDATIONS:

- (1) Remove the bushes and saplings at the east entrance as necessary to keep them from obstructing the flow of water.
- (2) Grade channel to prevent water from ponding under the structure.
- (3) Wire brush screw jacks to remove all rust, then apply two coats of red lead paint and one coat of aluminum.

Estimated Cost: \$250.00

Next Investigation: October, 1966

DONE 11-3-66
W.O. 532 (611)
COST \$59.04
Items #1 & 3

D. B. Jennings
by: Tom Brown
Tom Brown

TB:mb
cc: Dist. VII
Hdq. Maint.

(over)

Investigated 10/4/66 By FJS

Changes Noted Prev rec. work
partly done. Rec'd item 2
prev. rec.

Investigated 9-7-67 By PAB

Changes Noted Rec'd item 2
of report dated 8-27-65.

Investigated 10-24-68 By ARR

Changes Noted Walt Craig and
Power pole @ SW. Winged.
N.R.

Investigated 10-16-69 By WWJ

Changes Noted PT&T Lines along
east side of roadway. N.E.

1. The first item on the list is a power pole located at the SW. Winged. (1)

2. The second item on the list is a power pole located at the SW. Winged. (1)

3. The third item on the list is a power pole located at the SW. Winged. (1)

4. The fourth item on the list is a power pole located at the SW. Winged. (1)

5. The fifth item on the list is a power pole located at the SW. Winged. (1)

6. The sixth item on the list is a power pole located at the SW. Winged. (1)

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation August 8, 1960

Name BREA CANYON

VII-Ora-⁵⁷~~19~~A

Location ^{4.35}~~4.4~~ Miles Northeast of Jct. with Rte. 72 Sta. 15+48⁺
Dist.-Co.-Rt.-Sec.

Refer to the original report dated April 22, 1938, and to subsequent supplementary reports.

PM 26.75 A

CONDITION OF STRUCTURE:

The structure appears to be in good condition throughout.

In connection with the resurfacing of the roadway through this section, a lift of 3" of P.M.S. material has been placed on the roadway over the bridge.

RECOMMENDATIONS:

None

Next Investigation: August 1961

Wm. M. Crawford
Wm. M. Crawford

WMC:cm
cc:Dist. VII
Hdq. Maint.

Investigated 8/21/61 By ARR

Changes Noted None

Investigated 8/17/62 By ARR

Changes Noted none

Investigated 8/8/63 By BWC

Changes Noted none

Investigated 10/7/64 By MCH

Changes Noted none

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation December 22, 1955Name BREA CANYON

VII-0ra-19-A

Location 4.4 Miles Northeast of Junction with Route 2. Sta. 15+48⁺ Dist.-Co.-Rt.-Sec.

Refer to original report dated April 1938 and to subsequent supplementary reports.

WORK DONE:

The work recommended in the previous report has not been done, but in view of the condition of the channel as described below, the previous recommendations should be rescinded.

CONDITION OF STRUCTURE:

Except as noted in this report, the structure appears to be in good condition throughout and about the same as when last inspected.

The channel is heavily overgrown with high tules and light saplings both on and off of the right of way, so that the clearing of the right of way only would serve no useful purpose.

In connection with the resurfacing of the roadway through this section, a lift of from 1 1/2" to 2 1/2" of asphaltic material has been placed on the deck.

RECOMMENDATIONS:

None.

Next Inspection: December 1956.

W E Bastues

W. E. Bastues

WEB:mh
cc: Dist VII
Maint. Dept.

Investigated 12-18-56 by ARRNext Investigation 12-57Changes Noted NoneInvestigated 8-21-59 By WHH

Changes Noted Large amount of trees & brush
noted up & downstream from structure.
No Recommendation.

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation December 6, 1954Name BREA CANYON

VII-0ra-19-A

Location 4.4 Miles Northeast of Jct. with Rte. 2 Sta. 15+48⁺ Dist.-Co.-Rt.-Sec.

Refer to original report dated April 1938, and to subsequent supplementary reports.

CONDITION OF STRUCTURE:

Upstream from the structure the channel is heavily covered with tule and saplings.

The structure is apparently in good condition and about the same as when last inspected.

RECOMMENDATIONS:

1. Remove the tule and saplings which are growing upstream from the structure and within the right of way.

Estimated Cost: \$75.00

Next Inspection: December 1955.

WEB:mh
cc: Dist VII
Maint. Dept.

W. E. Bastues
W. E. Bastues

BRIDGE No. 55-124

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation January 17, 1951

Name BREA CANYON

VII-Ora-19-A

Dist.-Co.-Rt.-Sec.

Location 4.4 miles north of Junction with Rte.2. Sta. 15+48

Refer to original report dated April, 1938, and to subsequent supplementary reports.

CONDITION OF STRUCTURE:

There is a considerable accumulation of weed growth within the right of way at the upstream face of the structure.

The structure is otherwise in good condition.

RECOMMENDATIONS:

Remove as much of the above described weed growth at the upstream face and within the right of way ~~as may be~~ practicable.

Next investigation: January, 1952.


H. K. MAUZY

EKM:jc

cc: Dist. VII
Maint. Dept.

Investigated 1-17-52 By MWG

Next Investigation 1-53

Changes Noted Work Previously Recommended Properly Done

Investigated 12-17-52 By JPA

Next Investigation 12-53

Changes Noted NONE

over

Investigated 12/14/53 by TMF

Next Investigation 12-54

Changes Noted None

Date of Investigation _____

VI-11-12-1

Name BRAD CANNON

Location 4.1 miles north of Junction with E. 1. S. Sec. 13-18

Refer to original report dated April, 1953, and to subsequent supplementary reports.

COMMITTEE OF REVIEW:

There is a considerable accumulation of rock growth within the right of way at the upstream face of the structure.

The structure is otherwise in good condition.

RECOMMENDATIONS:

Remove as much of the above described rock growth at the upstream face and within the right of way as may be practicable.

Next Investigation: January, 1954.

W. H. HARRY

RM. 10

Investigated 1-17-54 by W.H.G.

Next Investigation 1-23

Changes Noted removed bridge deck

cc: Dist. VII
Mainst. Dept.

Investigated _____ by _____

Next Investigation _____

Changes Noted _____

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation August 17, 1948

Name BREA CANYON

VII-Ora-19-A

Dist.-Co.-Rt.-Sec.

Location 4.4 Miles NE of Jct. with Rte. 2

Sta. 15+48

Refer to original report dated April 1938, and to subsequent supplementary reports.

CONDITION OF CHANNEL:

The channel is well defined.

WIDENING:

Widening is feasible on either side.

DETOUR:

A detour is feasible on the east side at an estimated cost of \$3,500.

SALVABLE MATERIALS:

None.

CONDITION OF STRUCTURE:

The structure is in good condition.

RECOMMENDATIONS:

None.

Next Investigation: August 1949.

ORIGINAL SIGNED BY
 M. W. GEWERTZ

M. W. GEWERTZ

MWG:lh

cc: Dist. VII
 Maint. Dept.

Investigated 11-3-49 By WOL

Next Investigation 11-50

Changes Noted None

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation June 29, 1944

Name BREA CANYON

VII-Ora-19-A

Location 4.4 Miles N.E. of Junction with Route 2.

Dist.-Co.-Rt.-Sec.

Sta. 15+48+

Refer to original report dated April, 1938, and to subsequent supplementary reports.

WORK DONE:

The work recommended in the previous report has been properly done.

CONDITION OF STRUCTURE:

Except as noted above, the condition of the structure is about the same as when last inspected.

RECOMMENDATIONS:

None.

Next Investigation: June, 1945.

RAW:t

cc: District VII (2)
Maintenance Dept.
R. A. WAGNER

Investigated 4/23/45 By RES

Next Investigation 4-46

Changes Noted None

Investigated 5-16-46 By RAW

Next Investigation 4-47

Changes Noted None

Investigated 6-19-47 By AJS

Next Investigation 6-48

Changes Noted None



SUPPLEMENTARY BRIDGE REPORT

Date of Investigation June 3, 1943

Name BREA CANYON

VII-Ora-19-A

Dist.-Co.-Rt.-Sec.

Location 4.4 miles N.E. of Jct. with Rte. 2.

Sta. 15+48 +

Refer to original report dated April 1938 and to subsequent supplementary reports.

CONDITION OF STRUCTURE:-

Some of the steel screw jacks of the supplementary bent are loose.

The structure is in good condition and is otherwise about the same as when last inspected.

RECOMMENDATIONS:-

Tighten the steel screw jacks at the center supplementary bent as required to make them uniformly snug.

Finance: General Maintenance

Done 4-24-44 @ #28

57-H-1.

Next Investigation: June 1944

R.A. Wagner

CC: District VII (2)
Maintenance Dept.

SUPPLEMENTARY BRIDGE REPORT

Date of Investigation Oct. 17, 1938.Name BREA CANYON

VII-Ora-19-A

Dist.-Co.-Rt.-Sec.

Location 4.3 miles N.E. of junction with route 2.

Refer to original report dated April 22, 1938.


REMARKS:-

When excavating for the footings it was found that the material upon which it is proposed to support the bridge consists of fairly fine sand mixed with some rotary mud. The latter material apparently was deposited in the channel from nearby oil well workings. The material is inundated under normal conditions and it is necessary to pump water from the excavations in order to carry on the work.

When the material is inundated and is agitated due to excavation operations it is of the nature of quicksand but it is considered that it will safely support the structure when confined and if a small amount of stabilization work is done and if the spread of the footings is increased. The structure being widened rests on similar material and has spread footings which are at less depth than those which it is proposed to place in the widened portion.

CHANGES:-

1. Due to the nature of the foundation material the following changes in the pier and abutment footings will be made:



2. In this foundation material it is considered advisable to decrease the toe pressure on the wingwall footings hence the toes of the wingwall footings will be extended 1 ft. and adequately reinforced.

3. Instead of widening the structure to 37' to right of centerline the structure proper will be constructed up to the R/W line 30' to right of centerline. In order to catch the toe of the fill the height of the side wall will be increased from 16.5" to 3'-0" and it will be adequately reinforced.

CC: District VII (2)
Maintenance Dept.
Mr. Wagner

APR 14 1939

SEE SUPPLEMENTARY REPORT OF _____ FOLLOWING.

556-12)
BRIDGE No. ~~55-104~~
SHEET 2
DATE 10/17/38

FINANCING:-

It is believed that the additional cost of the footings will be offset all or in part by the decreased cost due to decreasing the width of the proposed structure and that the work can be completed within the present allotments.

If the final cost of the work exceeds the allotment it will probably be best to finance the difference from the unexpended balance of Bridge Betterments- Secondaries south-89-90 biennium.

Final Report filed in
Maintenance Dept

FRED BARNES

By

R. A. Wegner

SEE SUPPLEMENTARY REPORT OF APR 14 1939 FOLLOWING.

STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC WORKS
DIVISION OF HIGHWAYS

DAY LABOR WORK ORDER NO.

67XX19

July 25, 1938

MR.

S. V. Cortelyou

DISTRICT ENGINEER

Los Angeles, California.

YOU ARE HEREBY AUTHORIZED TO HAVE THE WORK DESCRIBED BELOW DONE BY DAY LABOR AND THE FOLLOWING SUM IS HEREBY ALLOTTED TO BE EXPENDED FOR THE PURPOSE HEREIN SPECIFIED:


LOCATION AND DESCRIPTION OF WORK

Road VII-02-19-A
At Green Canyon Bridge No. 55-134

Extend and repair bridge..
(per detail within)

Requested for day labor because of the small amount of work involved.

All work to be done in accordance with the Standard Specifications dated January, 1935.



| | | |
|--|----|----------|
| THIS AUTHORIZATION | \$ | |
| PREVIOUS AUTHORIZATIONS | \$ | 1,500.00 |
| TOTAL AUTHORIZATIONS TO DATE | \$ | 1,500.00 |

PAYABLE FROM STATE HIGHWAY FUND

| | | |
|-------------------------------------|----|----------|
| BALANCE AVAILABLE | \$ | |
| AMOUNT OF THIS WORK ORDER | \$ | 1,500.00 |
| BALANCE | \$ | |

FORM 102. EST. 3806. 51771 11-27 3M
STATE PRINTING OFFICE

G. H. PERCELL
State Highway Engineer

ORIGINAL SIGNED BY G. T. MCCOY

By Assistant State Highway Engineer STATE HIGHWAY ENGINEER

ALLOTMENT APPROVED:

EARL LEE KELLY
Director of Public Works

By Chief of Section PUBLIC WORKS
ADMINISTRATIVE ASSISTANT

DATE

JUL 30 1938

FOR

32132
1500
30632

APPROVAL RECOMMENDED

7/28/38

WATERMAN
Construction Engineer

BRIDGE REPORT

Date of Investigation April 22, 1938

General Description

Name BREA CANYON 57
VII-Ora-16-A
Dist.-Co.-Rt.-Sec.
 Location 4.35 miles N.E. of Jct. with Rte. 2.72 Sta. 15+48+
PM 26.75 A
 Description RC slab span with RC wing abutments and under 5'+ earth fill.
 Approximate skew 32°15' Lt.
 Spans 2-136' d/c.
1-@ 27.2' clr. (23' normal clr.).
 Total length 30.2'
 Roadway width 40' between shoulder berms. Sidewalks None.
 Alignment Good. On short tang. btw. two curves. Final for some time.
 Width Good.
 Standard of design Orange County Standards.
 Waterway Sufficient. Sandy channel. Velocity fairly high.
Clear height practically uniform at 8.4'dwnstr. and 6.8' upstr.
 Vertical clearance --- under --- (See diagram)

History

Widened 1929
 Date built Old. By Orange County. Contract No. ----
 Designed by Orange County.

Plans Tracing of widened portion built in 1929 from sheet 16 of 21 sheets, in Bridge Department Files. Drawing Number M840-2.

REMARKS

NO ENCLOSURES

cc: District VII. (2).
 Maintenance Dept.
 Mr. Wagner.

OCT 17, 1938

APR 14 1939

SEE SUPPLEMENTARY REPORT OF FOLLOWING.

PRESENT CONDITION OF STRUCTURE(Flood damage of Mar. 1938):-

The flood of Mar. 1938 caused undermining of the footing of the original (east) portion of the structure at the upstream end causing the upstream side of the original portion to settle about 2'±. This settlement caused the original east portion to pull out of the dowels and away from the 1929 widened portion for distances of about 2" at the south end and about 12" at the north end.

The north abutment of the original portion is badly shattered and part of the lower portion was displaced about 8" towards the channel during settlement.

The south abutment of the original portion has two vertical cracks as wide as 4" at the top.

There are several cracks on the bottom of the original slab due to settlement. These are both approximately parallel to and across the main reinforcing steel.

There are a few hair cracks in the bottom of the slab of the 1929 widened portion. This portion of the bridge is otherwise intact.

STRESS ANALYSIS:-

A complete stress analysis has not been made but the structure is unsafe for the loads caused by the roadway fill and traffic.

SUMMARY:-

The structure will be safe for full legal loads upon completion of the recommended repairs and strengthening.

The remaining economic service life, structurally, is about 40 years for the 1929 widened portion.

RECOMMENDATIONS:-

The following work should be done as soon as possible as the work is considered to be urgently needed:

- (1). Replace the failed original portion with a new RC slab structure on a central RC wall pier and RC wing abutments.
- (2). Strengthened the 1929 portion by extending the central RC wall. All work is to done in accordance with the attached print marked Drawing No. DL-840-243

Estimated cost, about---\$4,500.
Finance: Replacements.

Next Inspection: Aug. 1938

Fred Barnes
By: RAW/MEF

55C-121
Bridge No. ~~55-124~~
Brea Cañon
VII-0m-19-A

Revised
SUMMARY OF QUANTITIES
FOR REPAIRS

| | | |
|-------------------------|--------|------|
| Class "A" Concrete | 112 | CY. |
| Reinforcing Steel | 10 580 | Lbs. |
| Structural Steel Bars | 720 | Lbs. |
| Bolts, Nuts and Washers | 110 | Lbs. |

Submitted with Report of APR 12 1938.

W.P.
5-25-38

Bridge No. 55-134
Brea Cañon
VII - Ora - 19-A

SUMMARY OF QUANTITIES
FOR REPAIRS

| | |
|--------------------------|-----------|
| Class "A" Concrete | 100 C.Y. |
| Reinforcing Steel | 9670 Lbs. |
| Structural Steel Bars | 720 Lbs. |
| Bolts, Nuts, and Washers | 110 Lbs. |

2500
530
Submitted with Report of APR 12 1938
50
700
3950
4500

See revised sheet
5/25/38

W.P.
5-5-38

Computed by W.P. Date 5-5-1938
Checked by _____ Date 19

Bridge No. 55-134
Brea Cañon
VII - Ora-19-A

Quantities for Repairs

① of ③

Concrete

Cross Section Area of New Portion

$$\begin{array}{rcl} \text{Slab} & = 1.21 \times 25.5 & = 31 \text{ Ft.}^2 \\ \text{Abut. Walls} & = 1.25 \times 14 \times 2 & = 35 \\ \text{Center Wall} & = 1.00 \times 14 & = 14 \\ \text{Footings} & = 1.00 \times 3.00 \times 3 & = 9 \\ \text{Total} & & = 89 \text{ Ft.}^2 \end{array}$$

Average Length of New Portion

$$\left[25 - \frac{8.58 + 11.33}{2} \right] \text{ CSC } 57^\circ 45' = 17.7 \text{ Ft.}$$

Cross Section Area of Wing Wall

$$\begin{array}{rcl} \text{Wall} & = .83 \times 10 \text{ (Average)} & = 8.3 \text{ Ft.}^2 \\ \text{Footg} & = 1.00 \times 3.00 & = 3.0 \\ \text{Total} & & = 11.3 \text{ Ft.}^2 \end{array}$$

Volumes

$$\begin{array}{rcl} \text{Main Portion} & = 89 \times 17.7 & = 1575 \text{ Ft.}^3 \\ \text{Wings} & = 11.3 \times 12 \times 2 & = 272 \\ \text{New Cent. Wall} & = 14 \times 1 \times 41.6 & = 583 \\ \text{✓ ✓ Ftg} & = 3 \times 1 \times 41.6 & = 125 \\ \text{Struts} & = 1.5 \times 10 \times 11 \times 4 & = 66 \\ \text{New "Curbs"} & = 1.38 \times 1 \times 63 & = 87 \\ \text{Total} & & = 2708 \text{ Ft.}^3 \\ & & = \underline{\underline{100 \text{ C.Y.}}} \end{array}$$

Submitted with Report of APR 12 1938.

see Revised
Sheet
Dated 5/25/38

Calc. by

D.P.

Date

5/5/38

Bridge:

Brea Cation

Sheet

55-134

Sheet

2 of 3

Chkd. by

Date

Item: REINFORCING STEEL

Contract No.

STATE OF CALIFORNIA
DEPARTMENT OF PUBLIC WORKS
DIVISION OF HIGHWAYS

| ITEM | MARK | SIZE | NO. | LENGTH | TOTAL LENGTH—EACH SIZE | |
|------------------------|------|---------------------------|-----|-------------------|---------------------------|------------------------|
| | | | | | $\frac{1}{2}$ " \square | $\frac{3}{8}$ " ϕ |
| <u>New Portion</u> | | | | | | |
| Slab | | $\frac{3}{8}$ " ϕ | 45 | 30' | | 1350 |
| | | $\frac{1}{2}$ " \square | 13 | 17' | 221 | |
| Abutments | | $\frac{3}{8}$ " ϕ | 33 | 15 ⁵ ' | | 512 |
| | | $\frac{1}{2}$ " \square | 26 | 20 ⁵ | 534 | |
| | | ✓ | 32 | 17 | 544 | |
| Center Wall | | ✓ | 18 | 15 ⁵ | 279 | |
| | | ✓ | 20 | 18 | 360 | |
| Footings | | ✓ | 30 | 3 | 90 | |
| Curbs | | ✓ | 4 | 31 | 124 | |
| | | ✓ | 63 | 7 | 441 | |
| Wing Walls | | ✓ | 52 | 15 | 780 | |
| | | ✓ | 48 | 10 | 480 | |
| Footing | | ✓ | 16 | 3 | 48 | |
| <u>New Center Wall</u> | | | | | | |
| Wall | | ✓ | 82 | 15 | 1230 | |
| | | | 55 | 1 | 55 | |
| | | ✓ | 20 | 41 | 820 | |
| Footing | | ✓ | 28 | 3 | 84 | |
| Struts | | $\frac{3}{8}$ " ϕ | 8 | 23 | | 184 |
| | | $\frac{1}{2}$ " \square | 44 | 5 | 220 | |
| TOTAL LENGTHS | | | | | 6310 | 2046 |
| WT. PER FOOT | | | | | .86 | 2.07 |
| TOTAL WT. PER SIZE | | | | | 5430 | 4240 |
| TOTAL WT. FOR SHEET | | | | | 9670* | |

Submitted with Report of

APR 12 1938

See revised sheet

Dated 5/25/38

Submitted with Report of APR 12 1938

See revised sheet
Dated 5/25/38

80749 11 30 5M DUP. EST. 4489 50 SETS TO PAD
CALIFORNIA STATE PRINTING OFFICE

NOTE.—Original to Bridge Department. Carbon copy retained by Resident Engineer.

Computed by W.P. Date 5/5/1938
Checked by _____ Date _____ 19__

Bridge No. 55-134
Brea Canyon
VII - Ora - 19 - A

Quantities for Repairs

③ of ③

Structural Steel Bars

40 Bars $6 \times \frac{7}{8} \times 140''$ = 714 #
say 720 #

Bolts, Nuts, and Washers

40 - $1\frac{1}{4}'' \phi \times 2''$ Bolts, H.H. & N. = 90 #

80 - $1\frac{1}{4}'' \phi$ Cut Washers = 20 #

110 #

Submitted with Report of APR 12 1938

Computed by V.P. 5-25-38
Checked by _____ Date _____ 19__

Bridge No. 55-134
Brea Cañon
VII - Ora - 19-A

Revised Quantities for repairs

① of ②

Concrete

North Wingwall

$$\frac{(13 \times 1.24) + (16.5 \times 1.35)}{2} \times 12 = 231 \text{ Ft}^3$$

$$6 \times 6 \times 1.5 = 54$$

$$\frac{6+3}{2} \times 6 \times 1.5 = 41$$

South Wingwall

$$\frac{(8.5 \times 1.10) + (16.5 \times 1.35)}{2} \times 12 = 190$$

$$5 \times 6 \times 1.5 = 45$$

$$\frac{(5+3)}{2} \times 6 \times 1.5 = 36$$

$$\text{Balance Same as 5/5/38 figures} = 2436$$

$$\underline{3033}$$

$$= \underline{112 \text{ C.Y.}}$$

Submitted with Report of APR 12 1938

1002

Item: REINFORCING STEEL Contract No

ClibPDF - www.fastio.com

Computed by W.P. Date 4-30-38
Checked by _____ Date 19


Bridge No. 55-134
Brea Cañon
VII - Ora - 19-A

REPAIRS and STRENGTHENING

① of ③

Portion Built in 1929

Slab Reaction on 14' Span



Submitted with Report of APR 12 1938

Dead Load

$$\begin{array}{lcl} \text{Fill} & = 120 \times 5 \times 13 & = 7800 \text{ \#/Ft.} \\ \text{Slab} & = 1.58 \times 13 \times 150 & = 3080 \\ \text{Total} & & = 10880 \text{ \#/Ft.} \end{array}$$

Reaction on 13' length of Center Wall

$$\begin{array}{lcl} \text{Dead Load} & = 10880 \times 14 & = 152000 \text{ \#} \\ \text{Live Load} & = 2\frac{1}{2} \times 12700 & = 32000 \\ \text{Total} & & = 184000 \text{ \#} \end{array}$$

Load per foot of Center Wall

$$\text{Ld./Ft.} = \frac{184000}{13} = 14200 \text{ \#/Ft.}$$

Computed by W.P. Date Feb 23 38
Checked by Date

Bridge No. 55-134
Brea Cañon
VII - Ora - 19-A

REPAIRS and STRENGTHENING

② of ③

Portion Built in 1929

Design of Center Wall

With 12" Wall, Conc. stress

$$= \frac{14200}{144}$$

$$= 99 \text{ #/in}^2$$

12" Wall with Light Steel Amply Safe

New Portion

$$\text{Total Load per square foot} = \frac{14200}{14} = 1020 \text{ #}$$

Design for 1 Ft. Wide Strip of Slab

$$\text{Span - Center to center} = 14'$$

$$\text{Moment} = \frac{1020 \times (14)^2}{8} = 25000 \text{ Ft. #}$$

$$f_c = 1000 \text{ #/in}^2; f_s = 18000; n = 10$$

$$k = \frac{1000}{\frac{18000}{10} + 1000} = .357$$

$$j = 1 - \frac{.357}{3} = .881$$

$$\text{Assume } d = 13''$$

$$f_c = \left(\frac{25000 \times 12}{13 \times .881 \times 13 \times .357 \times 12} \right) \times 2 = 940 \text{ #/in}^2$$

$$A_s = \frac{25000 \times 12}{13 \times .881 \times 18000} = 1.46 \text{ in}^2$$

Use 14½" Slab, 13" To Steel, 7/8" □ Bars @ 4½"

Submitted with Report of APR 12 1938

Computed by W.P. Date 5-4-38
 Checked by _____ Date _____ 19__

Bridge No. 55-134
 Brea Cañon
 VII - Ora - 19-A

REPAIRS and STRENGTHENING

③ of ③

New Portion

Center Wall Same as for 1924 Portion

Abutment

Subjected to same loads as 1929 portion - hence use same design.

Wing Walls


Use Same as 1929 Portion.

SEE Revised sheet dated 5/24/38

Abutments - 1' Wide Strip

$$R_A = (110 \times 7.5) + \frac{300 \times 7.5 \times 5}{15} = 1575 \text{ \#}$$

Submitted with Report of APR 12 1938



$$M_x = 1575x - 55x^2 - 3.33x^3$$

$$\frac{dM}{dx} = 1575 - 110x - 10x^2 = 0$$

$$x^2 + 11x - 157.5 = 0$$

$$x = 8.2 \text{ for Max Moment}$$

$$\begin{aligned} \text{Max Mom} &= (1575)(8.2) - (55)(8.2)^2 - (3.33)(8.2)^3 \\ &= 7400 \text{ Ft\#} \end{aligned}$$


$$A_s = \frac{7400 \times 12}{13.2 \times 88 \times 18000} = .416 \text{ in}^2$$

$$\frac{7}{8} \text{ \" } \Phi \text{ Bars @ 12\" OK} = .60 \text{ in}^2$$

Computed by W.P. Date 5-24-38
Checked by W.P. Date 19

Bridge No. 55-134
Brea Cañon
VII - Ora - 19 - A

REVISED WINGWALL DESIGN



580-121
 BRIDGE No. ~~55-134~~
 Sheet ~~---~~

Name BREA CANYON Location VII-Ora-19-A
 Dist.-Co.-Rt.-Sec. ---

Summary of Construction, Maintenance and Alteration Work

| CONT. OR W. O. No. | DATE | DESCRIPTION | W. O. AMOUNT | FINAL COST |
|-----------------------|---------|--|--------------|------------|
| --- | --- | Estimated cost including widening @ \$4.00 | --- | 6,600 |
| | | Repair flood damage and strengthen. | | |
| 07XX19 | 7-25-38 | Repairs | \$1500 | |
| 87-J-1 | " | (See following) | | |
| | | 2 Old portion rebuilt after 1938 flood & new portion strengthened. | | |
| 57-7H1-B | 1951 | Work as recommended in Bridge Report dated 1-17-51 | | \$8.94 |
| 532(611) | 12-1-66 | Per Rpt. dated 8-27-65 | | \$59.04 |