



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0123
Facility Carried: BREA CANYON BLVD.
Location : 0.8 MI N/O CENTRAL AVENUE
City :
Inspection Date : 11/01/2017
Inspection Type
Routine ☒ FC ☐ Underwater ☐ Special ☐ Other ☐

Bridge Inspection Report

STRUCTURE NAME: BREA CANYON CHANNEL

CONSTRUCTION INFORMATION

Year Built : 1939 Skew (degrees): 60
Year Modified: N/A No. of Joints : 0
Length (m) : 28 No. of Hinges : 0

Structure Description: Simply supported 3-span CIP/RC T-beam (5 each) with RC pier walls and with RC open end diaphragm abutments, all supported upon concrete piles.

Span Configuration : (W) 3 @ 30.00 ft (E)

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN
Inventory Rating: RF= 0.69 Calculation Method: (LRFR) LD & RES FACT RATING
Operating Rating: RF= 0.89 Calculation Method: (LRFR) LD & RES FACT RATING
Permit Rating : PPPPP
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 1.00 ft br, 0.67 ft cu, 30.00 ft, 0.67 ft cu, 1.00 ft br (N).

Total Width: 10.1 m Net Width: 9.1 m No. of Lanes: 2 Speed: 55 mph
Min. Vertical Clearance: Unimpaired Overlay Thickness: 3.0 inches

Rail Code: 0000

Rail Type	Location	Length (ft)	Rail Modifications
Concrete	Right/Left	242	
Baluster			

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal, RC rectangular through the site.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

The inspection was performed by walking on shoulder and under the bridge. There was about 1-2 feet of water in all spans. A full visual inspection is performed for the visible substructure elements. Inspection access to the under of the bridge is from northwest

INSPECTION COMMENTARY

quadrant. A rain boots and binocular is used to perform this inspection.

MISCELLANEOUS

Ten year routine underside photograph was taken during this inspection and is included with this report. (see the attached photo no. 6)

DECK AND ROADWAY

The AC approach roadway is settled 2 inches at eastbound lane.

SUBSTRUCTURE

There were two spalls sized +/- 12 inches X 3 inches X 1 inch with exposed rebars at the northwest wing wall. (see the attached photo no. 3)

SAFE LOAD CAPACITY

Load Rating Summary Sheet dated 8/28/2015 is on file for this structure. While this report does not include a check of that analysis, it does verify that the structural conditions observed during this inspection are consistent with those assumed in that analysis. The current rating is based on LRFR calculation.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition State	St. 1	St. 2	St. 3	St. 4
16			Top Flange-RC	2	283	sq.m	278	2	3	0	0
	1080		Delamination/Spall/Patched Area	2	5		0	2	3	0	0
	510		Deck Wearing Surface-Asphalt	2	255	sq.m	240	15	0	0	0
	3220		Cracking-AC (WS)	2	15		0	15	0	0	0
(16-1080)											
There are ten spalls at the north edge of the deck with exposed rusted rebars mostly at spans 2 and 3, the average size was 8 inches x 6 inches x 1 inch. (see the attached photos no. 7 & 8)											
(16-510-3220)											
AC overlay exhibits Longitudinal crack 30 feet long and 0.5 inches wide at eastbound lane.											
110			Girder/Beam-RC	2	140	m	136	0	4	0	0
	1080		Delamination/Spall/Patched Area	2	4		0	0	4	0	0
(110-1080)											
There was four spalls 16 inches X 10 inches X 1 inch with exposed rebars at the bottom of both exterior girders at spans 1 and 3 and at span 2 north exterior girder. (see the attached photos no. 4 & 5)											
210			Pier Wall-RC	2	40	m	38	2	0	0	0
	1130		Cracking (RC and Other)	2	2		0	2	0	0	0

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each Condition State	St. 1	St. 2	St. 3	St. 4
----------	--------------	---------------------	-----	-----------	-------	-----------------------------	-------	-------	-------	-------

(210)

There were no significant defects noted.

(210-1130)

Pierwalls 2 has three vertical cracks, up to 0.04 inches wide.

Pierwalls 3 has three vertical cracks, up to 0.04 inches wide.

215		Abutment-RC	2	52	m	52	0	0	0
-----	--	-------------	---	----	---	----	---	---	---

(215)

There were no significant defects noted.

227		Pile-RC	2	1	ea.	1	0	0	0
-----	--	---------	---	---	-----	---	---	---	---

(227)

The pile element is included to indicate the presence of piles on this structure. The piles were not exposed for visual inspection. No indication of pile distress was noted in any substructure element.

331		Railing-RC	2	56	m	36	10	10	0
-----	--	------------	---	----	---	----	----	----	---

1080		Delamination/Spall/Patched Area	2	20		0	10	10	0
------	--	---------------------------------	---	----	--	---	----	----	---

(331-1080)

The concrete balusters at both rails have been cracked or spalled +/- 15 inches X 3 inches X 1 inch in many locations.

WORK RECOMMENDATIONS

RecDate: 05/06/2010

Action : Sub-Patch spalls

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Repair the three spalls +/- 12 inches X 3 inches X 1 inch with exposed rebars at the northwest wing wall.

RecDate: 05/06/2010

Action : Railing-Repair

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Repair the spalls +/- 15 inches X 3 inches X 1 inch in both concrete baluster railings. Revised by A. Shenouda 5/9/2018

RecDate: 05/30/2007

Action : Super-Patch spalls

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Repair and patch the four spalls 16 inches X 10 inches X 1 inch with exposed rebars at the bottom of both exterior girders at spans 1 and 3 and at span 2 north exterior girder.

Team Leader : Ashraf Shenouda
Report Author : Ashraf Shenouda
Inspected By : A. Shenouda/KD. Henderson


Ashraf Shenouda (Registered Civil Engineer) (Date) 5/11/18



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0123
 (5) INVENTORY ROUTE (ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- BREA CANYON CHANNEL
 (7) FACILITY CARRIED- BREA CANYON BLVD.
 (9) LOCATION- 0.8 MI N/O CENTRAL AVENUE
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 56 MIN 27.32 SEC
 (17) LONGITUDE 117 DEG 53 MIN 15.24 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE
 TYPE- STRINGER/MULTI-BEAM OR GDR CODE 102
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 3
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- BITUMINOUS CODE 6
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1939
 (106) YEAR RECONSTRUCTED 0000
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 19000
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 2 %
 (19) BYPASS, DETOUR LENGTH 2 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 9.1 M
 (49) STRUCTURE LENGTH 28.0 M
 (50) CURB OR SIDEWALK: LEFT 0.2 M RIGHT 0.2 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 9.1 M
 (52) DECK WIDTH OUT TO OUT 10.1 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 8.2 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 60 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 9.1 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 63.9

STATUS

HEALTH INDEX 98.1

PAINT CONDITION INDEX = N/A

***** CLASSIFICATION *****

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- MINOR ARTERIAL URBAN 16
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION *****

(58) DECK 7
 (59) SUPERSTRUCTURE 7
 (60) SUBSTRUCTURE 7
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING *****

(31) DESIGN LOAD- UNKNOWN 0
 (63) OPERATING RATING METHOD- (LRFR) LD & RES FA 8
 (64) OPERATING RATING- RF= 0.89
 (65) INVENTORY RATING METHOD- (LRFR) LD & RES FA 8
 (66) INVENTORY RATING- RF= 0.69
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL *****

(67) STRUCTURAL EVALUATION 5
 (68) DECK GEOMETRY 3
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 9
 (72) APPROACH ROADWAY ALIGNMENT 8
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES 8

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- SUP/SUB REHAB CODE 35
 (76) LENGTH OF STRUCTURE IMPROVEMENT 28 M
 (94) BRIDGE IMPROVEMENT COST \$282,000
 (95) ROADWAY IMPROVEMENT COST \$56,400
 (96) TOTAL PROJECT COST \$473,760
 (97) YEAR OF IMPROVEMENT COST ESTIMATE 2017
 (114) FUTURE ADT 41217
 (115) YEAR OF FUTURE ADT 2035

***** INSPECTIONS *****

(90) INSPECTION DATE 11/17 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)

119 - PHOTO-Rail-Damage/Deterioration




Photo No. 2

Spalls at the concrete balusters.

113 - PHOTO-Sub-Damage/Deterioration



Photo No. 3

Nothwest has two spalls with exposed rebar.

107 - PHOTO-Super-Damage/Deteroration



Photo No. 4

Spalls with exposed rebars at the bottom face of the exterior girders.

107 - PHOTO-Super-Damage/Deteroration




Photo No. 5

Spalls with exposed rebars at the bottom face of the exterior girders.



Photo No. 6
Underside View looking South.



Photo No. 7
North deck elevations has 10 spalls with exposed rebars mainly in spans 2 and 3.

BREA CANYON CHANNEL

0.8 MI N/O CENTRAL AVENUE

11/01/2017 [AAAK]

55C0123

102 - PHOTO-Deck-Damage/Deterioration



Photo No. 8

North deck elevations has 10 spalls with exposed rebars mainly in spans 2 and 3.