

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



Jeff



*Making Conservation
a California Way of Life.*

September 3, 2018

RECEIVED**OCT 05 2018****OC PUBLIC WORKS
DIRECTOR'S OFFICE**

Mr. Shane Silsby
Director of Public Works
County of Orange
P O Box 4048
Santa Ana, CA 92702-4048

Dear Mr. Silsby:

In accordance with Title 23 of the Code of Federal Regulations (Federal Highway Act) and the National Bridge Inspection Standards (NBIS), Caltrans Structure Maintenance and Investigations performed an inspection of 2 bridges under your jurisdiction. The type of inspection is indicated on the bridge report transmittal sheet. The bridges have been rated to indicate their deficiencies, structural adequacy, safe load carrying capacity and overall general condition.

Enclosed are copies of the Bridge Inspection Reports for the structures noted on the attached transmittal sheet. These reports contain descriptions of physical changes to the structures since the last inspection, recommendations for work to be done, and additional information not recorded in the previous Bridge Reports.

Your attention is directed to the requirements of Title 23, Part 650 of the Code of Federal Regulations, where newly completed structures or any modification of existing structures shall be entered in the inventory within 90 days. Please notify this office of any newly constructed bridge or culvert within your jurisdiction, more than 20 feet measured along the center of the roadway and carrying public vehicular traffic or over a public roadway, in order that it may be entered in the inventory of bridge structures in compliance with Federal requirements.

Should you have any questions regarding the enclosed Bridge Inspection Reports, please contact Bing Wu @ (213) 897-0874.

Sincerely,

CHING CHAO
Office Chief
Structure Maintenance & Investigations - (Investigations-South)

Enclosures



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0130
Facility Carried: GLASSELL STREET
Location : 0.3 MI S/O ROUTE 91 FWY
City :
Inspection Date : 12/31/2017

Bridge Inspection Report

Inspection Type

Routine	FC	Underwater	Special	Other
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

STRUCTURE NAME: SANTA ANA RIVER CHANNEL

CONSTRUCTION INFORMATION

Year Built : 1963
Year Modified: 2005
Length (m) : 293.5

Skew (degrees): 0
No. of Joints : 4
No. of Hinges : 4

Structure Description: 18 span continuous CIP RC "T" beam (12 each total including widening) supported by RC pier walls and open end RC diaphragm abutments on steel piles, except Pier 10 through Pier 18 of the east half widening which are RC column (4 each) bents on continuous RC footing and steel piles.

Widen 2005: the bridge was widened 2 CIP/RC beam (2 each) at the west and the east ends.

Span Configuration : (S) 41.00 ft, 16 @ 55.00 ft, 41.00 ft (N)

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN

Inventory Rating: RF=0.52 =>16.8 metric tons

Operating Rating: RF=0.86 =>27.9 metric tons

Permit Rating : XXXXX

Posting Load : Type 3: Legal

Calculation Method: FIELD EVAL/ENG JUDGMENT

Calculation Method: FIELD EVAL/ENG JUDGMENT

Type 3S2: Legal

Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (W) 1.25 ft br; 5.00 ft sw; 35.00 ft; 4.00 ft cu. med.; 35.00 ft; 5.00 ft sw; 1.25 ft br (E).

Total Width: 26.1 m Net Width: 21.2 m No. of Lanes: 4 Speed: 45 mph
Min. Vertical Clearance: Unimpaired Overlay Thickness: 0.0 inches
Rail Code: 1000

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural sandy earth trapezoidal with rock slope protection through the site.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

INSPECTION COMMENTARY

This inspection was performed by walking on the sidewalks, raised median and under all spans. A visual inspection is performed for the visible substructure elements. The water in the channel was up to 3.5 feet deep at spans 3 to 8 (no underside inspection) & 1 foot water at span 11 to span 16 that were inspected using arain boots. Inspection access is through a vehicular access at northeast gate.

DECK AND ROADWAY

Southeast corner of the sidewalk settled up to 3/4 inches, with a spall 8 inches X 3 inches X 1 inch at the sidewalk approach at the same location.

SAFE LOAD CAPACITY

A Load Rating Summary sheet is archived on 01/31/2016. As-built drawings are not available for the original bridge. The Load rating Summary Sheet has verified the physical conditions assumed in the above referenced load rating calculation have not changed significantly.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition	State
							St. 1 St. 2 St. 3 St. 4	
16			Top Flange-RC	2	7440	sq.m	6990 450 0 0	
	1080		Delamination/Spall/Patched Area	2	50		0 50 0 0	
	1120		Efflorescence/Rust Staining	2	400		0 400 0 0	
	1130		Cracking (RC and Other)	2	400		400 0 0 0	
	521		Concrete Coat. (Meth/Paint/Seal)	2	6222	sq.m	6222 0 0 0	

(16-1080)

The concrete deck has few sound patched areas +/- 2 feet X 18 inches in several locations, mostly in spans 12, 14 and 16.

(16-1120)

The soffit exhibits: (see the attached photo no. 1)

* span #1: all bays under the traffic lanes (original bridge) has several transverse cracks with heavy white efflorescence;

* span #2: all bays under the traffic lanes (original bridge) has several transverse cracks, up to 6 feet long with light white efflorescence mostly at south end; and

* at spans #8 to #18: few transverse cracks with light white efflorescence; these cracks mirror the deck cracks.

(16-1130)

The bridge deck is treated with methacrylate and all the deck cracks that were in condition state 2 will move to condition state 1.

(16-521)

There were no significant defects noted.

The deck is sealed with methacrylate in around year 2012.

110			Girder/Beam-RC	2	3524	m	3251 270 3 0	
	1080		Delamination/Spall/Patched Area	2	23		0 20 3 0	
	1130		Cracking (RC and Other)	2	250		0 250 0 0	

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each Condition State			
						St. 1	St. 2	St. 3	St. 4

(110-1080)

The concrete girders exhibit:

At span 2: Girder 3, has six sound patched areas +/- 12 inches X 10 inches in different locations.

* at span 9:

- girder 1 exhibits a spall 3 inches X 3 inches X 1 inch at west fascia at 15 feet from PW #10;
- girder 3 exhibits four spalls +/- 12 inches X 5 inches X 2 inch at west fascia; (see the attached photo no. 3)
- girder #9 exhibits two spalls 5 inches X 5 inches X 1 inch at 5 feet north from intermediate diaphragm at both faces; and
- girder #10 exhibits a spall 5 inches X 6 inches X 1 inch at 5 feet north from intermediate diaphragm at west face.

* at span 10: a spall 4 inches X 4 inches X 1 inch at girder #9 at 2 feet from the intermediate diaphragm without any rebar exposed.

* at span 11: girder #10 (from west) has a spall 10 inches X 3 inches X 1 inch with rebar exposed and rusted at 5 feet north of intermediate diaphragm.

* at span 17: most girders from 3 to 10 have up to two sound patched areas +/- 12 inches X 12 inches.

(110-1130)

The concrete girders exhibit: (see the attached photo no. 4)

* in span 2: most original girders (south end) have few shear cracks (2 cracks at each girder) 0.04 inches wide;

* in span 9:

- 4 shear cracks (at each end) at each original girder , up to 0.04 inches wide;

* in span 10: girders 7, 8, 9 and 10 each has eight vertical cracks, up to 0.04 inches wide and 2.5 feet spaced apart mostly at the middle 2/3rd of the span.

* most original girders exhibit few shear cracks up to 0.03 inches wide at both ends.

182	EQ Restrainer Cable-Other	2	40	ea.	35	5	0	0
1000	Corrosion	2	5		0	5	0	0

(182-1000)

Steel cables of the seismic retrofit have a sign of rust of some of them.

205	Column-RC	2	36	each	36	0	0	0
-----	-----------	---	----	------	----	---	---	---

(205)

4 columns at each Bent , at Bents 10 to 18.

There were no significant defects noted.

210	Pier Wall-RC	2	280	m	269	10	1	0
1080	Delamination/Spall/Patched Area	2	1		0	0	1	0
1130	Cracking (RC and Other)	2	10		0	10	0	0

(210-1080)

Pier wall #11 exhibits two spalls 3 inches X 3 inches X 1 inch at north face.

Pier wall #14 exhibits a spall 1.5 feet diameter X 2 inches at 15 feet from west end southerly face.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each State	Condition	State
						St. 1	St. 2	St. 3 St. 4

(210-1130)

Pier walls exhibit:

Pier wall #2 exhibits two vertical cracks, 0.05 inches wide.

Pier wall #3 exhibits a vertical crack, 0.04 inches wide.

Pier wall #10 exhibits a vertical crack, at the west portion 0.04 inches wide.

Pier wall #11 exhibits a vertical crack, 0.04 inches wide.

Pier wall #12 exhibits two vertical cracks, up to 0.05 inches wide at the westerly portion.

Pier wall #14 exhibits two vertical crack, 0.04 inches wide.

Pier wall #15 exhibits a vertical crack, 0.04 inches wide at the westerly portion and one horizontal crack 0.05 inches wide at the east portion of the pier wall.

Pier wall #16 exhibits a vertical crack, 0.05 inches wide.

215	Abutment-RC	2	36	m	36	0	0	0
-----	-------------	---	----	---	----	---	---	---

(215)

There were no significant defects noted.

225	Pile-Steel	2	1	ea.	1	0	0	0
-----	------------	---	---	-----	---	---	---	---

(225)

The pile element is included to indicate the presence of piles on this structure. The piles were not exposed for visual inspection. No indication of pile distress was noted in any substructure element.

256	Slope Protection	2	1	ea.	1	0	0	0
-----	------------------	---	---	-----	---	---	---	---

(256)

There were no significant defects noted.

Only at south Abutment.

301	Joint-Pourable Seal	2	88	m	75	13	0	0
2320	Seal Adhesion (Joints)	2	13		0	13	0	0

(301)

The joint seals were replaced around year 2012.

(301-2320)

The pourable joint seal at hinge 3 lost adhesion about 17 feet long.

The pourable joint seal at hinge 7 lost adhesion about 6 feet long at westbound lanes.

The pourable joint seal at hinge 16 lost adhesion about 20 feet long at westbound and southbound lanes.

312	Bearing-Enclosed	2	2	each	2	0	0	0
-----	------------------	---	---	------	---	---	---	---

(312)

The enclosed bearing pads are not exposed for visual inspection.

331	Railing-RC	2	591	m	531	60	0	0
1130	Cracking (RC and Other)	2	60		0	60	0	0

(331-1130)

The RC rails have several vertical cracks, up to 0.05 inches wide and 10 feet spaced apart.

WORK RECOMMENDATIONS

WORK RECOMMENDATIONS

RecDate: 12/31/2017	EstCost:	Patch Pier wall #14 that has a spall 1.5
Action : Sub-Patch spalls	StrTarget: 2 YEARS	feet diameter X 2 inches at 15 feet from
Work By: LOCAL AGENCY	DistTarget:	west end southerly face. (see the
Status : PROPOSED	EA:	attached photo no. 2)

RecDate: 12/31/2017	EstCost:	Patch all the spalls at the concrete
Action : Super-Patch spalls	StrTarget: 2 YEARS	girders at span #9 that have several
Work By: LOCAL AGENCY	DistTarget:	spalls +/- 12 inches X 5 inches X 2
Status : PROPOSED	EA:	inches. (see the attached photo no. 3)

Team Leader : Ashraf Shenouda

Report Author : Ashraf Shenouda

Inspected By : A. Shenouda/KD. Henderson

 8/27/18

Ashraf Shenouda (Registered Civil Engineer) (Date)

CC: City of Orange
City of Anaheim



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0130
 (5) INVENTORY ROUTE(ON/UNDER)- ON 150000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- SANTA ANA RIVER CHANNEL
 (7) FACILITY CARRIED- GLASSELL STREET
 (9) LOCATION- 0.3 MI S/O ROUTE 91 FWY
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- PART OF NET 1
 (13) LRS INVENTORY ROUTE & SUBROUTE 000000000000
 (16) LATITUDE 33 DEG 50 MIN 35.94 SEC
 (17) LONGITUDE 117 DEG 51 MIN 09.2 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE CONT
 TYPE- TEE BEAM CODE 204
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 18
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- CONCRETE CODE 1
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1963
 (106) YEAR RECONSTRUCTED 2005
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 04 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 22000
 (30) YEAR OF ADT 2003 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 5 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 16.8 M
 (49) STRUCTURE LENGTH 293.5 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 21.2 M
 (52) DECK WIDTH OUT TO OUT 26.1 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 21.2 M
 (33) BRIDGE MEDIAN- CLOSED NON-MOUNTABLE 3
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 10.6 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 69.0
 STATUS
 HEALTH INDEX 97.8
 PAINT CONDITION INDEX = N/A

***** CLASSIFICATION *****

	CODE
(112) NBIS BRIDGE LENGTH- YES	Y
(104) HIGHWAY SYSTEM- ROUTE ON NHS	1
(26) FUNCTIONAL CLASS- OTHER PRIN ART URBAN	14
(100) DEFENSE HIGHWAY- NOT STRAHNET	0
(101) PARALLEL STRUCTURE- NONE EXISTS	N
(102) DIRECTION OF TRAFFIC- 2 WAY	2
(103) TEMPORARY STRUCTURE-	
(105) FED.LANDS HWY- NOT APPLICABLE	0
(110) DESIGNATED NATIONAL NETWORK - NOT ON NET	0
(20) TOLL- ON FREE ROAD	3
(21) MAINTAIN- CITY OR MUNICIPAL HIGHWAY AGENCY	04
(22) OWNER- CITY OR MUNICIPAL HIGHWAY AGENCY	04
(37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE	5

***** CONDITION *****

	CODE
(58) DECK	7
(59) SUPERSTRUCTURE	7
(60) SUBSTRUCTURE	7
(61) CHANNEL & CHANNEL PROTECTION	8
(62) CULVERTS	N

***** LOAD RATING AND POSTING *****

	CODE
(31) DESIGN LOAD- UNKNOWN	0
(63) OPERATING RATING METHOD- FIELD EVAL/ENG JUD	0
(64) OPERATING RATING-	27.9
(65) INVENTORY RATING METHOD- FIELD EVAL/ENG JUI	0
(66) INVENTORY RATING-	16.8
(70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS	5
(41) STRUCTURE OPEN, POSTED OR CLOSED-	A
DESCRIPTION- OPEN, NO RESTRICTION	

***** APPRAISAL *****

	CODE
(67) STRUCTURAL EVALUATION	4
(68) DECK GEOMETRY	9
(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL	N
(71) WATER ADEQUACY	9
(72) APPROACH ROADWAY ALIGNMENT	8
(36) TRAFFIC SAFETY FEATURES	1000
(113) SCOUR CRITICAL BRIDGES	8

***** PROPOSED IMPROVEMENTS *****

	CODE
(75) TYPE OF WORK-	
(76) LENGTH OF STRUCTURE IMPROVEMENT	M
(94) BRIDGE IMPROVEMENT COST	
(95) ROADWAY IMPROVEMENT COST	
(96) TOTAL PROJECT COST	
(97) YEAR OF IMPROVEMENT COST ESTIMATE	
(114) FUTURE ADT	45792
(115) YEAR OF FUTURE ADT	2035

***** INSPECTIONS *****

(90) INSPECTION DATE 12/17	(91) FREQUENCY 24	MO
(92) CRITICAL FEATURE INSPECTION:	(93) CFI DATE	
A) FRACTURE CRIT DETAIL-	NO	MO A)
B) UNDERWATER INSP-	NO	MO B)
C) OTHER SPECIAL INSP-	NO	MO C)

SANTA ANA RIVER CHANNEL

0.3 MI S/O ROUTE 91 FWY

12/31/2017 [AAAK]

55C0130

102 - PHOTO-Deck-Damage/Deterioration



Photo No. 1

113 - PHOTO-Sub-Damage/Deterioration




Photo No. 2

Spall 1.5 feet diameter X 2 inches deep at pier wall 14.

107 - PHOTO-Super-Damage/Deteroration



Photo No. 3

Spalls 12 in X 5 in. X 2 in.at G#9 at span 9.

107 - PHOTO-Super-Damage/Deteroration




Photo No. 4

Diagonal cracks at the RC girders, up to 0.04 inches wide.