



**DEPARTMENT OF TRANSPORTATION**  
Structure Maintenance & Investigations

Bridge Number : 55C0148  
Facility Carried: WARNER AVENUE  
Location : 0.1 MI W/O HARBOR BLVD  
City :  
Inspection Date : 06/28/2017

**Bridge Inspection Report**

Inspection Type  
Routine FC Underwater Special Other  
☒

**STRUCTURE NAME:** SANTA ANA RIVER CHANNEL (WARNER AVE)

**CONSTRUCTION INFORMATION**

Year Built : 1961 Skew (degrees): 9  
Year Modified: 1969 No. of Joints : 2  
Length (m) : 77.4 No. of Hinges : 2

Structure Description: Continuous six span CIP/RC T-beam (9 each) and widened is PC/PS 3 girders at North; and PC/PS 2 girders South with stay in place steel forms with RC pier walls and RC open end diaphragm abutments, all supported upon concrete piles.

Span Configuration : (W) 34.50 ft, 2 @ 46.00 ft, 46.20 ft, 34.50 ft (E)

**SAFE LOAD CAPACITY AND RATINGS**

Design Live Load: MS-18 OR HS-20  
Inventory Rating: RF=1.00 =>32.4 metric tons Calculation Method: ASSIGNED (LFD)  
Operating Rating: RF=1.67 =>54.1 metric tons Calculation Method: ASSIGNED (LFD)  
Permit Rating : PPPPP  
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

**DESCRIPTION ON STRUCTURE**

Deck X-Section: (S) 1.00 ft br, 5.00 ft sw, 44.00 ft, 8.00 ft cu.med, 40.00 ft, 5.00 ft sw, 1.00 ft br (N).

Total Width: 31.6 m Net Width: 24.5 m No. of Lanes: 6 Speed: 45 mph  
Min. Vertical Clearance: Unimpaired Overlay Thickness: 0.7 inches

Rail Code: 1111

Rail Type	Location	Length (ft)	Rail Modifications
Type 26	Right/Left	525	

**DESCRIPTION UNDER STRUCTURE**

Channel Description: RC trapezoidal.

**NOTICE**

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

**INSPECTION COMMENTARY**

**SCOPE AND ACCESS**

This inspection was performed by walking on the sidewalks, on the abutment slopes and under all spans of the superstructure. The water in the channel was 3 inches through span 3 during the time of inspection. A full inspection is performed for all substructure elements.

**INSPECTION COMMENTARY****REVISIONS**

The slope protection (element 256) is deleted from element table, because the channel lining is continuous at the channel and under the bridge.

NBI #108A was modified from 1 (Concrete) to 2 (Integrated Concrete) because of the bridge deck is protected with polyester concrete.

**DECK AND ROADWAY**

The roadway at the east side roadway of eastbound lanes has a pothole 1.5 feet X 1 foot X 3 inches at the south shoulder. (see the attached photos no. 1 to 3)

**SUBSTRUCTURE**

There is soot at the concrete girders at the west span, using the binocular there is no visible damaged noted.

**SAFE LOAD CAPACITY**

A load Rating Summary sheet is archived on 11/13/2014 with this bridge inspection report. This load rating was assigned in accordance with current SM&I procedures.

<u>ELEMENT INSPECTION RATINGS AND COMMENTARY</u>										
Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition State			
							St. 1	St. 2	St. 3	St. 4
12			Deck-RC	2	688	sq.m	587	101	0	0
	1080		Delamination/Spall/Patched Area	2	1		0	1	0	0
	1130		Cracking (RC and Other)	2	100		0	100	0	0
(12-1080)										
The polyester concrete exhibits two unsound concrete areas 4 feet X 3 inches at eastbound lane 2 (east end).										
(12-1130)										
The concrete deck exhibits several cracks with 5-10 feet long, 1.00 foot spacing and up to 0.05 inches wide at westbound lane 3 and south shoulder. (see the attached photos no. 6 & 7)										
16			Top Flange-RC	2	1757	sq.m	1657	100	0	0
	1120		Efflorescence/Rust Staining	2	100		0	100	0	0
	511		Deck Wearing Surface-Concrete	2	1571	sq.m	1567	4	0	0
		3211	Delam./Spall/Patch-Concrete (WS)	2	2		0	2	0	0
		3221	Cracking-Concrete (WS)	2	2		0	2	0	0
(16)										
There were no significant defects noted.										
(16-1120)										
The soffit of the original portion exhibits transverse cracks with white efflorescence at few bays in all spans.										
(16-511)										

**ELEMENT INSPECTION RATINGS AND COMMENTARY**

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each	Condition	State	
						St. 1	St. 2	St. 3	St. 4
The polyester concrete is placed on top of the original deck only.									
There were no significant defects noted.									
(16-511-3211)									
There are few spalls 12 inches X 3 inches X 0.75 inches at the polyester concrete at hinges 2 and 5 at eastbound lanes.									
(16-511-3221)									
There are few transverse cracks at eastbound lane 3 at east span.									
109		Girder/Beam-PS Conc.	2	387	m	387	0	0	0
(109)									
There were no significant defects noted.									
110		Girder/Beam-RC	2	697	m	687	10	0	0
1130		Cracking (RC and Other)	2	10		0	10	0	0
(110)									
There were no significant defects noted.									
(110-1130)									
The concrete girders at the (original portion) have vertical cracks, next to the the supports.									
182		EQ Restrainer Cable-Other	2	18	ea.	18	0	0	0
(182)									
There were no significant defects noted.									
210		Pier Wall-RC	2	155	m	155	0	0	0
(210)									
There were no significant defects noted.									
215		Abutment-RC	2	64	m	64	0	0	0
(215)									
There were no significant defects noted.									
227		Pile-RC	2	1	ea.	1	0	0	0
(227)									
There were no significant defects noted.									
302		Joint-Compression Seal	2	56	m	56	0	0	0
(302)									
There were no significant defects noted.									
312		Bearing-Enclosed	2	7	each	7	0	0	0
(312)									
There were no significant defects noted.									
331		Railing-RC	2	155	m	152	3	0	0
1130		Cracking (RC and Other)	2	3		0	3	0	0
(331-1130)									
The concrete rails exhibits several vertical cracks, up to 0.05 inches wide.									

**WORK RECOMMENDATIONS**

**WORK RECOMMENDATIONS**

RecDate: 10/24/2014	EstCost:	Repair the hole (18 inches x 8 inches x
Action : Appr. Roadway-Repair	StrTarget: 2 YEARS	12 inches) in the AC westbound departure
Work By: LOCAL AGENCY	DistTarget:	(west) lane #1.
Status : PROPOSED	EA:	

Team Leader : Ashraf Shenouda

Report Author : Ashraf Shenouda

Inspected By : A.Shenouda/KD.Henderson

 12/26/17

Ashraf Shenouda (Registered Civil Engineer) (Date)



**STRUCTURE INVENTORY AND APPRAISAL REPORT**

## \*\*\*\*\* IDENTIFICATION \*\*\*\*\*

(1) STATE NAME- CALIFORNIA 069  
 (8) STRUCTURE NUMBER 55C0148  
 (5) INVENTORY ROUTE(ON/UNDER)- ON 140000000  
 (2) HIGHWAY AGENCY DISTRICT 12  
 (3) COUNTY CODE 059 (4) PLACE CODE 00000  
 (6) FEATURE INTERSECTED- SANTA ANA RIVER CHANNEL  
 (7) FACILITY CARRIED- WARNER AVENUE  
 (9) LOCATION- 0.1 MI W/O HARBOR BLVD  
 (11) MILEPOINT/KILOMETERPOINT 0  
 (12) BASE HIGHWAY NETWORK- PART OF NET 1  
 (13) LRS INVENTORY ROUTE & SUBROUTE 000000000000  
 (16) LATITUDE 33 DEG 42 MIN 51.76 SEC  
 (17) LONGITUDE 117 DEG 55 MIN 17.07 SEC  
 (98) BORDER BRIDGE STATE CODE % SHARE %  
 (99) BORDER BRIDGE STRUCTURE NUMBER

## \*\*\*\*\* STRUCTURE TYPE AND MATERIAL \*\*\*\*\*

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE CONT  
 TYPE- TEE BEAM CODE 204  
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA  
 TYPE- OTHER/NA CODE 000  
 (45) NUMBER OF SPANS IN MAIN UNIT 6  
 (46) NUMBER OF APPROACH SPANS 0  
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1  
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:  
 A) TYPE OF WEARING SURFACE- INTEGRAL CONC. CODE 2  
 B) TYPE OF MEMBRANE- NONE CODE 0  
 C) TYPE OF DECK PROTECTION- NONE CODE 0

## \*\*\*\*\* AGE AND SERVICE \*\*\*\*\*

(27) YEAR BUILT 1961  
 (106) YEAR RECONSTRUCTED 1969  
 (42) TYPE OF SERVICE: ON- HIGHWAY 1  
 UNDER- WATERWAY 5  
 (28) LANES:ON STRUCTURE 06 UNDER STRUCTURE 00  
 (29) AVERAGE DAILY TRAFFIC 25000  
 (30) YEAR OF ADT 2008 (109) TRUCK ADT 1 %  
 (19) BYPASS, DETOUR LENGTH 2 KM

## \*\*\*\*\* GEOMETRIC DATA \*\*\*\*\*

(48) LENGTH OF MAXIMUM SPAN 14.0 M  
 (49) STRUCTURE LENGTH 77.4 M  
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 1.5 M  
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 24.5 M  
 (52) DECK WIDTH OUT TO OUT 31.6 M  
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 25.7 M  
 (33) BRIDGE MEDIAN- CLOSED NON-MOUNTABLE 3  
 (34) SKEW 9 DEG (35) STRUCTURE FLARED NO  
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M  
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 13.4 M  
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M  
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M  
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M  
 (56) MIN LAT UNDERCLEAR LT 0.0 M

## \*\*\*\*\* NAVIGATION DATA \*\*\*\*\*

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N  
 (111) PIER PROTECTION- CODE  
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M  
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M  
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

## \*\*\*\*\* SUFFICIENCY RATING \*\*\*\*\*

SUFFICIENCY RATING = 91.5  
 STATUS  
 HEALTH INDEX 98.4  
 PAINT CONDITION INDEX = N/A

## \*\*\*\*\* CLASSIFICATION \*\*\*\*\* CODE

(112) NBIS BRIDGE LENGTH- YES Y  
 (104) HIGHWAY SYSTEM- ROUTE ON NHS 1  
 (26) FUNCTIONAL CLASS- OTHER PRIN ART URBAN 14  
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0  
 (101) PARALLEL STRUCTURE- NONE EXISTS N  
 (102) DIRECTION OF TRAFFIC- 2 WAY 2  
 (103) TEMPORARY STRUCTURE-  
 (105) FED.LANDS HWY- NOT APPLICABLE 0  
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0  
 (20) TOLL- ON FREE ROAD 3  
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02  
 (22) OWNER- COUNTY HIGHWAY AGENCY 02  
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

## \*\*\*\*\* CONDITION \*\*\*\*\* CODE

(58) DECK 7  
 (59) SUPERSTRUCTURE 7  
 (60) SUBSTRUCTURE 7  
 (61) CHANNEL & CHANNEL PROTECTION 8  
 (62) CULVERTS N

## \*\*\*\*\* LOAD RATING AND POSTING \*\*\*\*\* CODE

(31) DESIGN LOAD- MS-18 OR HS-20 5  
 (63) OPERATING RATING METHOD- ASSIGNED (LFD) A  
 (64) OPERATING RATING- 54.1  
 (65) INVENTORY RATING METHOD- ASSIGNED (LFD) A  
 (66) INVENTORY RATING- 32.4  
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5  
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A  
 DESCRIPTION- OPEN, NO RESTRICTION

## \*\*\*\*\* APPRAISAL \*\*\*\*\* CODE

(67) STRUCTURAL EVALUATION 7  
 (68) DECK GEOMETRY 5  
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N  
 (71) WATER ADEQUACY 8  
 (72) APPROACH ROADWAY ALIGNMENT 7  
 (36) TRAFFIC SAFETY FEATURES 1111  
 (113) SCOUR CRITICAL BRIDGES 8

## \*\*\*\*\* PROPOSED IMPROVEMENTS \*\*\*\*\*

(75) TYPE OF WORK- CODE  
 (76) LENGTH OF STRUCTURE IMPROVEMENT M  
 (94) BRIDGE IMPROVEMENT COST  
 (95) ROADWAY IMPROVEMENT COST  
 (96) TOTAL PROJECT COST  
 (97) YEAR OF IMPROVEMENT COST ESTIMATE  
 (114) FUTURE ADT 58671  
 (115) YEAR OF FUTURE ADT 2036

## \*\*\*\*\* INSPECTIONS \*\*\*\*\*

(90) INSPECTION DATE 06/17 (91) FREQUENCY 48 MO  
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE  
 A) FRACTURE CRIT DETAIL- NO MO A)  
 B) UNDERWATER INSP- NO MO B)  
 C) OTHER SPECIAL INSP- NO MO C)






Photo No. 1

AC roadway at the outh shoulder EB llanes has a pothole 1.5 ft X 1 ft X 3 inches.





Photo No. 2

AC roadway at the outh shoulder EB llanes has a pothole 1.5 ft X 1 ft X 3 inches.





Photo No. 3

AC roadway at the outh shoulder EB lanes has a pothole 1.5 ft X 1 ft X 3 inches.






Photo No. 4  
Polyester spall at joint 5.






Photo No. 5  
Polyester spall at joint 2.





Photo No. 6

Deck transverse cracks.






Photo No. 7

Deck transverse cracks.





Photo No. 8  
Soot is noticed at the westerly span under the RC girders.



Photo No. 9

Transverse cracks with white efflorescence at the soffit, mainly at the original portion.