

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



Making Conservation
a California Way of Life.

*copy to Nandy FY Action
JyE
Scan :- File*

March 23, 2018

Mr. Shane Silsby
Director of Public Works
County of Orange
P O Box 4048
Santa Ana, CA 92702-4048

Dear Mr. Silsby:

In accordance with Title 23 of the Code of Federal Regulations (Federal Highway Act) and the National Bridge Inspection Standards (NBIS), Caltrans Structure Maintenance and Investigations performed an inspection of 3 bridges under your jurisdiction. The type of inspection is indicated on the bridge report transmittal sheet. The bridges have been rated to indicate their deficiencies, structural adequacy, safe load carrying capacity and overall general condition.

Enclosed are copies of the Bridge Inspection Reports for the structures noted on the attached transmittal sheet. These reports contain descriptions of physical changes to the structures since the last inspection, recommendations for work to be done, and additional information not recorded in the previous Bridge Reports.

Your attention is directed to the requirements of Title 23, Part 650 of the Code of Federal Regulations, where newly completed structures or any modification of existing structures shall be entered in the inventory within 90 days. Please notify this office of any newly constructed bridge or culvert within your jurisdiction, more than 20 feet measured along the center of the roadway and carrying public vehicular traffic or over a public roadway, in order that it may be entered in the inventory of bridge structures in compliance with Federal requirements.

Should you have any questions regarding the enclosed Bridge Inspection Reports, please contact Bing Wu @ (213) 897-0874.

Sincerely,

A blue ink signature of Ching Chao, written in a cursive style.

CHING CHAO
Office Chief
Structure Maintenance & Investigations - (Investigations-South)

Enclosures

RECEIVED

APR 23 2018

OC PUBLIC WORKS
DIRECTOR'S OFFICE

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

Bridge Report Transmittal Sheet**Batch 40274****County of Orange**

Bridge #	Bridge Name	Location	Inspection		Outstanding	
			Date	Type	Work	Cost
55C0008	TRABUCO CREEK	1.4 mi n/o Snta Margarita	09/07/2017	Routine	Y	\$
55C0065	LIMESTONE CANYON	4.4 mi se/o JAMBOREE RD.	09/13/2017	Routine	Y	\$
55C0168	HANDY CREEK	0.2 MI E/O ORANGE PK BLVD	09/07/2017	Routine	Y	\$

3 Bridge(s) in this Transmittal

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

WEB SITES:

The National Bridge Inspection Standards (NBIS) Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges, Element Level Inspection, Structure Maintenance and Investigations Manuals, Local Assistance Program Guidelines and other related information are posted on Division of Maintenance, Structure Maintenance and Investigations; Division of Local Assistance, Local Highway Bridge Program (HBP) and FHWA websites.

The websites can be accessed at:

1. "Caltrans Structure Maintenance and Investigations" <http://www.dot.ca.gov/hq/structur/strmaint/>
2. "Caltrans Division of Local Assistance"
<http://www.dot.ca.gov/hq/LocalPrograms/hbrr99/hbrr99a.htm>
3. "FHWA" <http://www.fhwa.dot.gov/BRIDGE/mtguide.pdf>

Inspection Type Definitions**Routine Inspection:**

Routine Inspections consist of both the initial Inventory Inspection (the first inspection of the bridge that places it in the bridge inventory or when there has been a change in the configuration of the structure) and subsequent regularly scheduled inspections. The initial inspection provides all the Structural Inventory & Appraisal (SI&A) data required by federal and state regulations, determines the baseline structural conditions, lists any existing problems, and establishes the load capacity of the structure. Subsequent inspections consist of observations, measurements needed to determine the physical and functional condition of the bridge, to identify any changes from the previously recorded conditions, and verification of its load capacity. These inspections are generally conducted from the deck, ground and/or water level, and from permanent work platforms and walkways, if present. Inspection of underwater portions of the substructure is limited to observations during low-flow periods and/or probing for signs of undermining. Special equipment should be utilized in circumstances where its use provides the only practical access to areas of the structure.

Fracture Critical, Special Feature & Underwater Inspections:

Fracture Critical, Special Feature, and Underwater Inspections are up close, hands-on inspections of one or more members above or below the water level to identify any deficiencies not readily detectable using Routine Inspection procedures. These inspections generally require special equipment such as under-bridge inspection equipment, manlifts, boats, traffic control, and railroad flagging. Personnel with special skills such as divers or structural steel inspectors trained in non-destructive testing techniques may be required.

Other Inspections:

Other Inspections are conducted on damaged structures, structures that have developed specific problems, or structures suspected of developing problems. The scope of these investigations should be sufficient to determine the need for emergency load restrictions or closure of the structure, monitor a changing condition, and to assess the level of effort necessary to effect a repair.



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0168
Facility Carried: AMAPOLA AVENUE
Location : 0.2 MI E/O ORANGE PK BLV
City :
Inspection Date : 09/07/2017

Bridge Inspection Report

Inspection Type

Routine	FC	Underwater	Special	Other
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

STRUCTURE NAME: HANDY CREEK

CONSTRUCTION INFORMATION

Year Built : 1937	Skew (degrees): 0
Year Modified: N/A	No. of Joints : 0
Length (m) : 8.5	No. of Hinges : 0

Structure Description: Simply supported two span timber stringers (19 each) and timber deck with a timber treated timber post (6 each) bent and a treated timber post (6 each) abutments, all supported upon treated timber sills.
All timber treated Douglas Fir.

Span Configuration : (W) 2 @ 13.00 ft (E)

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN	
Inventory Rating: RF=0.54 =>17.5 metric tons	Calculation Method: ALLOWABLE STRESS
Operating Rating: RF=0.77 =>24.9 metric tons	Calculation Method: ALLOWABLE STRESS
Permit Rating : 00000	
Posting Load : Type 3: Legal	Type 3S2: Legal
	Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.30 ft br, 23.30 ft, 0.30 ft br (N)

Total Width: 7.3 m	Net Width: 7.1 m	No. of Lanes: 2	Speed: 25 mph
Min. Vertical Clearance: Unimpaired		Overlay Thickness: 5.0 inches	

Rail Code: 0000

Rail Type	Location	Length (ft)	Rail Modifications
MBBR	Right/Left	56	

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal upstream, RC rectangular with a check dam downstream.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

A complete routine inspection was performed by walking on and around the structure to inspect all visible elements on the existing structures using a binocular from the 3 feet

INSPECTION COMMENTARY

dry area next to the west Abutment. The water in the creek was still and 1.5 feet deep in both spans except the 3 feet next the west Abutment. A full visual inspection is performed for the visible substructure elements. Pedestrian access is from the west side.

DECK AND ROADWAY

There was a (OM-3R) narrow sign road at the southwest corner and a (OM 1-3) road sign at the northeast corner.

There rail post were connected by 2 bolts one on each side.

SAFE LOAD CAPACITY

A load Rating Summary sheet is achieved in BIRIS. The current load rating was based on calculations dated 5/25/2010.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each Condition State	St. 1	St. 2	St. 3	St. 4
31		Deck-Timber	2	60	sq.m	60	0	0	0	0
	510	Deck Wearing Surface-Asphalt	2	60	sq.m	40	10	10	0	0
	3220	Cracking-AC (WS)	2	20		0	10	10	0	0

(31)

There were no significant defects noted.

(31-510-3220)

There was few tranverse and one longitudinal cracks in the AC ovelay, up to 0.75 inches wide and 10 feet wide.

111		Girder/Beam-Timber	2	162	m	162	0	0	0	0
-----	--	--------------------	---	-----	---	-----	---	---	---	---

(111)

There were no significant defects noted.

206		Column-Timber	3	18	each	0	18	0	0	0
	1180	Abrasion (Timber)	3	18		0	18	0	0	0

(206-1180)

There was shrinkage in the columns section due to the weather and water.

216		Abutment-Timber	3	16	m	6	9	1	0	0
	1180	Abrasion (Timber)	3	10		0	9	1	0	0

(216-1180)

At the east abutment north side there is a tree growing in between the timber planks. (see the attached photos no. 2 and 3)

The south blanks of the east Abutment is deteriorated. (see the attached photo no. 4)

235		Pier Cap-Timber	2	21	m	16	5	0	0	0
	1150	Check/Shake (Timber)	2	5		0	5	0	0	0

(235-1150)

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition State			
							St. 1	St. 2	St. 3	St. 4
The bent cap has few longitudinal checks.										
330			Railing-Metal	2	17	m	17	0	0	0
(330)										
There were no significant defects noted.										

WORK RECOMMENDATIONS

RecDate: 05/18/2012

EstCost:

Replace the deteriorated timber plank at

Action : Sub-Patch spalls

StrTarget: 2 YEARS

8 inches from the bottom and remove the

Work By: LOCAL AGENCY

DistTarget:

tree at the north side of the abutment

Status : PROPOSED

EA:

between timber planks.

Team Leader : Ashraf Shenouda

Report Author : Ashraf Shenouda

Inspected By : A.Shenouda/KD.Henderson

 3/16/18
 Ashraf Shenouda (Registered Civil Engineer) (Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0168
 (5) INVENTORY ROUTE (ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- HANDY CREEK
 (7) FACILITY CARRIED- AMAPOLA AVENUE
 (9) LOCATION- 0.2 MI E/O ORANGE PK BLVD
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 48 MIN 08.93 SEC
 (17) LONGITUDE 117 DEG 46 MIN 46.19 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- WOOD OR TIMBER
 TYPE- STRINGER/MULTI-BEAM OR GDR CODE 702
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 2
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- TIMBER CODE 8
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- BITUMINOUS CODE 6
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1937
 (106) YEAR RECONSTRUCTED 0000
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 1000
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 2 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 4.0 M
 (49) STRUCTURE LENGTH 8.5 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 7.1 M
 (52) DECK WIDTH OUT TO OUT 7.3 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 6.7 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 6.7 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

SUFFICIENCY RATING = 48.1
 STATUS
 HEALTH INDEX 94.9
 PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- COLLECTOR URBAN 17
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 7
 (59) SUPERSTRUCTURE 7
 (60) SUBSTRUCTURE 5
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- UNKNOWN 0
 (63) OPERATING RATING METHOD- ALLOWABLE STRESS 2
 (64) OPERATING RATING- 24.9
 (65) INVENTORY RATING METHOD- ALLOWABLE STRESS 2
 (66) INVENTORY RATING- 17.5
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 4
 (68) DECK GEOMETRY 4
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 5
 (72) APPROACH ROADWAY ALIGNMENT 6
 (36) TRAFFIC SAFETY FEATURES 0000
 (113) SCOUR CRITICAL BRIDGES 5

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 2061
 (115) YEAR OF FUTURE ADT 2035

***** INSPECTIONS *****

(90) INSPECTION DATE 09/17 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)

HANDY CREEK

0.2 MI E/O ORANGE PK BLVD

09/07/2017 [AAAK]

55C0168

113 - PHOTO-Sub-Damage/Deterioration



Photo No. 2

Tree is growing at the north end of the east Abutment blanks.

113 - PHOTO-Sub-Damage/Deterioration



Photo No. 3

Tree is growing at the north end of the east Abutment blanks.

HANDY CREEK

0.2 MI E/O ORANGE PK BLVD

09/07/2017 [AAAK]

55C0168

113 - PHOTO-Sub-Damage/Deterioration




Photo No. 4

The East timber Abutment blanks are deteriorated.