

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

July 4, 2018

Mr. Shane Silsby
Director of Public Works
County of Orange
P O Box 4048
Santa Ana, CA 92702-4048

Dear Mr. Silsby:

In accordance with Title 23 of the Code of Federal Regulations (Federal Highway Act) and the National Bridge Inspection Standards (NBIS), Caltrans Structure Maintenance and Investigations performed an inspection of 6 bridges under your jurisdiction. The type of inspection is indicated on the bridge report transmittal sheet. The bridges have been rated to indicate their deficiencies, structural adequacy, safe load carrying capacity and overall general condition.

Enclosed are copies of the Bridge Inspection Reports for the structures noted on the attached transmittal sheet. These reports contain descriptions of physical changes to the structures since the last inspection, recommendations for work to be done, and additional information not recorded in the previous Bridge Reports.

Your attention is directed to the requirements of Title 23, Part 650 of the Code of Federal Regulations, where newly completed structures or any modification of existing structures shall be entered in the inventory within 90 days. Please notify this office of any newly constructed bridge or culvert within your jurisdiction, more than 20 feet measured along the center of the roadway and carrying public vehicular traffic or over a public roadway, in order that it may be entered in the inventory of bridge structures in compliance with Federal requirements.

Should you have any questions regarding the enclosed Bridge Inspection Reports, please contact Bing Wu @ (213) 897-0874.

Sincerely,

A handwritten signature in blue ink, appearing to read "Ching Chao".

CHING CHAO
Office Chief
Structure Maintenance & Investigations - (Investigations-South)

Enclosures

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
 STRUCTURE MAINTENANCE & INVESTIGATIONS
 100 South Main Street, 3rd Floor
 LOS ANGELES, CA 90012
 PHONE (213) 897-2004
 FAX (213) 897-2033



*Making Conservation
 a California Way of Life.*

Bridge Report Transmittal Sheet**Batch 41392****County of Orange**

Bridge #	Bridge Name	Location	Inspection		Outstanding	
			Date	Type	Work	Cost
55C0177	SILVERADO CANYON CREEK	4.4 MI. E/O SANTIAGO ROAD	12/15/2017	Routine	Y	\$
55C0178	SILVERADO CANYON CREEK	4.9 MI. E/O SANTIAGO ROAD	12/15/2017	Routine	Y	\$
55C0179	SILVERADO CANYON CREEK	5.4 MI E/O SANTIAGO CYN	12/15/2017	Routine	Y	\$
55C0181	SILVERADO CANYON CREEK	3.1 MI E/O SANTIAGO ROAD	12/15/2017	Routine	Y	\$
55C0182	SILVERADO CANYON CREEK	3.6 MI. E/O SANTIAGO ROAD	12/15/2017	Routine	Y	\$
55C0183	SILVERADO CANYON CREEK	50' N/O SILVERADO CYN RD.	12/15/2017	Routine	N	\$

6 Bridge(s) in this Transmittal

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

WEB SITES:

The National Bridge Inspection Standards (NBIS) Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges, Element Level Inspection, Structure Maintenance and Investigations Manuals, Local Assistance Program Guidelines and other related information are posted on Division of Maintenance, Structure Maintenance and Investigations; Division of Local Assistance, Local Highway Bridge Program (HBP) and FHWA websites.

The websites can be accessed at:

1. "Caltrans Structure Maintenance and Investigations" <http://www.dot.ca.gov/hq/structur/strmaint/>
2. "Caltrans Division of Local Assistance"
<http://www.dot.ca.gov/hq/LocalPrograms/hbrr99/hbrr99a.htm>
3. "FHWA" <http://www.fhwa.dot.gov/BRIDGE/mtguide.pdf>

Inspection Type Definitions**Routine Inspection:**

Routine Inspections consist of both the initial Inventory Inspection (the first inspection of the bridge that places it in the bridge inventory or when there has been a change in the configuration of the structure) and subsequent regularly scheduled inspections. The initial inspection provides all the Structural Inventory & Appraisal (SI&A) data required by federal and state regulations, determines the baseline structural conditions, lists any existing problems, and establishes the load capacity of the structure. Subsequent inspections consist of observations, measurements needed to determine the physical and functional condition of the bridge, to identify any changes from the previously recorded conditions, and verification of its load capacity. These inspections are generally conducted from the deck, ground and/or water level, and from permanent work platforms and walkways, if present. Inspection of underwater portions of the substructure is limited to observations during low-flow periods and/or probing for signs of undermining. Special equipment should be utilized in circumstances where its use provides the only practical access to areas of the structure.

Fracture Critical, Special Feature & Underwater Inspections:

Fracture Critical, Special Feature, and Underwater Inspections are up close, hands-on inspections of one or more members above or below the water level to identify any deficiencies not readily detectable using Routine Inspection procedures. These inspections generally require special equipment such as under-bridge inspection equipment, manlifts, boats, traffic control, and railroad flagging. Personnel with special skills such as divers or structural steel inspectors trained in non-destructive testing techniques may be required.

Other Inspections:

Other Inspections are conducted on damaged structures, structures that have developed specific problems, or structures suspected of developing problems. The scope of these investigations should be sufficient to determine the need for emergency load restrictions or closure of the structure, monitor a changing condition, and to assess the level of effort necessary to effect a repair.



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0182
Facility Carried: SILVERADO CANYON RD.
Location : 3.6 MI. E/O SANTIAGO ROA
City :
Inspection Date : 12/15/2017

Bridge Inspection Report

Inspection Type
Routine ☒ FC ☐ Underwater ☐ Special ☐ Other ☐

STRUCTURE NAME: SILVERADO CANYON CREEK

CONSTRUCTION INFORMATION

Year Built : 1970 Skew (degrees): 53
Year Modified: N/A No. of Joints : 0
Length (m) : 13.1 No. of Hinges : 0

Structure Description: Single span CIP/RC rigid frame slab, all supported upon spread footings.

Span Configuration : (W) 1 @ 22.00 ft (E) clear, normal

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN
Inventory Rating: RF=0.75 =>24.3 metric tons Calculation Method: FIELD EVAL/ENG JUDGMENT
Operating Rating: RF=1.25 =>40.5 metric tons Calculation Method: FIELD EVAL/ENG JUDGMENT
Permit Rating : PPPPP
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 1.00 ft min pcc deck, 1.00 ft br, 20.00 ft, 1.00 ft br, 1.00 ft min deck (N)

Total Width: 6.7 m Net Width: 6.1 m No. of Lanes: 2 Speed: 25 mph
Min. Vertical Clearance: Unimpaired Overlay Thickness: 3.0 inches

Rail Code: 1000

Rail Type	Location	Length (ft)	Rail Modifications
Miscellaneous	Right/Left	124	

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with a cobbled bottom.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

This inspection was performed by walking on the bridge shoulders and deck, and under the span. A full visual inspection is performed for the visible substructure elements. The water in the channel was 8 inches deep at 5 feet wide of the middle of the channel at the time of the inspection. Inspection access is from the east side and southwest quadrants.

INSPECTION COMMENTARY

The bridge deck was inspected on 12/15/2017 and the underside elements were inspected on 2/8/2018.

SUBSTRUCTURE

The west abutment exhibits a void 18 inches 15 inches X 10 inches behind the abutment at south end at 2 feet above the ground level.

SAFE LOAD CAPACITY

A Load Rating Summary Sheet dated 04/30/2018 is on file for this structure. As-built plans are not available for this bridge. The load rating was assigned in accordance with Section 5.10 of the SM&I Inspection Procedure Manual and Article 6.1.4 of the AASHTO Manual for Bridge Evaluation (2018, Third Edition).

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition St. 1	St. 2	St. 3	State St. 4
38			Slab-RC	2	302	sq.m	282	15	5	0
	1120		Efflorescence/Rust Staining	2	5		0	5	0	0
	1130		Cracking (RC and Other)	2	15		0	10	5	0
	510		Deck Wearing Surface-Asphalt	2	80	sq.m	79	1	0	0
		3210	Delam./Pothole-AC (WS)	2	1		0	1	0	0

(38-1120)

The soffit exhibits two full length longitudinal cracks, 0.05 inches wide with light brown efflorescence; and a crack 8 feet long with white efflorescence. (see the attached photo no. 2)

(38-1130)

The bared concrete deck portion exhibits few longitudinal cracks at the north and south sides, 10 feet long and 0.05 inches wide.

(38-510-3210)

AC overlay exhibits two potholes +/- 2 feet X 1 foot X 1.5 inches at the bridge centerline.

215			Abutment-RC	3	46	m	43	3	0	0
	1130		Cracking (RC and Other)	3	3		0	3	0	0

(215-1130)

There are five vertical cracks, up to 0.04 inches wide in the east abutment wall.

The west abutment exhibits four vertical cracks, up to 0.05 inches wide.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each Condition State			
						St. 1	St. 2	St. 3	St. 4
333		Railing-Other	2	38	m	33	4	0	1
	1020	Connection	2	3		0	2	0	1
	1220	Deterioration (Other)	2	2		0	2	0	0

(333-1020)

The north rail exhibits:

- * timber post #4 (counting from west) is missing; (see the attached photo no. 1)
- * post #8 is missing a nut; and
- * post #10 is missing bolt and nut.

(333-1220)

Few timber posts are lightly decayed.

WORK RECOMMENDATIONS

RecDate: 12/20/2015

Action : Sub-Fix Scour Crit.

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Fill the west abutment's void 18" X 15" X 10" behind the abutment at south end at 2 ft above the ground level.

RecDate: 12/14/2013

Action : Railing-Repair

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Replace the missing timber post #4 (counting from west); Post #8 is missing a nut; and post #10 is missing bolt and nut at the north rail.

Team Leader : Ashraf Shenouda

Report Author : Ashraf Shenouda

Inspected By : A.Shenouda/KD.Henderson



Ashraf Shenouda (Registered Civil Engineer) (Date)

6/27/18



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0182
 (5) INVENTORY ROUTE (ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- SILVERADO CANYON CREEK
 (7) FACILITY CARRIED- SILVERADO CANYON RD.
 (9) LOCATION- 3.6 MI. E/O SANTIAGO ROAD
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 44 MIN 48.23 SEC
 (17) LONGITUDE 117 DEG 37 MIN 08.39 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE
 TYPE- SLAB CODE 101
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 1
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- BITUMINOUS CODE 6
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1970
 (106) YEAR RECONSTRUCTED 0000
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 2000
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 199 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 6.7 M
 (49) STRUCTURE LENGTH 13.1 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 6.1 M
 (52) DECK WIDTH OUT TO OUT 6.7 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 6.1 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 53 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 6.1 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 51.5
 STATUS
 HEALTH INDEX 97.2
 PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- COLLECTOR URBAN 17
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 7
 (59) SUPERSTRUCTURE 7
 (60) SUBSTRUCTURE 7
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- UNKNOWN 0
 (63) OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0
 (64) OPERATING RATING- 40.5
 (65) INVENTORY RATING METHOD- FIELD EVAL/ENG JUL 0
 (66) INVENTORY RATING- 24.3
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 6
 (68) DECK GEOMETRY 2
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 8
 (72) APPROACH ROADWAY ALIGNMENT 6
 (36) TRAFFIC SAFETY FEATURES 1000
 (113) SCOUR CRITICAL BRIDGES 8

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- SUP/SUB REHAB CODE 35
 (76) LENGTH OF STRUCTURE IMPROVEMENT 13.1 M
 (94) BRIDGE IMPROVEMENT COST \$88,000
 (95) ROADWAY IMPROVEMENT COST \$17,600
 (96) TOTAL PROJECT COST \$147,840
 (97) YEAR OF IMPROVEMENT COST ESTIMATE 2017
 (114) FUTURE ADT 4204
 (115) YEAR OF FUTURE ADT 2035

***** INSPECTIONS *****

(90) INSPECTION DATE 12/17 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)

3.6 MI. E/O SANTIAGO ROAD

SILVERADO CANYON CREEK

12/15/2017 [AAAK]

55C0182

121 - PHOTO-Rail-Unusual Conditions




Photo No. 1

The north rail has timber post #4 (counting from west) is missing.

102 - PHOTO-Deck-Damage/Deterioration



Photo No. 2

The soffit has few longitudinal cracks, 0.05 inches wide with light brown efflorescence.