



**DEPARTMENT OF TRANSPORTATION**  
Structure Maintenance & Investigations

**Bridge Number** : 55C0185  
**Facility Carried**: OLIVE HILL ROAD  
**Location** : 50' S/O MODJESKA CYN RD  
**City** :  
**Inspection Date** : 05/07/2019

**Bridge Inspection Report**

**Inspection Type**  
Routine FC Underwater Special Other  
☒ ☐ ☐ ☐ ☐

**STRUCTURE NAME:** SANTIAGO CREEK

**CONSTRUCTION INFORMATION**

Year Built : 1970 Skew (degrees): 0  
Year Modified: N/A No. of Joints : 0  
Length (m) : 11 No. of Hinges : 0

Structure Description: Single span CIP/RC rigid frame slab, all supported upon spread footing.

Span Configuration : (S) 34.00 feet (N)

**SAFE LOAD CAPACITY AND RATINGS**

Design Live Load: UNKNOWN  
Inventory Rating: RF=0.63 =>20.4 metric tons Calculation Method: FIELD EVAL/ENG JUDGMENT  
Operating Rating: RF=1.04 =>33.7 metric tons Calculation Method: FIELD EVAL/ENG JUDGMENT  
Permit Rating : 00000  
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

**DESCRIPTION ON STRUCTURE**

Deck X-Section: (W) 0.30 feet br, 15.50 feet, 0.30 feet br (E)  
Total Width: 4.9 m Net Width: 4.7 m No. of Lanes: 1 Speed: 25 mph  
Min. Vertical Clearance: Unimpaired Overlay Thickness: 0.0 inches  
Rail Code: 1000

**DESCRIPTION UNDER STRUCTURE**

Channel Description: Natural earth trapezoidal with a cobbled bottom.

**NOTICE**

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

**INSPECTION COMMENTARY**

**CONDITION OF STRUCTURE**

A complete routine inspection was performed by walking on and around the bridge to inspect all visible elements of the bridge structure. Bridge slab was inspected by walking on shoulder. Soffit and all substructure were inspected by walking underneath the bridge with rain boots due to 3.0 inches deep of water at the time of inspection.

There is no need for a special equipment to inspect this structure except rain boots if it is in raining season.

**DECK AND ROADWAY**

**INSPECTION COMMENTARY**

There are transverse and diagonal cracks, up to 0.04 inches wide and 5.0 to 10.0 feet long at 1.0 foot near by both of abutments.

The metal bridge beam was hit and bent, 1.0 foot at the west rail, northerly end; and 3.0 feet at the east rail southerly end (see the attached photos no. 3 and 4).

**SUBSTRUCTURE**

There are minor hairline cracks on both of abutment walls.

**SAFE LOAD CAPACITY**

As-built plans are not available for this bridge. The load rating was assigned by the Load Rating Office 04/30/2018 in accordance with Section 5.10 of the SM&I Inspection Procedure Manual and Article 6.1.4 of the AASHTO Manual for Bridge Evaluation (2018, Third Edition). The load rating summary sheet is archived on 04/30/2018.

**ELEMENT INSPECTION RATINGS AND COMMENTARY**

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each	Condition	State
							St. 1	St. 2	St. 3 St. 4
38			Slab-RC	2	54	sq.m	44	10	0 0
	1080		Delamination/Spall/Patched Area	2	10		0	10	0 0
(38)									
There were no significant defects noted.									
(38-1080)									
There are transverse and diagonal cracks, up to 0.04 inches wide and 5.0 to 10.0 feet long at 1.0 foot near by both of abutments.									
215			Abutment-RC	2	10	m	10	0	0 0
(215)									
There were no significant defects noted.									
330			Railing-Metal	2	22	m	20	2	0 0
	1900		Distortion	2	2		0	2	0 0
(330-1900)									
The metal bridge beam was hit and bent, 1.0 foot at the west rail, northerly end; and 3.0 feet at the east rail southerly end (see the attached photos no. 3 and 4).									


**WORK RECOMMENDATIONS**

RecDate: 01/13/2003  
 Action : Railing-Repair  
 Work By: LOCAL AGENCY  
 Status : PROPOSED

EstCost:  
 StrTarget: 2 YEARS  
 DistTarget:  
 EA:

Repair the damaged metal bridge beam that was hit and bent, 1.0 foot at the west rail northerly end; and 3.0 feet at the east rail southerly end.

Team Leader : Edwin Mah  
Report Author : Nelson N. Vo  
Inspected By : NN.Vo/E.Mah

  
Edwin Mah (Registered Civil Engineer) (Date) 8/25/2019



**STRUCTURE INVENTORY AND APPRAISAL REPORT**

## \*\*\*\*\* IDENTIFICATION \*\*\*\*\*

(1) STATE NAME- CALIFORNIA 069  
 (8) STRUCTURE NUMBER 55C0185  
 (5) INVENTORY ROUTE (ON/UNDER)- ON 140000000  
 (2) HIGHWAY AGENCY DISTRICT 12  
 (3) COUNTY CODE 059 (4) PLACE CODE 00000  
 (6) FEATURE INTERSECTED- SANTIAGO CREEK  
 (7) FACILITY CARRIED- OLIVE HILL ROAD  
 (9) LOCATION- 50' S/O MODJESKA CYN RD  
 (11) MILEPOINT/KILOMETERPOINT 0  
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0  
 (13) LRS INVENTORY ROUTE & SUBROUTE  
 (16) LATITUDE 33 DEG 42 MIN 34.04 SEC  
 (17) LONGITUDE 117 DEG 37 MIN 31.68 SEC  
 (98) BORDER BRIDGE STATE CODE % SHARE %  
 (99) BORDER BRIDGE STRUCTURE NUMBER

## \*\*\*\*\* STRUCTURE TYPE AND MATERIAL \*\*\*\*\*

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE  
 TYPE- SLAB CODE 101  
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA  
 TYPE- OTHER/NA CODE 000  
 (45) NUMBER OF SPANS IN MAIN UNIT 1  
 (46) NUMBER OF APPROACH SPANS 0  
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1  
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:  
 A) TYPE OF WEARING SURFACE- NONE CODE 0  
 B) TYPE OF MEMBRANE- NONE CODE 0  
 C) TYPE OF DECK PROTECTION- NONE CODE 0

## \*\*\*\*\* AGE AND SERVICE \*\*\*\*\*

(27) YEAR BUILT 1970  
 (106) YEAR RECONSTRUCTED 0000  
 (42) TYPE OF SERVICE: ON- HIGHWAY 1  
 UNDER- WATERWAY 5  
 (28) LANES:ON STRUCTURE 01 UNDER STRUCTURE 00  
 (29) AVERAGE DAILY TRAFFIC 150  
 (30) YEAR OF ADT 2019 (109) TRUCK ADT 1 %  
 (19) BYPASS, DETOUR LENGTH 199 KM

## \*\*\*\*\* GEOMETRIC DATA \*\*\*\*\*

(48) LENGTH OF MAXIMUM SPAN 10.4 M  
 (49) STRUCTURE LENGTH 11.0 M  
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M  
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 4.7 M  
 (52) DECK WIDTH OUT TO OUT 4.9 M  
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 4.9 M  
 (33) BRIDGE MEDIAN- NO MEDIAN 0  
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO  
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M  
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 4.7 M  
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M  
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M  
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M  
 (56) MIN LAT UNDERCLEAR LT 0.0 M

## \*\*\*\*\* NAVIGATION DATA \*\*\*\*\*

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N  
 (111) PIER PROTECTION- CODE  
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M  
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M  
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

## \*\*\*\*\* SUFFICIENCY RATING \*\*\*\*\*

SUFFICIENCY RATING = 61.3  
 PAINT CONDITION INDEX = N/A

## \*\*\*\*\* CLASSIFICATION \*\*\*\*\* CODE

(112) NBIS BRIDGE LENGTH- YES Y  
 (104) HIGHWAY SYSTEM- NOT ON NHS 0  
 (26) FUNCTIONAL CLASS- LOCAL RURAL 09  
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0  
 (101) PARALLEL STRUCTURE- NONE EXISTS N  
 (102) DIRECTION OF TRAFFIC- 1 LANE, 2 WAY 3  
 (103) TEMPORARY STRUCTURE-  
 (105) FED.LANDS HWY- NOT APPLICABLE 0  
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0  
 (20) TOLL- ON FREE ROAD 3  
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02  
 (22) OWNER- COUNTY HIGHWAY AGENCY 02  
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

## \*\*\*\*\* CONDITION \*\*\*\*\* CODE

(58) DECK 7  
 (59) SUPERSTRUCTURE 7  
 (60) SUBSTRUCTURE 7  
 (61) CHANNEL & CHANNEL PROTECTION 8  
 (62) CULVERTS N

## \*\*\*\*\* LOAD RATING AND POSTING \*\*\*\*\* CODE

(31) DESIGN LOAD- UNKNOWN 0  
 (63) OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0  
 (64) OPERATING RATING- 33.7  
 (65) INVENTORY RATING METHOD- FIELD EVAL/ENG JUI 0  
 (66) INVENTORY RATING- 20.4  
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5  
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A  
 DESCRIPTION- OPEN, NO RESTRICTION

## \*\*\*\*\* APPRAISAL \*\*\*\*\* CODE

(67) STRUCTURAL EVALUATION 5  
 (68) DECK GEOMETRY 2  
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N  
 (71) WATER ADEQUACY 8  
 (72) APPROACH ROADWAY ALIGNMENT 5  
 (36) TRAFFIC SAFETY FEATURES 1000  
 (113) SCOUR CRITICAL BRIDGES 8

## \*\*\*\*\* PROPOSED IMPROVEMENTS \*\*\*\*\*

(75) TYPE OF WORK- CODE  
 (76) LENGTH OF STRUCTURE IMPROVEMENT M  
 (94) BRIDGE IMPROVEMENT COST  
 (95) ROADWAY IMPROVEMENT COST  
 (96) TOTAL PROJECT COST  
 (97) YEAR OF IMPROVEMENT COST ESTIMATE  
 (114) FUTURE ADT 206  
 (115) YEAR OF FUTURE ADT 2037

## \*\*\*\*\* INSPECTIONS \*\*\*\*\*

(90) INSPECTION DATE 05/19 (91) FREQUENCY 24 MO  
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE  
 A) FRACTURE CRIT DETAIL- NO MO A)  
 B) UNDERWATER INSP- NO MO B)  
 C) OTHER SPECIAL INSP- NO MO C)