

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

July 4, 2018

RECEIVED

AUG 17 2018

**OC PUBLIC WORKS
DIRECTOR'S OFFICE**

Mr. Shane Silsby
Director of Public Works
County of Orange
P O Box 4048
Santa Ana, CA 92702-4048

Dear Mr. Silsby:

In accordance with Title 23 of the Code of Federal Regulations (Federal Highway Act) and the National Bridge Inspection Standards (NBIS), Caltrans Structure Maintenance and Investigations performed an inspection of 5 bridges under your jurisdiction. The type of inspection is indicated on the bridge report transmittal sheet. The bridges have been rated to indicate their deficiencies, structural adequacy, safe load carrying capacity and overall general condition.

Enclosed are copies of the Bridge Inspection Reports for the structures noted on the attached transmittal sheet. These reports contain descriptions of physical changes to the structures since the last inspection, recommendations for work to be done, and additional information not recorded in the previous Bridge Reports.

Your attention is directed to the requirements of Title 23, Part 650 of the Code of Federal Regulations, where newly completed structures or any modification of existing structures shall be entered in the inventory within 90 days. Please notify this office of any newly constructed bridge or culvert within your jurisdiction, more than 20 feet measured along the center of the roadway and carrying public vehicular traffic or over a public roadway, in order that it may be entered in the inventory of bridge structures in compliance with Federal requirements.

Should you have any questions regarding the enclosed Bridge Inspection Reports, please contact Bing Wu @ (213) 897-0874.

Sincerely,

A handwritten signature in blue ink, appearing to read "Ching Chao".

CHING CHAO
Office Chief
Structure Maintenance & Investigations - (Investigations-South)

Enclosures

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

Bridge Report Transmittal Sheet**Batch** **45045****County of Orange**

Bridge #	Bridge Name	Location	Inspection		Outstanding	
			Date	Type	Work	Cost
55C0175	LADD CANYON	2.2 MI. E/O SANTIAGO ROAD	12/15/2017	Routine	Y	\$
55C0176	SILVERADO CANYON CREEK	0.1 MI. S/O SLVRDO CYN RD	12/15/2017	Routine	Y	\$
55C0180	SILVERADO CANYON CREEK	2.7 MI E/O SANTIAGO ROAD	12/15/2017	Routine	N	\$
55C0188	SILVERADO CANYON CREEK	200' S/O SILVERADO CYN RD	12/15/2017	Routine	N	\$
55C0189	SILVERADO CANYON CREEK	50' N/O SILVERADO CYN RD	12/15/2017	Routine	Y	\$

5 Bridge(s) in this Transmittal

DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE
STRUCTURE MAINTENANCE & INVESTIGATIONS
100 South Main Street, 3rd Floor
LOS ANGELES, CA 90012
PHONE (213) 897-2004
FAX (213) 897-2033



*Making Conservation
a California Way of Life.*

WEB SITES:

The National Bridge Inspection Standards (NBIS) Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges, Element Level Inspection, Structure Maintenance and Investigations Manuals, Local Assistance Program Guidelines and other related information are posted on Division of Maintenance, Structure Maintenance and Investigations; Division of Local Assistance, Local Highway Bridge Program (HBP) and FHWA websites.

The websites can be accessed at:

1. "Caltrans Structure Maintenance and Investigations" <http://www.dot.ca.gov/hq/structur/strmaint/>
2. "Caltrans Division of Local Assistance"
<http://www.dot.ca.gov/hq/LocalPrograms/hbrr99/hbrr99a.htm>
3. "FHWA" <http://www.fhwa.dot.gov/BRIDGE/mtguide.pdf>

Inspection Type Definitions**Routine Inspection:**

Routine Inspections consist of both the initial Inventory Inspection (the first inspection of the bridge that places it in the bridge inventory or when there has been a change in the configuration of the structure) and subsequent regularly scheduled inspections. The initial inspection provides all the Structural Inventory & Appraisal (SI&A) data required by federal and state regulations, determines the baseline structural conditions, lists any existing problems, and establishes the load capacity of the structure. Subsequent inspections consist of observations, measurements needed to determine the physical and functional condition of the bridge, to identify any changes from the previously recorded conditions, and verification of its load capacity. These inspections are generally conducted from the deck, ground and/or water level, and from permanent work platforms and walkways, if present. Inspection of underwater portions of the substructure is limited to observations during low-flow periods and/or probing for signs of undermining. Special equipment should be utilized in circumstances where its use provides the only practical access to areas of the structure.

Fracture Critical, Special Feature & Underwater Inspections:

Fracture Critical, Special Feature, and Underwater Inspections are up close, hands-on inspections of one or more members above or below the water level to identify any deficiencies not readily detectable using Routine Inspection procedures. These inspections generally require special equipment such as under-bridge inspection equipment, manlifts, boats, traffic control, and railroad flagging. Personnel with special skills such as divers or structural steel inspectors trained in non-destructive testing techniques may be required.

Other Inspections:

Other Inspections are conducted on damaged structures, structures that have developed specific problems, or structures suspected of developing problems. The scope of these investigations should be sufficient to determine the need for emergency load restrictions or closure of the structure, monitor a changing condition, and to assess the level of effort necessary to effect a repair.



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0188
Facility Carried: THISA WAY
Location : 200' S/O SILVERADO CYN R
City :
Inspection Date : 12/15/2017

Bridge Inspection Report

Inspection Type
Routine ☒ FC ☐ Underwater ☐ Special ☐ Other ☐

STRUCTURE NAME: SILVERADO CANYON CREEK

CONSTRUCTION INFORMATION

Year Built : 1965 Skew (degrees): 9
Year Modified: N/A No. of Joints : 0
Length (m) : 7.9 No. of Hinges : 0

Structure Description: Single 7.3 m W x 2.7 m H x 7.4 m L RC box culvert (grade top).
Vehicular traffic ride upon an AC overlay upon the RC culvert top slab.

Span Configuration : (S) 24.00 ft (N)

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN
Inventory Rating: RF=0.75 =>24.3 metric tons Calculation Method: FIELD EVAL/ENG JUDGMENT
Operating Rating: RF=1.25 =>40.5 metric tons Calculation Method: FIELD EVAL/ENG JUDGMENT
Permit Rating : PPPPP
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (W) 0.3 br, 23.30 ft, 0.3 ft br (E)
Total Width: 7.3 m Net Width: 7.2 m No. of Lanes: 2 Speed: 25 mph
Min. Vertical Clearance: Unimpaired Overlay Thickness: 3.0 inches
Rail Code: 1000

Rail Type	Location	Length (ft)	Rail Modifications
MBBR	Right/Left	59	

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with cobbled bottom.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

This inspection was performed by walking on the culvert shoulders and deck, and under the span. A full visual inspection is performed for the visible substructure elements.

There was 4 inches running water through the mid-span, pedestrian inspection access is from northwest and northeast quadrants.

INSPECTION COMMENTARY**DECK AND ROADWAY**

There is a tree growing over the northeast corner of the bridge.

SAFE LOAD CAPACITY

A Load Rating Summary Sheet was updated on 01/24/2016 for this structure. The current rating has been assigned in accordance with SMI procedures for culverts. Based on the field conditions and load history, the culvert is adequate to carry legal loads.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Defect Element Description	Env	Total Qty	Units	Qty in each Condition State	St. 1	St. 2	St. 3	St. 4
241		Culvert-RC	2	8	m	1	7	0	0	
	1130	Cracking (RC and Other)	2	3		0	3	0	0	
	1190	Abrasion (PS Conc./RC)	2	4		0	4	0	0	
	510	Deck Wearing Surface-Asphalt	2	58	sq.m	53	5	0	0	
	3220	Cracking-AC (WS)	2	5		0	5	0	0	

(241-1130)

The soffit of the top slab exhibits:

- * three longitudinal cracks, up to 4 ft long at the southerly wall.
- * three longitudinal cracks, up to 2 ft long at the northerly wall.

The culvert walls exhibit:

- * Culvert wall #1 (south) exhibits a vertical crack, 1.0 mm wide.
- * Culvert wall #2 (north) exhibits two vertical cracks, up to 1.5 mm wide.

(241-1190)

At the north wall, there is an abrasion area at the bottom 3 ft high X most of the entire wall length.

(241-510-3220)

AC exhibits full width transverse cracks, 0.50 inches wide at both ends; and three longitudinal cracks up to 20 feet long and 0.50 inches wide.

330		Railing-Metal	2	18	m	18	0	0	0	
-----	--	---------------	---	----	---	----	---	---	---	--

(330)

There were no significant defects noted.

WORK RECOMMENDATIONS - NONE

Team Leader : Ashraf Shenouda
Report Author : Ashraf Shenouda
Inspected By : A.Shenouda/KD.Henderson



6/27/18

Ashraf Shenouda (Registered Civil Engineer) (Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0188
 (5) INVENTORY ROUTE(ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- SILVERADO CANYON CREEK
 (7) FACILITY CARRIED- THISA WAY
 (9) LOCATION- 200' S/O SILVERADO CYN RD
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0
 (13) LRS INVENTORY ROUTE & SUBROUTE
 (16) LATITUDE 33 DEG 44 MIN 49.51 SEC
 (17) LONGITUDE 117 DEG 38 MIN 22.57 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE
 TYPE- CULVERT CODE 119
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 1
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- NOT APPLICABLE CODE N
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- BITUMINOUS CODE 6
 B) TYPE OF MEMBRANE- NOT APPLICABLE CODE N
 C) TYPE OF DECK PROTECTION- NOT APPLICABLE CODE N

***** AGE AND SERVICE *****

(27) YEAR BUILT 1965
 (106) YEAR RECONSTRUCTED 0000
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 200
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 2 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 7.3 M
 (49) STRUCTURE LENGTH 7.9 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 7.2 M
 (52) DECK WIDTH OUT TO OUT 7.3 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 7.4 M
 (33) BRIDGE MEDIAN- NO MEDIAN 0
 (34) SKEW 9 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 7.2 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING *****

SUFFICIENCY RATING = 82.5

***** STATUS *****

HEALTH INDEX 87.7

PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- NOT ON NHS 0
 (26) FUNCTIONAL CLASS- LOCAL RURAL 09
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK N
 (59) SUPERSTRUCTURE N
 (60) SUBSTRUCTURE N
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS 6

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- UNKNOWN 0
 (63) OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0
 (64) OPERATING RATING- 40.5
 (65) INVENTORY RATING METHOD- FIELD EVAL/ENG JUL 0
 (66) INVENTORY RATING- 24.3
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 6
 (68) DECK GEOMETRY 4
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 6
 (72) APPROACH ROADWAY ALIGNMENT 6
 (36) TRAFFIC SAFETY FEATURES 1000
 (113) SCOUR CRITICAL BRIDGES 3

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 210
 (115) YEAR OF FUTURE ADT 2035

***** INSPECTIONS *****

(90) INSPECTION DATE 12/17 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)

**NO BRIDGE
INSPECTION REPORT
PHOTOS FOR
55C0188**

SILVERADO CANYON CREEK

0.1 MI. S/O SLVRDO CYN RD

12/15/2017 [AAAK]

55C0176

113 - PHOTO-Sub-Damage/Deterioration



Photo No. 1

Some aggregates were missing from the north abutment westerly end.

115 - PHOTO-Sub-Unusual Conditions



Photo No. 2

Undermining 2.5'X 5' X 20' at 10 ft from the west end of the bridge.

SILVERADO CANYON CREEK

0.1 MI. S/O SLVRDO CYN RD

12/15/2017 [AAAK]

55C0176

115 - PHOTO-Sub-Unusual Conditions



Photo No. 3

Undermining 2.5'X 5' X 20' at 10 ft from the west end of the bridge.

115 - PHOTO-Sub-Unusual Conditions



Photo No. 4

The channel bed is degraded in front of the grouted channel bed 20' dia. X 3' Deep.

102 - PHOTO-Deck-Damage/Deterioration




Photo No. 1

Diagonal and longitudinal cracks with white and brown efflorescence.