

## DEPARTMENT OF TRANSPORTATION

DIVISION OF MAINTENANCE  
STRUCTURE MAINTENANCE & INVESTIGATIONS  
100 South Main Street, 3rd Floor  
LOS ANGELES, CA 90012  
PHONE (213) 897-2004  
FAX (213) 897-2033



Making Conservation  
a California Way of Life.

March 23, 2020

RECEIVED

MAR 31 2020

OC PUBLIC WORKS  
DIRECTOR'S OFFICE

100  
or: Regina  
c: Nancy 2 pages

Mr. Shane Silsby  
Director of Public Works  
County of Orange  
P O Box 4048  
Santa Ana, CA 92702-4048

Dear Mr. Silsby:

In accordance with Title 23 of the Code of Federal Regulations (Federal Highway Act) and the National Bridge Inspection Standards (NBIS), Caltrans Structure Maintenance and Investigations performed an inspection of 4 bridges under your jurisdiction. The type of inspection is indicated on the bridge report transmittal sheet. The bridges have been rated to indicate their deficiencies, structural adequacy, safe load carrying capacity and overall general condition.

Enclosed are copies of the Bridge Inspection Reports for the structures noted on the attached transmittal sheet. These reports contain descriptions of physical changes to the structures since the last inspection, recommendations for work to be done, and additional information not recorded in the previous Bridge Reports.

Your attention is directed to the requirements of Title 23, Part 650 of the Code of Federal Regulations, where newly completed structures or any modification of existing structures shall be entered in the inventory within 90 days. Please notify this office of any newly constructed bridge or culvert within your jurisdiction, more than 20 feet measured along the center of the roadway and carrying public vehicular traffic or over a public roadway, in order that it may be entered in the inventory of bridge structures in compliance with Federal requirements.

Should you have any questions regarding the enclosed Bridge Inspection Reports, please contact Bing Wu @ (213) 897-0874.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Ching Chao'.

CHING CHAO  
Office Chief  
Structure Maintenance & Investigations -  
(Investigations-South)

Enclosures

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF MAINTENANCE  
STRUCTURE MAINTENANCE & INVESTIGATIONS  
100 South Main Street, 3rd Floor  
LOS ANGELES, CA 90012  
PHONE (213) 897-2004  
FAX (213) 897-2033



*Making Conservation  
a California Way of Life.*

**Bridge Report Transmittal Sheet****Batch 57987****County of Orange**

Bridge #	Bridge Name	Location	Inspection		Outstanding	
			Date	Type	Work	Cost
55C0205	SANTA ANA DELHI CHANNEL	0.1 MI S/O BRISTOL STREET	02/06/2020	Routine	Y	\$
55C0572	SANTA ANA DELHI CHANNEL	0.4 MI SW/O BRISTOL ST.	02/06/2020	Routine	Y	\$
55C0573	REDHILL CHANNEL	0.1 MI. NW/O BROWNING AVE	02/06/2020	Routine	N	\$
55C0574	REDHILL CHANNEL	0.1 MI. NW/O BROWNING AVE	02/06/2020	Routine	Y	\$

4 Bridge(s) in this Transmittal

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF MAINTENANCE  
STRUCTURE MAINTENANCE & INVESTIGATIONS  
100 South Main Street, 3rd Floor  
LOS ANGELES, CA 90012  
PHONE (213) 897-2004  
FAX (213) 897-2033



*Making Conservation  
a California Way of Life.*

**WEB SITES:**

The National Bridge Inspection Standards (NBIS) Recording and Coding Guide for the Structure Inventory and Appraisal of the Nation's Bridges, Element Level Inspection, Structure Maintenance and Investigations Manuals, Local Assistance Program Guidelines and other related information are posted on Division of Maintenance, Structure Maintenance and Investigations; Division of Local Assistance, Local Highway Bridge Program (HBP) and FHWA websites.

The websites can be accessed at:

1. "Caltrans Structure Maintenance and Investigations" <http://www.dot.ca.gov/hq/structur/strmaint/>
2. "Caltrans Division of Local Assistance"  
<http://www.dot.ca.gov/hq/LocalPrograms/hbrr99/hbrr99a.htm>
3. "FHWA" <http://www.fhwa.dot.gov/BRIDGE/mtguide.pdf>

**Inspection Type Definitions****Routine Inspection:**

Routine Inspections consist of both the initial Inventory Inspection (the first inspection of the bridge that places it in the bridge inventory or when there has been a change in the configuration of the structure) and subsequent regularly scheduled inspections. The initial inspection provides all the Structural Inventory & Appraisal (SI&A) data required by federal and state regulations, determines the baseline structural conditions, lists any existing problems, and establishes the load capacity of the structure. Subsequent inspections consist of observations, measurements needed to determine the physical and functional condition of the bridge, to identify any changes from the previously recorded conditions, and verification of its load capacity. These inspections are generally conducted from the deck, ground and/or water level, and from permanent work platforms and walkways, if present. Inspection of underwater portions of the substructure is limited to observations during low-flow periods and/or probing for signs of undermining. Special equipment should be utilized in circumstances where its use provides the only practical access to areas of the structure.

**Fracture Critical, Special Feature & Underwater Inspections:**

Fracture Critical, Special Feature, and Underwater Inspections are up close, hands-on inspections of one or more members above or below the water level to identify any deficiencies not readily detectable using Routine Inspection procedures. These inspections generally require special equipment such as under-bridge inspection equipment, manlifts, boats, traffic control, and railroad flagging. Personnel with special skills such as divers or structural steel inspectors trained in non-destructive testing techniques may be required.

**Other Inspections:**

Other Inspections are conducted on damaged structures, structures that have developed specific problems, or structures suspected of developing problems. The scope of these investigations should be sufficient to determine the need for emergency load restrictions or closure of the structure, monitor a changing condition, and to assess the level of effort necessary to effect a repair.



**DEPARTMENT OF TRANSPORTATION**  
Structure Maintenance & Investigations

Bridge Number : 55C0573  
Facility Carried: RIVERFORD ROAD  
Location : 0.1 MI. NW/O BROWNING AV  
City :  
Inspection Date : 02/06/2020

**Bridge Inspection Report**

Inspection Type

Routine	FC	Underwater	Special	Other
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**STRUCTURE NAME:** REDHILL CHANNEL

**CONSTRUCTION INFORMATION**

Year Built : 1980	Skew (degrees): 0
Year Modified: 1989	No. of Joints : 0
Length (m) : 6.7	No. of Hinges : 0

Structure Description: Double 12 ft W and 8.5 ft W x 8 ft H x 47 ft L RC box culvert beneath 2 ft of earth fill and AC surfacing.

Span Configuration : (W) 8.50 ft, 12.00 ft (E) clear, normal

**SAFE LOAD CAPACITY AND RATINGS**

Design Live Load: UNKNOWN		
Inventory Rating: RF=1.00 =>32.4 metric tons	Calculation Method: FIELD EVAL/ENG JUDGMENT	
Operating Rating: RF=1.67 =>54.1 metric tons	Calculation Method: FIELD EVAL/ENG JUDGMENT	
Permit Rating : PPPPP		
Posting Load : Type 3: <u>Legal</u>	Type 3S2: <u>Legal</u>	Type 3-3: <u>Legal</u>

**DESCRIPTION ON STRUCTURE**

Deck X-Section: (S) 0.70 ft br, 4.00 ft sw, 36.00 ft, 4.00 ft sw, 0.70 ft br (N)  
Total Width: 14.8 m Net Width: 11.0 m No. of Lanes: 2 Speed: 25 mph  
Min. Vertical Clearance: Unimpaired Overlay Thickness: 3.0 inches  
Rail Code: 0000

**DESCRIPTION UNDER STRUCTURE**

Channel Description: RC rectangular.

**NOTICE**

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

**INSPECTION COMMENTARY**

**SCOPE AND ACCESS**

A routine inspection was performed by Y. Chen and P. Piratheepan. The conditions of AC pavement surface and rails on the top of the bridge were inspected by walking along the sidewalks. The conditions of culvert cells were inspected at walking through both cells. At the time of inspection, there was up to 1-inch deep water on the bottom of both culvert cells. A 12 ft aluminum extension ladder was used to reach the channel bottom.

**DECK AND ROADWAY**

There are transverse cracks on AC pavement at the areas above abutments up to 0.2 inch

**INSPECTION COMMENTARY**

wide (Photo Number 2).

**SAFE LOAD CAPACITY**

A revised assigned load rating has been performed on this structure by SMI Ratings Branch based on Section 5.10 of the SM&I Inspection Procedure Manual and a Load Rating Summary Sheet (LRSS) dated on 09/21/2018 is in file. While this report does not include a check of that analysis, it does verify that the structural conditions observed during this inspection are consistent with those assumed in that analysis.

**ELEMENT INSPECTION RATINGS AND COMMENTARY**

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each State	St. 1	St. 2	St. 3	St. 4
241		Culvert-RC	2	28	m	28	0	0	0	0
(241) There were no significant defects noted. All wall vertical and diagonal cracks are sealed with epoxy paste by local agency (Photo Number 5).										
334		Railing-Masonry	2	13	m	13	0	0	0	0
(334) There were no significant defects noted.										

**WORK RECOMMENDATIONS** - NONE

Team Leader : Young Chen  
 Report Author : Young Chen  
 Inspected By : Y.Chen/P.Piratheepan

Young Chen 3/16/2020  
 Young Chen (Registered Civil Engineer) (Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

## \*\*\*\*\* IDENTIFICATION \*\*\*\*\*

(1) STATE NAME- CALIFORNIA 069  
 (8) STRUCTURE NUMBER 55C0573  
 (5) INVENTORY ROUTE(ON/UNDER)- ON 140000000  
 (2) HIGHWAY AGENCY DISTRICT 12  
 (3) COUNTY CODE 059 (4) PLACE CODE 00000  
 (6) FEATURE INTERSECTED- REDHILL CHANNEL  
 (7) FACILITY CARRIED- RIVERFORD ROAD  
 (9) LOCATION- 0.1 MI. NW/O BROWNING AVE  
 (11) MILEPOINT/KILOMETERPOINT 0  
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0  
 (13) LRS INVENTORY ROUTE & SUBROUTE  
 (16) LATITUDE 33 DEG 44 MIN 17.15 SEC  
 (17) LONGITUDE 117 DEG 48 MIN 08.32 SEC  
 (98) BORDER BRIDGE STATE CODE % SHARE %  
 (99) BORDER BRIDGE STRUCTURE NUMBER

## \*\*\*\*\* STRUCTURE TYPE AND MATERIAL \*\*\*\*\*

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE  
 TYPE- CULVERT CODE 119  
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA  
 TYPE- OTHER/NA CODE 000  
 (45) NUMBER OF SPANS IN MAIN UNIT 2  
 (46) NUMBER OF APPROACH SPANS 0  
 (107) DECK STRUCTURE TYPE- NOT APPLICABLE CODE N  
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:  
 A) TYPE OF WEARING SURFACE- NOT APPLICABLE CODE N  
 B) TYPE OF MEMBRANE- NOT APPLICABLE CODE N  
 C) TYPE OF DECK PROTECTION- NOT APPLICABLE CODE N

## \*\*\*\*\* AGE AND SERVICE \*\*\*\*\*

(27) YEAR BUILT 1980  
 (106) YEAR RECONSTRUCTED 1989  
 (42) TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5  
 UNDER- WATERWAY 5  
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00  
 (29) AVERAGE DAILY TRAFFIC 1040  
 (30) YEAR OF ADT 2010 (109) TRUCK ADT 1 %  
 (19) BYPASS, DETOUR LENGTH 2 KM

## \*\*\*\*\* GEOMETRIC DATA \*\*\*\*\*

(48) LENGTH OF MAXIMUM SPAN 3.7 M  
 (49) STRUCTURE LENGTH 6.7 M  
 (50) CURB OR SIDEWALK: LEFT 1.2 M RIGHT 1.2 M  
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 11.0 M  
 (52) DECK WIDTH OUT TO OUT 14.8 M  
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 11.0 M  
 (33) BRIDGE MEDIAN- NO MEDIAN 0  
 (34) SKEW 0 DEG (35) STRUCTURE FLARED NO  
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M  
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 11.0 M  
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M  
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M  
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M  
 (56) MIN LAT UNDERCLEAR LT 0.0 M

## \*\*\*\*\* NAVIGATION DATA \*\*\*\*\*

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N  
 (111) FIER PROTECTION- CODE  
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M  
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M  
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

\*\*\*\*\* SUFFICIENCY RATING = 96.9  
 PAINT CONDITION INDEX = N/A

## \*\*\*\*\* CLASSIFICATION \*\*\*\*\* CODE

(112) NBIS BRIDGE LENGTH- YES Y  
 (104) HIGHWAY SYSTEM- NOT ON NHS 0  
 (26) FUNCTIONAL CLASS- LOCAL URBAN 19  
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0  
 (101) PARALLEL STRUCTURE- NONE EXISTS N  
 (102) DIRECTION OF TRAFFIC- 2 WAY 2  
 (103) TEMPORARY STRUCTURE-  
 (105) FED.LANDS HWY- NOT APPLICABLE 0  
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0  
 (20) TOLL- ON FREE ROAD 3  
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02  
 (22) OWNER- COUNTY HIGHWAY AGENCY 02  
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

## \*\*\*\*\* CONDITION \*\*\*\*\* CODE

(58) DECK N  
 (59) SUPERSTRUCTURE N  
 (60) SUBSTRUCTURE N  
 (61) CHANNEL & CHANNEL PROTECTION 9  
 (62) CULVERTS 7

## \*\*\*\*\* LOAD RATING AND POSTING \*\*\*\*\* CODE

(31) DESIGN LOAD- UNKNOWN 0  
 (63) OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0  
 (64) OPERATING RATING- 54.1  
 (65) INVENTORY RATING METHOD- FIELD EVAL/ENG JUD 0  
 (66) INVENTORY RATING- 32.4  
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5  
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A  
 DESCRIPTION- OPEN, NO RESTRICTION

## \*\*\*\*\* APPRAISAL \*\*\*\*\* CODE

(67) STRUCTURAL EVALUATION 7  
 (68) DECK GEOMETRY 6  
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N  
 (71) WATER ADEQUACY 9  
 (72) APPROACH ROADWAY ALIGNMENT 8  
 (36) TRAFFIC SAFETY FEATURES 0000  
 (113) SCOUR CRITICAL BRIDGES 8

## \*\*\*\*\* PROPOSED IMPROVEMENTS \*\*\*\*\*

(75) TYPE OF WORK- CODE  
 (76) LENGTH OF STRUCTURE IMPROVEMENT M  
 (94) BRIDGE IMPROVEMENT COST  
 (95) ROADWAY IMPROVEMENT COST  
 (96) TOTAL PROJECT COST  
 (97) YEAR OF IMPROVEMENT COST ESTIMATE  
 (114) FUTURE ADT 2096  
 (115) YEAR OF FUTURE ADT 2037

## \*\*\*\*\* INSPECTIONS \*\*\*\*\*

(90) INSPECTION DATE 02/20 (91) FREQUENCY 48 MO  
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE  
 A) FRACTURE CRIT DETAIL- NO MO A)  
 B) UNDERWATER INSP- NO MO B)  
 C) OTHER SPECIAL INSP- NO MO C)

100 - PHOTO> Routine-Roadway View



Photo No. 1

ROADWAY VIEW LOOKING SOUTHEAST

133 - PHOTO> Unclassified



Photo No. 2

A TRANSVERSE ROADWAY AC PAVEMENT CRACK ABOVE THE CULVERT

101 - PHOTO> Routine-Elevation View



Photo No. 3

SIDE VIEW LOOKING SOUTHWEST

135 - PHOTO> Routine-Underside View



Photo No. 4

UNDER VIEW IN THE WEST CELL, LOOKING SOUTHWEST



# REDHILL CHANNEL

0.1 MI. NW/O BROWNING AVE

02/06/2020 [AAA]

55C0573

118 - PHOTO> Sub-Repairs



Photo No. 5

TYPICAL SEALED WALL CRACKS ALONG CELLS

101 - PHOTO> Routine-Elevation View



Photo No. 6

SIDE VIEW LOOKING NORTHEAST



Photo No. 7

UNDER VIEW IN THE EAST CELL, LOOKING SOUTHWEST