



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0637
Facility Carried: CROWN VALLEY PKWY
Location : 0.5 MI E/O MARGUERITE PW
City :
Inspection Date : 03/20/2019

Bridge Inspection Report

Inspection Type
Routine ☒ FC ☐ Underwater ☐ Special ☐ Other ☐

STRUCTURE NAME: ARROYO TRABUCO

CONSTRUCTION INFORMATION

Year Built : 2000 Skew (degrees): 0
Year Modified: 2005 No. of Joints : 2
Length (m) : 238 No. of Hinges : 0

Structure Description: Continuous 4-span CIP/PS concrete box girder (5 cells) with RC 2-column bents and RC closed end backfilled cantilever abutments, all supported upon 2 feet diameter (abutments) and 10 feet diameter (bents) CIDH concrete piles.
Widen (North side): Continuous 4-span CIP/PS concrete box girder (3 cells) with RC 1-column bents and RC closed end backfilled cantilever abutments.

Span Configuration : (W) 170.50 feet, 219.75 feet, 219.75 feet, 170.50 feet (E) c/c

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: HL 93
Inventory Rating: RF= 1.00 Calculation Method: ASSIGNED (LRFD)
Operating Rating: RF= 1.30 Calculation Method: ASSIGNED (LRFD)
Permit Rating : PPPPP
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (N) 1.00 foot br, 5.00 feet sw, 54.75 feet, 4.00 feet median, 55.00 feet; 5.00 feet sw, 1.00 foot br (S)
Total Width: 38.3 m Net Width: 33.5 m No. of Lanes: 7 Speed: 55 mph
Min. Vertical Clearance: Unimpaired Overlay Thickness: 0.0 inches
Rail Code: 0110

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth canyon.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

A complete routine inspection was performed by walking on and around the bridge to inspect all visible elements of the bridge structure. Bridge deck was inspected by walking on shoulder and median area. Soffit and all substructure were inspected by walking underneath the bridge.

INSPECTION COMMENTARY

The channel is dry and with vegetation from spans #2 through #4 at the time of inspection.

Pedestrian access underneath the bridge is through a hole in CLF in span 4.

There is no need for a special equipment to inspect this structure.

DECK AND ROADWAY

There are random longitudinal to diagonal cracks, up to 0.06 inches wide and 10.0 feet long throughout the entire deck. There are especially map pattern cracks, up to 0.05 inches wide and 6.0 inches in spacing heavily on westbound lane #1 next to median throughout the entire length.

There are longitudinal cracks 50.0 feet long and up to 0.06 inches wide on both directions above bents #2, #3, and #4; and also, there are few longitudinal cracks 3.0 feet long and up to 0.05 inches wide scattering throughout the deck. The work-recommendation has been made to seal deck cracks with Methacrylate.

Westbound, the middle metal members of the Assembly-Joint are broken, snapped right between lanes #2 and #3 on eastbound at both abutment joints. In addition, The entire rubber strip seal of ELI 303 are twisted, cracked and missing at both abutments. The work-recommendation has been made in the previous bridge inspection report.

The approach and departure slabs have map and longitudinal cracks up to 15.0 feet long and 0.05 inches wide.

Westbound, there are total of eight manholes on the bridge deck.

SUPERSTRUCTURE

There are few longitudinal cracks from 8.0 feet to 12.0 feet long on soffit of the southerly box girder in span #4 about 8.0 feet from the southerly edge.

SUBSTRUCTURE

There is no notable distress observed at the time of inspection.

MISCELLANEOUS

There is a construction project to replace joint seal assembly ELI #303 from Orange County Public Agency at the time of inspection.

ENCROACHMENTS

There are total of 6.0 metal conduits (5 at 2.0 inches diameter, 1 at 2.0 inches diameter) those run across the westerly slope protection at the time of inspection.

SAFE LOAD CAPACITY

A Load Rating Summary Sheet dated 03/19/2013 is on file for this structure. The current rating has been assigned in accordance with SMI procedures.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each	Condition	State	
						St. 1	St. 2	St. 3	St. 4
16		Top Flange-RC	2	9115	sq.m	7315	1100	700	0
	1130	Cracking (RC and Other)	2	1800		0	1100	700	0
(16)									
Deck cracks throughout the entire deck.									
(16-1130)									
There are random longitudinal to diagonal cracks, up to 0.06 inches wide and 10.0 feet long throughout the entire deck. There are especially map pattern cracks, up to 0.05 inches wide and 6.0 inches in spacing heavily on westbound lane #1 next to median throughout the entire length.									
There are longitudinal cracks 50.0 feet long and up to 0.06 inches wide on both directions above bents #2, #3, and #4; and also, there are few longitudinal cracks 3.0 feet long and up to 0.05 inches wide scattering throughout the deck.									
104		Box Girder-PS Conc.	2	476	m	468	8	0	0
	1110	Cracking (PS Conc.)	2	8		0	8	0	0
(104)									
There were no significant defects noted.									
(104-1110)									
There are few longitudinal cracks from 8.0 feet to 12.0 feet long on soffit of the southerly box girder in span #4 about 8.0 feet from the southerly edge.									
205		Column-RC	2	9	each	9	0	0	0
(205)									
There were no significant defects noted.									
215		Abutment-RC	2	90	m	90	0	0	0
(215)									
There were no significant defects noted.									
252		Pile-CIDH	2	1	ea.	1	0	0	0
(252)									
The pile element is included to indicate the presence of piles on this structure. The piles were not exposed for visual inspection. No indication of pile distress was noted in any substructure element.									
256		Slope Protection	2	2	ea.	2	0	0	0
(256)									
There were no significant defects noted.									
303		Joint-Assembly w/ Seal	2	76	m	51	20	5	0
	2330	Seal Damage (Joints)	2	10		0	10	0	0
	2370	Metal Deter./Damage (Joints)	2	15		0	10	5	0

(303)

Aluminum members are broken; and Strip seal are cracked. There is a construction project to replace this bridge element at the time of inspection.

(303-2330)

Westbound, the middle metal members of the Assembly-Joint are broken, snapped right between lanes #2 and #3 on eastbound at both abutment joints. In addition, The entire rubber strip seal of ELI 303 are twisted, cracked and missing at both abutments. The work-recommendation has been made in the previous bridge inspection report.


ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Element Description	Env	Total Qty	Units	Qty in each	Condition	State
						St. 1	St. 2	St. 3 St. 4
(303-2370)								
The middle metal bar is broken at at the stripping line between eastbound lanes #2 and #3 above the west abutment, and this bar is bent and warp in eastbound lanes #1 and #2, therefore the joint seal is torn out. (see photo 4).								
The middle metal bar is broken at at the stripping line between eastbound lanes #2 and #3 above the east abutment. (see photo 9)								
312		Bearing-Enclosed	2	2	each	2	0	0 0
(312)								
There were no significant defects noted.								
321		Approach Slab-RC	2	555	sq.m	415	80	60 0
	1130	Cracking (RC and Other)	2	140		0	80	60 0
(321)								
There were no significant defects noted.								
(321-1130)								
The approach and departure slabs have map and longitudinal cracks up to 15.0 feet long and 0.05 inches wide.								
331		Railing-RC	2	476	m	476	0	0 0
(331)								
There were no significant defects noted.								

WORK RECOMMENDATIONS

RecDate: 08/23/2016	EstCost:	Clean and seal the deck cracks and cracks
Action : Deck-Methacrylate	StrTarget: 2 YEARS	on approach and departure slabs by using
Work By: LOCAL AGENCY	DistTarget:	methacrylate.
Status : PROPOSED	EA:	
RecDate: 08/23/2016	EstCost:	Replace the aluminum joints with proper
Action : Joints-Replace	StrTarget: 2 YEARS	joint seal assembly.
Work By: LOCAL AGENCY	DistTarget:	
Status : PROPOSED	EA:	
RecDate: 02/10/2013	EstCost:	The county has to check the utility pipes
Action : Super-Misc.	StrTarget: 2 YEARS	inside the box cells where the soffit
Work By: LOCAL AGENCY	DistTarget:	access is leaking water and the cover
Status : PROPOSED	EA:	place is heavily rusted and corroded in
		span 4.

Team Leader : Edwin Mah
Report Author : Nelson N. Vo
Inspected By : NN.Vo/E.Mah


Edwin Mah (Registered Civil Engineer) (Date) 7/17/2019



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0637
 (5) INVENTORY ROUTE(ON/UNDER)- ON 150000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- ARROYO TRABUCO
 (7) FACILITY CARRIED- CROWN VALLEY PKWY
 (9) LOCATION- 0.5 MI E/O MARGUERITE PWY
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- PART OF NET 1
 (13) LRS INVENTORY ROUTE & SUBROUTE 000000000000
 (16) LATITUDE 33 DEG 33 MIN 46.01 SEC
 (17) LONGITUDE 117 DEG 39 MIN 10.4 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- PRSTR CONC CONT
 TYPE- BOX BEAM OR GIRDER - MULTI CODE 605
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 4
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- NONE CODE 0
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 2000
 (106) YEAR RECONSTRUCTED 2005
 (42) TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 07 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 33160
 (30) YEAR OF ADT 2019 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 20 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 67.0 M
 (49) STRUCTURE LENGTH 238.0 M
 (50) CURB OR SIDEWALK: LEFT 1.5 M RIGHT 1.5 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 33.5 M
 (52) DECK WIDTH OUT TO OUT 38.3 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 33.5 M
 (33) BRIDGE MEDIAN- CLOSED NON-MOUNTABLE 3
 (34) SKEW 0 DEG (35) STRUCTURE FLARED YES
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 16.8 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

***** SUFFICIENCY RATING = 83.0 *****

PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- ROUTE ON NHS 1
 (26) FUNCTIONAL CLASS- OTHER PRIN ART URBAN 14
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 5
 (59) SUPERSTRUCTURE 7
 (60) SUBSTRUCTURE 7
 (61) CHANNEL & CHANNEL PROTECTION 9
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- HL 93 A
 (63) OPERATING RATING METHOD- ASSIGNED (LRFD) F
 (64) OPERATING RATING- RF= 1.30
 (65) INVENTORY RATING METHOD- ASSIGNED (LRFD) F
 (66) INVENTORY RATING- RF= 1.00
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 7
 (68) DECK GEOMETRY 9
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 9
 (72) APPROACH ROADWAY ALIGNMENT 8
 (36) TRAFFIC SAFETY FEATURES 0110
 (113) SCOUR CRITICAL BRIDGES 5

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 60565
 (115) YEAR OF FUTURE ADT 2037

***** INSPECTIONS *****

(90) INSPECTION DATE 03/19 (91) FREQUENCY 24 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)