

## **Orange County Bridge Review Summary**

Dokken Engineering performed a field review of the Orange County bridge listed below in April 2017 to identify maintenance activities eligible for Caltrans' Bridge Preventive Maintenance Program (BPMP), dated December 2015, funding. Additional maintenance activities, if present, not eligible for BPMP funding were also noted. Maintenance recommendations, if noted in the most recent Caltrans Bridge Inspection Report (BIR), were confirmed.

**Bridge Number:** 55C0121

**Bridge Name:** Brea Canyon Channel

**Year Built:** 1920

**Facility Carried:** Brea Canyon BLVD

The Brea Canyon Channel at Brea Canyon Boulevard is a continuous 2-span cast-in-place reinforced concrete deck slab supported by struttled abutments, on unknown foundation type.

### **Caltrans BIR recommendations:**

- Repair spall and delamination at north side of pier wall, west face of wall.
- Clearing and grubbing channel bed.

### **Field Inspection Observations**

- There was limited access to the substructure.
- Exposed rebar on pier wall (photo 2).
- Confirmed vegetation overgrowth in channel. Recommend clearing and grubbing the channel.
- Portion of road is being undermined. Recommend removing portion of AC and filling and reconstructing the eroded slope. Investigate if roadside drainage pattern is causing erosion.
- Rutting at power pole. Recommend filling eroded slope. (photo 3)

### **Maintenance Needs Assessment**

#### **BPMP Assessment**

- N/A – No eligible maintenance activities

#### **General Maintenance – Non-BPMP**

- Repair spalled pier wall. This should be performed soon to prevent additional corrosion of reinforcement.

### **BPMP Assessment**

- Recommend patching spalled concrete on pier wall.

### **Proposed BPMP Construction Costs**

- N/A

### **Construction Items Not Funded by BPMP**

- Repair Spalls < \$10,000 (includes engineering, mobilization and contingency)
- Clearing and Grubbing
- Bank erosion repair

# **APPENDIX A**

## **Photos and BIR**



Photo 1: Edge of Pavement



Photo 2: Bridge Pier



Photo 3:



Photo 4: Pier Wall



Photo 5:



Photo 6:



DEPARTMENT OF TRANSPORTATION  
Structure Maintenance & Investigations

Bridge Number : 55C0121  
Facility Carried: BREA CANYON BLVD.  
Location : 0.4 MI N/O CENTRAL AVENUE  
City :  
Inspection Date : 10/02/2015

# Bridge Inspection Report

Inspection Type  
Routine FC Underwater Special Other  
☒

**STRUCTURE NAME:** BREA CANYON CHANNEL

## CONSTRUCTION INFORMATION

Year Built : 1920 Skew (degrees): 32  
Year Widened: 1929 No. of Joints : 0  
Length (m) : 9.1 No. of Hinges : 0

Structure Description: Continuous 2-span CIP/RC deck slab under 1.5 m of fill with an RC pier and RC closed end backfilled strutted abutments. Foundation type is unknown.

Span Configuration : (S) 2 @ 4.1 m (N) c/c

## SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN  
Inventory Rating: RF=1.00 =>32.4 metric tons Calculation Method: LOAD FACTOR  
Operating Rating: RF=1.67 =>54.1 metric tons Calculation Method: LOAD FACTOR  
Permit Rating : P P P P P  
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

## DESCRIPTION ON STRUCTURE

Deck X-Section: (W) 3.4 m ea, 11 m, 0.9 m ea (E)  
Total Width: 17.1 m Net Width: 11.3 m No. of Lanes: 2 Speed: 55 mph  
Min. Vertical Clearance: Unimpaired Overlay Thickness: 6.0 Inches  
Rail Code: 0000

| Rail Type | Location | Length (ft) | Rail Modifications |
|-----------|----------|-------------|--------------------|
| MBGR on   | Right    | 30          |                    |
| Fill      |          |             |                    |
| None      | Left     |             |                    |

## DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with heavy bushes and trees in the channel bed.

## NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

## INSPECTION COMMENTARY

### SCOPE AND ACCESS

The inspection was performed by walking on and under the bridge. There was 2' of stagnant water in span #1 (south) and there was 2.5' of dirt accumulated in span #2 (north); all elements were Visually inspected. Access the under the bridge is from northeast quadrant.

**INSPECTION COMMENTARY****SAFE LOAD CAPACITY**

The load rating for this structure is being reviewed by SM&I Rating Branch. An updated Load Rating Summary Sheet will be archived when this review is completed. The current load rating is based on BDS computer output dated 11/21/1979.

**ELEMENT INSPECTION RATINGS AND NOTES**

| Elem No.  | Defect /Prot | Defect | Element Description             | Env | Total Qty | Units | Qty in each State | Condition | State       |
|---|--------------|--------|---------------------------------|-----|-----------|-------|-------------------|-----------|-------------|
|   |              |        |                                 |     |           |       | St. 1             | St. 2     | St. 3 St. 4 |
| 38  |              |        | Slab-RC                         | 2   | 156       | sq.m  | 156               | 0         | 0 0         |
|   | 510          |        | Deck Wearing Surface-Asphalt    | 2   | 110       | sq.m  | 110               | 0         | 0 0         |
| (38)  |              |        |                                 |     |           |       |                   |           |             |
| There were no significant defects noted. (under 4ft of fill)  |              |        |                                 |     |           |       |                   |           |             |
| (38-510)  |              |        |                                 |     |           |       |                   |           |             |
| There were no significant defects noted. (above 4 ft of fill)   |              |        |                                 |     |           |       |                   |           |             |
| 210   |              |        | Pier Wall-RC                    | 2   | 17        | m     | 11                | 3         | 3 0         |
|   | 1080         |        | Delamination/Spall/Patched Area | 2   | 6         |       | 0                 | 3         | 3 0         |
| (210-1080)  |              |        |                                 |     |           |       |                   |           |             |
| There is 10' x 2' x 2" spall in the west side at the north end with exposed rebars and delamination in the east side of the northend of the peirwall #2 |              |        |                                 |     |           |       |                   |           |             |
| 215   |              |        | Abutment-RC                     | 2   | 34        | m     | 34                | 0         | 0 0         |
| (215)   |              |        |                                 |     |           |       |                   |           |             |
| There were no significant defects noted.  |              |        |                                 |     |           |       |                   |           |             |
| 313   |              |        | Bearing-Fixed                   | 2   | 21        | each  | 21                | 0         | 0 0         |
| (313)   |              |        |                                 |     |           |       |                   |           |             |
| There were no significant defects noted.  |              |        |                                 |     |           |       |                   |           |             |
| 330   |              |        | Railing-Metal                   | 2   | 10        | m     | 10                | 0         | 0 0         |
| (330)   |              |        |                                 |     |           |       |                   |           |             |
| There were no significant defects noted.  |              |        |                                 |     |           |       |                   |           |             |

**WORK RECOMMENDATIONS**

RecDate: 05/18/2012

Action : Sub-Patch spalls

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Repair the spall and delamination at the north side of the pier wall west face of the wall 3 m x 0.6 m x 50 mm spall and at the east face of the wall the delamination area 3 m x 0.5 m.

RecDate: 06/05/2001

Action : Remove Vegetation

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

StrTarget: 2 YEARS

DistTarget:

EA:

Clean the channel to improve the water flow. Remove the bushes and the trees in the channel bed within 30 meters of the bridge.

Team Leader : Mikhael T. Zaarour  
Report Author : Mikhael T. Zaarour  
Inspected By : MT.Zaarour / DH.Kim

*Mikhael T. Zaarour* 2/24/16  
Mikhael T. Zaarour (Registered Civil Engineer) (Date)



**STRUCTURE INVENTORY AND APPRAISAL REPORT**

## \*\*\*\*\* IDENTIFICATION \*\*\*\*\*

(1) STATE NAME- CALIFORNIA 069  
 (8) STRUCTURE NUMBER 55C0121  
 (5) INVENTORY ROUTE(ON/UNDER)- ON 140000000  
 (2) HIGHWAY AGENCY DISTRICT 12  
 (3) COUNTY CODE 059 (4) PLACE CODE 00000  
 (6) FEATURE INTERSECTED- BREA CANYON CHANNEL  
 (7) FACILITY CARRIED- BREA CANYON BLVD.  
 (9) LOCATION- 0.4 MI N/O CENTRAL AVENUE  
 (11) MILEPOINT/KILOMETERPOINT 0  
 (12) BASE HIGHWAY NETWORK- NOT ON NET 0  
 (13) LRS INVENTORY ROUTE & SUBROUTE  
 (16) LATITUDE 33 DEG 56 MIN 16.26 SEC  
 (17) LONGITUDE 117 DEG 53 MIN 29.83 SEC  
 (98) BORDER BRIDGE STATE CODE % SHARE %  
 (99) BORDER BRIDGE STRUCTURE NUMBER

## \*\*\*\*\* STRUCTURE TYPE AND MATERIAL \*\*\*\*\*

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE  
 TYPE- SLAB CODE 101  
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA  
 TYPE- OTHER/NA CODE 000  
 (45) NUMBER OF SPANS IN MAIN UNIT 2  
 (46) NUMBER OF APPROACH SPANS 0  
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1  
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:  
 A) TYPE OF WEARING SURFACE- GRAVEL CODE 8  
 B) TYPE OF MEMBRANE- NONE CODE 0  
 C) TYPE OF DECK PROTECTION- NONE CODE 0

## \*\*\*\*\* AGE AND SERVICE \*\*\*\*\*

(27) YEAR BUILT 1920  
 (106) YEAR RECONSTRUCTED 1929  
 (42) TYPE OF SERVICE: ON- HIGHWAY 1  
 UNDER- WATERWAY 5  
 (28) LANES:ON STRUCTURE 02 UNDER STRUCTURE 00  
 (29) AVERAGE DAILY TRAFFIC 19000  
 (30) YEAR OF ADT 2009 (109) TRUCK ADT 2 %  
 (19) BYPASS, DETOUR LENGTH 2 KM

## \*\*\*\*\* GEOMETRIC DATA \*\*\*\*\*

(48) LENGTH OF MAXIMUM SPAN 4.3 M  
 (49) STRUCTURE LENGTH 9.1 M  
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M  
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 11.3 M  
 (52) DECK WIDTH OUT TO OUT 17.1 M  
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 11.0 M  
 (33) BRIDGE MEDIAN- NO MEDIAN 0  
 (34) SKEW 32 DEG (35) STRUCTURE FLARED NO  
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M  
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 8.5 M  
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M  
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M  
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M  
 (56) MIN LAT UNDERCLEAR LT 0.0 M

## \*\*\*\*\* NAVIGATION DATA \*\*\*\*\*

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N  
 (111) PIER PROTECTION- CODE  
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M  
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M  
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

## \*\*\*\*\* SUFFICIENCY RATING \*\*\*\*\*

SUFFICIENCY RATING = 93.2  
 STATUS  
 HEALTH INDEX 98.4  
 PAINT CONDITION INDEX = N/A

## \*\*\*\*\* CLASSIFICATION \*\*\*\*\* CODE

(112) NBIS BRIDGE LENGTH- YES Y  
 (104) HIGHWAY SYSTEM- NOT ON NHS 0  
 (26) FUNCTIONAL CLASS- MINOR ARTERIAL URBAN 16  
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0  
 (101) PARALLEL STRUCTURE- NONE EXISTS N  
 (102) DIRECTION OF TRAFFIC- 2 WAY 2  
 (103) TEMPORARY STRUCTURE-  
 (105) FED.LANDS HWY- NOT APPLICABLE 0  
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0  
 (20) TOLL- ON FREE ROAD 3  
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02  
 (22) OWNER- COUNTY HIGHWAY AGENCY 02  
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

## \*\*\*\*\* CONDITION \*\*\*\*\* CODE

(58) DECK 8  
 (59) SUPERSTRUCTURE 8  
 (60) SUBSTRUCTURE 7  
 (61) CHANNEL & CHANNEL PROTECTION 8  
 (62) CULVERTS N

## \*\*\*\*\* LOAD RATING AND POSTING \*\*\*\*\* CODE

(31) DESIGN LOAD- UNKNOWN 0  
 (63) OPERATING RATING METHOD- LOAD FACTOR 1  
 (64) OPERATING RATING- 54.1  
 (65) INVENTORY RATING METHOD- LOAD FACTOR 1  
 (66) INVENTORY RATING- 32.4  
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5  
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A  
 DESCRIPTION- OPEN, NO RESTRICTION

## \*\*\*\*\* APPRAISAL \*\*\*\*\* CODE

(67) STRUCTURAL EVALUATION 7  
 (68) DECK GEOMETRY 4  
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N  
 (71) WATER ADEQUACY 9  
 (72) APPROACH ROADWAY ALIGNMENT 8  
 (36) TRAFFIC SAFETY FEATURES 0000  
 (113) SCOUR CRITICAL BRIDGES U

## \*\*\*\*\* PROPOSED IMPROVEMENTS \*\*\*\*\*

(75) TYPE OF WORK- CODE  
 (76) LENGTH OF STRUCTURE IMPROVEMENT M  
 (94) BRIDGE IMPROVEMENT COST  
 (95) ROADWAY IMPROVEMENT COST  
 (96) TOTAL PROJECT COST  
 (97) YEAR OF IMPROVEMENT COST ESTIMATE  
 (114) FUTURE ADT 41217  
 (115) YEAR OF FUTURE ADT 2035

## \*\*\*\*\* INSPECTIONS \*\*\*\*\*

(90) INSPECTION DATE 10/15 (91) FREQUENCY 24 MO  
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE  
 A) FRACTURE CRIT DETAIL- NO MO A)  
 B) UNDERWATER INSP- NO MO B)  
 C) OTHER SPECIAL INSP- NO MO C)