



DEPARTMENT OF TRANSPORTATION
Structure Maintenance & Investigations

Bridge Number : 55C0148
Facility Carried: WARNER AVENUE
Location : 0.1 MI W/O HARBOR BLVD
City :
Inspection Date : 10/24/2014

Bridge Inspection Report

Inspection Type

Routine FC Underwater Special Other

☒

STRUCTURE NAME: SANTA ANA RIVER CHANNEL (WARNER AVE)

CONSTRUCTION INFORMATION

Year Built : 1961 Skew (degrees): 9
Year Widened: 1969 No. of Joints : 2
Length (m) : 77.4 No. of Hinges : 2

Structure Description: Continuous six span CIP/RC T-beam (9 each) and widened 3 girders N and 2 girders S with RC pier walls and RC open end diaphragm abutments, all supported upon concrete piles. Wi

Span Configuration : (W) 10.4 m, 4 @ 14.0 m, 10.4 m (E) c/c

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: MS-18 OR HS-20
Inventory Rating: RF=1.00 =>32.4 metric tons Calculation Method: ASSIGNED (LFD)
Operating Rating: RF=1.67 =>54.1 metric tons Calculation Method: ASSIGNED (LFD)
Permit Rating : PPPPP
Posting Load : Type 3: Legal Type 3S2: Legal Type 3-3: Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.3 m br, 1.5 m sw, 13.4 m, 2.4 m med, 12.3 m, 1.5 m sw, 0.3 m br (N)
Total Width: 31.6 m Net Width: 24.5 m No. of Lanes: 6 Speed: 45 mph
Min. Vertical Clearance: Unimpaired

Rail Code: 1111

Rail Type	Location	Length (ft)	Rail Modifications
Type 26	Right/Left	525	

DESCRIPTION UNDER STRUCTURE

Channel Description: RC trapezoidal.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

The river was dry at inspection time. All elements were visually inspected.

DECK AND ROADWAY

There is a hole (18" x 8" x 12") in the AC westbound departure lane #1.

INSPECTION COMMENTARY**REVISIONS**

The bridge name was revised to include the road carried name.

Old name: SANTA ANA RIVER CHANNEL.

New name: SANTA ANA RIVER CHANNEL (WARNER AVE).

SAFE LOAD CAPACITY

A load Rating Summary sheet is included with this bridge inspection report. This load rating was assigned in accordance with current SM&I procedures.

ELEMENT INSPECTION RATINGS AND COMMENTARY

Elem No.	Defect /Prot	Defect	Element Description	Env	Total Qty	Units	Qty in each Condition	State		
							St. 1	St. 2	St. 3	St. 4
12			Deck-RC	2	688	sq.m	688	0	0	0
(12)										
There were no significant defects noted.										
16			Top Flange-RC	2	1757	sq.m	1757	0	0	0
	511		Deck Wearing Surface-Concrete	2	1571	sq.m	1571	0	0	0
(16)										
There were no significant defects noted.										
(16-511)										
There were no significant defects noted.										
109			Girder/Beam-PS Conc.	2	387	m	387	0	0	0
(109)										
There were no significant defects noted.										
110			Girder/Beam-RC	2	697	m	697	0	0	0
(110)										
There were no significant defects noted.										
182			EQ Restrainer Cable-Other	2	18	ea.	18	0	0	0
(182)										
There were no significant defects noted.										
210			Pier Wall-RC	2	155	m	155	0	0	0
(210)										
There were no significant defects noted.										
215			Abutment-RC	2	64	m	64	0	0	0
(215)										
There were no significant defects noted.										
256			Slope Protection	2	2	ea.	2	0	0	0
(256)										
There were no significant defects noted.										
302			Joint-Compression Seal	2	56	m	56	0	0	0
(302)										
There were no significant defects noted.										
312			Bearing-Enclosed	2	2	each	2	0	0	0


ELEMENT INSPECTION RATINGS AND COMMENTARY


Elem No.	Defect /Prot	Defect	Element Description	Env Qty	Total Qty	Units	Qty in each Condition State			
							St. 1	St. 2	St. 3	St. 4
(312)										
There were no significant defects noted.										
331			Railing-RC	2	155	m	155	0	0	0
(331)										
There were no significant defects noted.										

WORK RECOMMENDATIONS

RecDate: 10/24/2014 EstCost: Repair the hole (18" x 8" x 12") in the
 Action : Appr. Roadway-Repair StrTarget: 2 YEARS AC westbound departure (west) lane #1.
 Work By: LOCAL AGENCY DistTarget:
 Status : PROPOSED EA:

Team Leader : Mikhael T. Zaarour
 Report Author : Mikhael T. Zaarour
 Inspected By : MT.Zaarour/KD.Henderson

 11/13/14
 Mikhael T. Zaarour (Registered Civil Engineer) (Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

***** IDENTIFICATION *****

(1) STATE NAME- CALIFORNIA 069
 (8) STRUCTURE NUMBER 55C0148
 (5) INVENTORY ROUTE(ON/UNDER)- ON 140000000
 (2) HIGHWAY AGENCY DISTRICT 12
 (3) COUNTY CODE 059 (4) PLACE CODE 00000
 (6) FEATURE INTERSECTED- SANTA ANA RIVER CHANNEL
 (7) FACILITY CARRIED- WARNER AVENUE
 (9) LOCATION- 0.1 MI W/O HARBOR BLVD
 (11) MILEPOINT/KILOMETERPOINT 0
 (12) BASE HIGHWAY NETWORK- PART OF NET 1
 (13) LRS INVENTORY ROUTE & SUBROUTE 000000000000
 (16) LATITUDE 33 DEG 42 MIN 51.96 SEC
 (17) LONGITUDE 117 DEG 55 MIN 18.68 SEC
 (98) BORDER BRIDGE STATE CODE % SHARE %
 (99) BORDER BRIDGE STRUCTURE NUMBER

***** STRUCTURE TYPE AND MATERIAL *****

(43) STRUCTURE TYPE MAIN:MATERIAL- CONCRETE CONT
 TYPE- TEE BEAM CODE 204
 (44) STRUCTURE TYPE APPR:MATERIAL- OTHER/NA
 TYPE- OTHER/NA CODE 000
 (45) NUMBER OF SPANS IN MAIN UNIT 6
 (46) NUMBER OF APPROACH SPANS 0
 (107) DECK STRUCTURE TYPE- CIP CONCRETE CODE 1
 (108) WEARING SURFACE / PROTECTIVE SYSTEM:
 A) TYPE OF WEARING SURFACE- CONCRETE CODE 1
 B) TYPE OF MEMBRANE- NONE CODE 0
 C) TYPE OF DECK PROTECTION- NONE CODE 0

***** AGE AND SERVICE *****

(27) YEAR BUILT 1961
 (106) YEAR RECONSTRUCTED 1969
 (42) TYPE OF SERVICE: ON- HIGHWAY 1
 UNDER- WATERWAY 5
 (28) LANES:ON STRUCTURE 06 UNDER STRUCTURE 00
 (29) AVERAGE DAILY TRAFFIC 25000
 (30) YEAR OF ADT 2008 (109) TRUCK ADT 1 %
 (19) BYPASS, DETOUR LENGTH 2 KM

***** GEOMETRIC DATA *****

(48) LENGTH OF MAXIMUM SPAN 14.0 M
 (49) STRUCTURE LENGTH 77.4 M
 (50) CURB OR SIDEWALK: LEFT 0.0 M RIGHT 1.5 M
 (51) BRIDGE ROADWAY WIDTH CURB TO CURB 24.5 M
 (52) DECK WIDTH OUT TO OUT 31.6 M
 (32) APPROACH ROADWAY WIDTH (W/SHOULDERS) 25.7 M
 (33) BRIDGE MEDIAN- CLOSED (NO BARRIER) 2
 (34) SKEW 9 DEG (35) STRUCTURE FLARED NO
 (10) INVENTORY ROUTE MIN VERT CLEAR 99.99 M
 (47) INVENTORY ROUTE TOTAL HORIZ CLEAR 13.4 M
 (53) MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M
 (54) MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M
 (55) MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M
 (56) MIN LAT UNDERCLEAR LT 0.0 M

***** NAVIGATION DATA *****

(38) NAVIGATION CONTROL- NOT APPLICABLE CODE N
 (111) PIER PROTECTION- CODE
 (39) NAVIGATION VERTICAL CLEARANCE 0.0 M
 (116) VERT-LIFT BRIDGE NAV MIN VERT CLEAR M
 (40) NAVIGATION HORIZONTAL CLEARANCE 0.0 M

SUFFICIENCY RATING = 91.5
 STATUS
 HEALTH INDEX 100.0
 PAINT CONDITION INDEX = N/A

***** CLASSIFICATION ***** CODE

(112) NBIS BRIDGE LENGTH- YES Y
 (104) HIGHWAY SYSTEM- ROUTE ON NHS 1
 (26) FUNCTIONAL CLASS- OTHER PRIN ART URBAN 14
 (100) DEFENSE HIGHWAY- NOT STRAHNET 0
 (101) PARALLEL STRUCTURE- NONE EXISTS N
 (102) DIRECTION OF TRAFFIC- 2 WAY 2
 (103) TEMPORARY STRUCTURE-
 (105) FED.LANDS HWY- NOT APPLICABLE 0
 (110) DESIGNATED NATIONAL NETWORK - NOT ON NET 0
 (20) TOLL- ON FREE ROAD 3
 (21) MAINTAIN- COUNTY HIGHWAY AGENCY 02
 (22) OWNER- COUNTY HIGHWAY AGENCY 02
 (37) HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5

***** CONDITION ***** CODE

(58) DECK 8
 (59) SUPERSTRUCTURE 8
 (60) SUBSTRUCTURE 8
 (61) CHANNEL & CHANNEL PROTECTION 8
 (62) CULVERTS N

***** LOAD RATING AND POSTING ***** CODE

(31) DESIGN LOAD- MS-18 OR HS-20 5
 (63) OPERATING RATING METHOD- ASSIGNED (LFD) A
 (64) OPERATING RATING- 54.1
 (65) INVENTORY RATING METHOD- ASSIGNED (LFD) A
 (66) INVENTORY RATING- 32.4
 (70) BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
 (41) STRUCTURE OPEN, POSTED OR CLOSED- A
 DESCRIPTION- OPEN, NO RESTRICTION

***** APPRAISAL ***** CODE

(67) STRUCTURAL EVALUATION 8
 (68) DECK GEOMETRY 5
 (69) UNDERCLEARANCES, VERTICAL & HORIZONTAL N
 (71) WATER ADEQUACY 9
 (72) APPROACH ROADWAY ALIGNMENT 7
 (36) TRAFFIC SAFETY FEATURES 1111
 (113) SCOUR CRITICAL BRIDGES 8

***** PROPOSED IMPROVEMENTS *****

(75) TYPE OF WORK- CODE
 (76) LENGTH OF STRUCTURE IMPROVEMENT M
 (94) BRIDGE IMPROVEMENT COST
 (95) ROADWAY IMPROVEMENT COST
 (96) TOTAL PROJECT COST
 (97) YEAR OF IMPROVEMENT COST ESTIMATE
 (114) FUTURE ADT 57703
 (115) YEAR OF FUTURE ADT 2031

***** INSPECTIONS *****

(90) INSPECTION DATE 10/14 (91) FREQUENCY 48 MO
 (92) CRITICAL FEATURE INSPECTION: (93) CFI DATE
 A) FRACTURE CRIT DETAIL- NO MO A)
 B) UNDERWATER INSP- NO MO B)
 C) OTHER SPECIAL INSP- NO MO C)