

Bridge Number : 55C0174
Facility Carried: SILVERADO CNYN RD.
Location : 1.6 MI E/O SANTIAGO ROAD
City :
Inspection Date : 05/28/2014
Inspection Type
Routine ☒ FC ☐ Underwater ☐ Special ☐ Other

Inspection Type

Routine	<u>FC</u>	Underwater	Special	Other

X

Rail Type	Location	Length (ft)	Rail Modifications
Misc. Steel	Right/Left		

55C0174/AAAO/29738

STEEL INVESTIGATIONS

This structure qualifies for an in-depth Steel investigation because it possesses the following fracture critical or fatigue prone details :

Plate Girder: FC Members

Fracture Critical: Yes

Inspection Freq.: 24

Next Inspection: 05/28/2016

Team Leader : Carlos Villalobos
Report Author : Carlos Villalobos
Inspected By : C.Villalobos/A.Rouzbehan

Carlos F. Villalobos 9/15/2014

Carlos Villalobos (Registered Civil Engineer) (Date)

