

DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

: 55C0180 Bridge Number

Facility Carried: SILVERADO CNYN RD

Location : 2.7 MI E/O SANTIAGO ROAD

Inspection Date: 12/20/2015

Inspection Type

Routine FC Underwater Special Other

Х

Bridge Inspection Report

STRUCTURE NAME: SILVERADO CANYON CREEK

CONSTRUCTION INFORMATION

Year Built : 1971 Year Widened: N/A Length (m) : 16.2

Skew (degrees): No. of Joints : No. of Hinges :

Structure Description: Single span CIP/RC rigid frame slab, all supported upon spread

footings.

:(W) 1 @ 7.3 m (E) clear, normal Span Configuration

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN

Inventory Rating: RF=0.75 =>24.3 metric tons

Calculation Method: FIELD EVAL/ENG JUDGMENT Calculation Method: FIELD EVAL/ENG JUDGMENT

Operating Rating: RF=1.25 =>40.5 metric tons

Permit Rating : PPPPP

Posting Load : Type 3: Legal Type 3S2:Legal

Type 3-3:Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 1.2 m min deck, 0.3 m br, 2 @ 3.8 m, 0.3 m br, 1.5 m min deck (N)

Total Width: 11.0 m Min. Vertical Clearance: Unimpaired

Net Width: 7.6 m No. of Lanes: 2

Speed: 25 mph

Overlay Thickness: 3.0 Inches

Rail Code: 1000

Rail Type Location Length (ft) Rail Modifications MBBR Right/Left 111

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with a cobbled bottom.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

The water in the channel is 10" deep, so all visible substructure elements were inspected.

03/11/2016 01:45 PM

SAFE LOAD CAPACITY

Printed on: Friday

55C0180/AAAJ/34050

INSPECTION COMMENTARY

A Load Rating Summary Sheet dated 2/3/2014 is on file for this structure. The current rating has been assigned in accordance with SMI procedures for concrete bridges without plans.

Elem	Defect De	efect Element Description	Env	Total	Units	Qty in	each Co	ndition	State
No.	/Prot			Qty		St. 1	St. 2	St. 3	St. 4
38		Slab-RC	2	534	sq.m	518	16	0	0
	1080	Delamination/Spall/Patched Area	2	1		0	1	0	0
	1130	Cracking (RC and Other)	2	15		0	15	0	0
	510	Deck Wearing Surface-Asphalt	2	123	sq.m	120	3	0	0
	3	220 Cracking-AC (WS)	2	3		0	3	0	0
There the bi (38-1) There Long v	are two s ridge. 130) are three with light	e longitudinal and two diagonal cracks in brown efflorescence.	n the	soffit	near l	ooth ab	utments,	up to	8 ft
the br (38-11 There long v The so	are two s ridge. 130) are three with light offit has from the	e longitudinal and two diagonal cracks i	n the	soffit	near l	ooth ab	utments,	up to	8 ft
There the bi (38-1) There long v The so 15 ft (38-5)	are two s ridge. 130) are three with light offit has from the 10-3220)	e longitudinal and two diagonal cracks i brown efflorescence. a crack almost 1/2 width of the span, t	n the	soffit	near h	noth ab	utments,	up to	8 ft
There the bi (38-1) There long w The so 15 ft (38-5)	are two s ridge. 130) are three with light offit has from the 10-3220)	e longitudinal and two diagonal cracks in brown efflorescence. a crack almost 1/2 width of the span, to north end.	n the	soffit	near h	noth ab	utments,	up to	8 ft
There the br (38-11 There long v The sc 15 ft (38-51	are two s ridge. 130) are three with light offit has from the 10-3220)	e longitudinal and two diagonal cracks in brown efflorescence. a crack almost 1/2 width of the span, to north end. ibits few diagonal, and transverse full	n the	soffit rack ex-	near h	ooth ab	utments, the eas	up to	8 ft ent at
There the br (38-11) There Long v The so (38-51) (38-51) (215-1)	are two s ridge. 130) are three with light offit has from the 10-3220) erlay exhi	e longitudinal and two diagonal cracks in brown efflorescence. a crack almost 1/2 width of the span, to north end. ibits few diagonal, and transverse full Abutment-RC	n the his cr	soffit cack excracks	near letends of up to	nooth ab	utments, the eas wide.	up to	8 ft ent at

WORK RECOMMENDATIONS - NONE

Team Leader : Ashraf Shenouda Ashraf Shenouda Report Author : A.Shenouda/KD.Henderson Inspected By :

Ashraf Shenouda (Registered Civil Engineer)

PROFESSIONA Ashraf Shenouda No. <u>64332</u> 06/30/2017 CIVIL

55C0180/AAAJ/34050

Printed on: Friday 03/11/2016 01:45 PM

STRUCTURE INVENTORY AND APPRAISAL REPORT

	**************************************		***********
107			SUFFICIENCY RATING = 54.7
93	STATE NAME- CALIFORNIA 069		STATUS
2500000	STRUCTURE NUMBER 55C0180		HEALTH INDEX 98.8
	INVENTORY ROUTE (ON/UNDER) - ON 140000000 HIGHWAY AGENCY DISTRICT 12		PAINT CONDITION INDEX = N/A
700.000			******* CLASSIFICATION ******* CODE
	COUNTY CODE 059 (4) PLACE CODE 00000	(112)	NBIS BRIDGE LENGTH- YES Y
	FEATURE INTERSECTED- SILVERADO CANYON CREEK		HIGHWAY SYSTEM- NOT ON NHS 0
	FACILITY CARRIED- SILVERADO CNYN RD		FUNCTIONAL CLASS- MAJOR COLLECTOR RURAL 07
	LOCATION- 2.7 MI E/O SANTIAGO ROAD MILEDOINT/KILOMETERPOINT 0		DEFENSE HIGHWAY- NOT STRAHNET 0
	MILEPOINT/KILOMETERPOINT 0 BASE HIGHWAY NETWORK- NOT ON NET 0		PARALLEL STRUCTURE- NONE EXISTS N
	LRS INVENTORY ROUTE & SUBROUTE		DIRECTION OF TRAFFIC- 2 WAY 2
,,	LATITUDE 33 DEG 44 MIN 48.61 SEC		TEMPORARY STRUCTURE-
	LONGITUDE 117 DEG 37 MIN 52.44 SEC		FED.LANDS HWY- NOT APPLICABLE 0
7/A/C2/00/00 (A/C	BORDER BRIDGE STATE CODE	(110)	DESIGNATED NATIONAL NETWORK - NOT ON NET 0
	DOINDER DRIDGE CITIES CODE	(20)	TOLL- ON FREE ROAD 3
(99)	BORDER BRIDGE STRUCTURE NUMBER	(21)	MAINTAIN- COUNTY HIGHWAY AGENCY 02
3	****** STRUCTURE TYPE AND MATERIAL ******	(22)	OWNER- COUNTY HIGHWAY AGENCY 02
(43)	STRUCTURE TYPE MAIN: MATERIAL- CONCRETE	(37)	HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5
	TYPE- SLAB CODE 101		******* CODE
(44)	STRUCTURE TYPE APPR:MATERIAL- OTHER/NA		
	TYPE- OTHER/NA CODE 000	Associated.	DECK 8
(45)	NUMBER OF SPANS IN MAIN UNIT	,,	SUPERSTRUCTURE 8
(46)	NUMBER OF APPROACH SPANS 0	*	SUBSTRUCTURE 7
(107)	DECK STRUCTURE TYPE- CIP CONCRETE CODE 1		CHANNEL & CHANNEL PROTECTION 8 CULVERTS N
(108)	WEARING SURFACE / PROTECTIVE SYSTEM:	(62)	CULVERTS
A)	TYPE OF WEARING SURFACE- BITUMINOUS CODE 6		****** LOAD RATING AND POSTING ****** CODE
	TYPE OF MEMBRANE- NONE CODE 0	(31)	DESIGN LOAD- UNKNOWN 0
	TYPE OF DECK PROTECTION- NONE CODE 0	(63)	OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0
	******* AGE AND SERVICE *********	(64)	OPERATING RATING- 40.5
(27)	YEAR BUILT 1971	(65)	INVENTORY RATING METHOD- FIELD EVAL/ENG JUL 0
(106)	YEAR RECONSTRUCTED 0000	(66)	INVENTORY RATING- 24.3
(42)	TYPE OF SERVICE: ON- HIGHWAY 1	(70)	BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
(20)	UNDER- WATERWAY 5	(41)	STRUCTURE OPEN, POSTED OR CLOSED- A
	LANES:ON STRUCTURE 02 UNDER STRUCTURE 00 AVERAGE DAILY TRAFFIC 2000		DESCRIPTION- OPEN, NO RESTRICTION
	AVERAGE DAILY TRAFFIC 2000 YEAR OF ADT 2009 (109) TRUCK ADT 1 %		******* APPRAISAL ********* CODE
	TO STATE OF THE ST		CONTROL DIVINITAL
(19)	Billion Billon Billion		DRGW GROWDERN
	******* GEOMETRIC DATA **********	*	UNDERCLEARANCES, VERTICAL & HORIZONTAL N
	LENGTH OF MAXIMUM SPAN 7.3 M		WATER ADEQUACY 9
	STRUCTURE LENGTH 16.2 M		APPROACH ROADWAY ALIGNMENT 6
	CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M	(36)	TRAFFIC SAFETY FEATURES 1000
	BRIDGE ROADWAY WIDTH CURB TO CURB 7.6 M	(113)	SCOUR CRITICAL BRIDGES 8
	DECK WIDTH OUT TO OUT 11.0 M		****** PROPOSED IMPROVEMENTS *******
	APPROACH ROADWAY WIDTH (W/SHOULDERS) 7.0 M BRIDGE MEDIAN 0	(25)	
	DATE OF THE PARTY.		TYPE OF WORK- CODE
2000			LENGTH OF STRUCTURE IMPROVEMENT M
	INVENTORY ROUTE MIN VERT CLEAR 99.99 M		BRIDGE IMPROVEMENT COST
	INVENTORY ROUTE TOTAL HORIZ CLEAR 7.6 M MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M		ROADWAY IMPROVEMENT COST
	MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M	11.591.591.000.501	TOTAL PROJECT COST
	MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M		YEAR OF IMPROVEMENT COST ESTIMATE
	MIN LAT UNDERCLEAR LT 0.0 M		FUTURE ADT 4204
	****** NAVIGATION DATA *********	(115)	YEAR OF FUTURE ADT 2035
(20)			**************************************
	NAVIGATION CONTROL- NOT APPLICABLE CODE N		INSPECTION DATE 12/15 (91) FREQUENCY 24 MO
	PIER PROTECTION- CODE NAVIGATION VERTICAL CLEARANCE 0.0 M		CRITICAL FEATURE INSPECTION: (93) CFI DATE
	NAVIGATION VERTICAL CLEARANCE 0.0 M VERT-LIFT BRIDGE NAV MIN VERT CLEAR M		FRACTURE CRIT DETAIL- NO MO A)
	NAVIGATION HORIZONTAL CLEARANCE 0.0 M		UNDERWATER INSP- NO MO B)
, 10)	0.0 M	C)	OTHER SPECIAL INSP- NO MO C)