Caltrans

DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

Bridge Inspection Report

Bridge Number : 55C0181

Facility Carried: SILVERADO CNYN RD.

Location : 3.1 MI E/O SANTIAGO ROAD

ity

Inspection Date : 12/20/2015

Inspection Type

Routine FC Underwater Special Other

Х

STRUCTURE NAME: SILVERADO CANYON CREEK

CONSTRUCTION INFORMATION

Year Built : 1970 Year Widened: N/A

Length (m) : 14

Skew (degrees): 59 No. of Joints: 0

No. of Hinges:

Structure Description: Single span CIP/RC rigid frame slab, all supported upon spread

footings.

Span Configuration : (W) 1 @ 6.1 m (E) clear, normal

SAFE LOAD CAPACITY AND RATINGS

Design Live Load: UNKNOWN

Inventory Rating: RF=0.75 =>24.3 metric tons

Calculation Method: FIELD EVAL/ENG JUDGMENT Calculation Method: FIELD EVAL/ENG JUDGMENT

Operating Rating: RF=1.25 =>40.5 metric tons
Permit Rating: PPPPP

Posting Load : Type 3: Legal

Type 3S2:Legal

Type 3-3:Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.6 m min deck, 0.3 m br, 2 @ 4.1 m, 0.3 m br, 0.6 m min deck (N)

Total Width: 8.2 m Net Wid

Net Width: 7.3 m No. of Lanes: 2

Speed: 25 mph

Min. Vertical Clearance: Unimpaired

Overlay Thickness: 3.0 Inches

Rail Code: 0000

Rail Type Location Length (ft) Rail Modifications

Miscellane Right/Left 124

ous

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth trapezoidal with a cobbled bottom.

NOTICE

The bridge inspection condition assessment used for this inspection is based on the American Association of State Highway and Transportation Officials (AASHTO) Bridge Element Inspection Manual 2013 as defined in Moving Ahead for Progress in the 21st Century (MAP-21) federal law. The new element inspection methodology may result in changes to related condition and appraisal ratings on the bridge without significant physical changes at the bridge.

The element condition information contained in this report represents the current condition of the bridge based on the most recent routine and special inspections. Some of the notes presented below may be from an inspection that occurred prior to the date noted in this report. Refer to the Scope and Access section of this inspection report for a description of which portions of the bridge were inspected on this date.

INSPECTION COMMENTARY

SCOPE AND ACCESS

The water in the channel is 8" deep, so all visible substructure elements were visually inspected.

SAFE LOAD CAPACITY

Printed on: Friday 03/11/2016 01:45 PM

55C0181/AAAJ/34050

INSPECTION COMMENTARY

A Load Rating Summary Sheet dated 2/10/2014 is on file for this structure. The current rating has been assigned in accordance with SMI procedures for concrete bridges without plans.

	Defect Defec	ON RATINGS AND NOTES Et Element Description	Env		Units			Condition 2 St. 3	
	71100			Qty					
38		Slab-RC	2	434	sq.m	399	30	5	0
	1130	Cracking (RC and Other)	2	35		0	30	5	0
	510	Deck Wearing Surface-Asphalt	2	102	sq.m	102	0	0	0
		s five full length longitudinal crack	s fro	m abutı	ment to	abutme	ent wi	ith white	and
(38-51 There	-,	ificant defects noted.							***************************************
215		Abutment-RC	3	60	m .	37	23	0	0
	1130	Cracking (RC and Other)	3	8		0	8	0	0
	6000	Scour	3	15		0	15	0	0
(215-1 There		ical cracks at each abutment wall, up	to 1	.5 mm v	wide.				
	st abutment	has 20 ft of exposed footings, up to		-				ongth	
333	sc abucilienc .	Railing-Other	2	38	m	28	2	4	4
	1020	Connection	2	4		0	0	0	4
	1220	Deterioration (Other)	2	6		0	2	4	0
(333-1 South		timber posts #3 and #7 were missing	(coun	ting fr	om wes	t).	ē		7
(333-1 Post #	/	from west) was decayed and has sectio	n los	s.				2	

WORK RECOMMENDATIONS - NONE

Team Leader : Ashraf Shenouda

Ashraf Shenouda Report Author :

A.Shenouda/KD.Henderson Inspected By :

Ashraf Shenouda (Registered Civil Engineer)

PROFESSIONA Ashraf Shenouda No. 64332 06/30/2017 CIVIL

STRUCTURE INVENTORY AND APPRAISAL REPORT

	**************************************		**********
(1)	STATE NAME- CALIFORNIA 069		SUFFICIENCY RATING = 52.5
(8)	STRUCTURE NUMBER 55C0181		STATUS
	INVENTORY ROUTE(ON/UNDER) - ON 140000000		HEALTH INDEX 94.9
	HIGHWAY AGENCY DISTRICT 12		PAINT CONDITION INDEX = N/A
	COUNTY CODE 059 (4) PLACE CODE 00000		******** CLASSIFICATION ******** CODE
	FEATURE INTERSECTED- SILVERADO CANYON CREEK	(112)	NBIS BRIDGE LENGTH- YES Y
	FACILITY CARRIED- SILVERADO CNYN RD.	(104)	HIGHWAY SYSTEM- NOT ON NHS
**********	LOCATION- 3.1 MI E/O SANTIAGO ROAD	(26)	FUNCTIONAL CLASS- COLLECTOR URBAN 17
3.00	MILEPOINT/KILOMETERPOINT 0	(100)	DEFENSE HIGHWAY- NOT STRAHNET 0
	BASE HIGHWAY NETWORK- NOT ON NET 0	(101)	PARALLEL STRUCTURE- NONE EXISTS N
	LRS INVENTORY ROUTE & SUBROUTE	(102)	DIRECTION OF TRAFFIC- 2 WAY 2
	LATITUDE 33 DEG 44 MIN 49.79 SEC	(103)	TEMPORARY STRUCTURE-
	LONGITUDE 117 DEG 37 MIN 23.53 SEC	(105)	FED.LANDS HWY- NOT APPLICABLE 0
	BORDER BRIDGE STATE CODE	(110)	DESIGNATED NATIONAL NETWORK - NOT ON NET 0
	DODDED DELDGE OFFICE CODE	(20)	TOLL- ON FREE ROAD 3
(99)	BORDER BRIDGE STRUCTURE NUMBER	(21)	MAINTAIN- COUNTY HIGHWAY AGENCY 02
	****** STRUCTURE TYPE AND MATERIAL *******	(22)	OWNER- COUNTY HIGHWAY AGENCY 02
(43)	STRUCTURE TYPE MAIN: MATERIAL- CONCRETE	(37)	HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5
	TYPE- SLAB CODE 101		******* CODE
(44)	STRUCTURE TYPE APPR:MATERIAL- OTHER/NA		72
927-034-9 80	TYPE- OTHER/NA CODE 000		DECK 7
(45)	NUMBER OF SPANS IN MAIN UNIT 1		SUPERSTRUCTURE 7
(46)	NUMBER OF APPROACH SPANS 0	National Control	SUBSTRUCTURE 7
(107)	DECK STRUCTURE TYPE- CIP CONCRETE CODE 1		CHANNEL & CHANNEL PROTECTION 8 CULVERTS N
(108)	WEARING SURFACE / PROTECTIVE SYSTEM:	(62)	CULVERTS
A)	TYPE OF WEARING SURFACE- BITUMINOUS CODE 6		****** LOAD RATING AND POSTING ****** CODE
	TYPE OF MEMBRANE- NONE CODE 0	(31)	DESIGN LOAD- UNKNOWN 0
C)	TYPE OF DECK PROTECTION- NONE CODE 0	(63)	OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0
	******** AGE AND SERVICE *********	(64)	OPERATING RATING- 40.5
28.63(33)1.78(.)	YEAR BUILT 1970	(65)	INVENTORY RATING METHOD- FIELD EVAL/ENG JUL 0
	YEAR RECONSTRUCTED 0000	(66)	INVENTORY RATING- 24.3
(42)	TYPE OF SERVICE: ON- HIGHWAY 1 UNDER- WATERWAY 5	(70)	BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
(28)	UNDER- WATERWAY 5 LANES:ON STRUCTURE 02 UNDER STRUCTURE 00	(41)	STRUCTURE OPEN, POSTED OR CLOSED- A
	AVERAGE DAILY TRAFFIC 2000		DESCRIPTION- OPEN, NO RESTRICTION
	YEAR OF ADT 2009 (109) TRUCK ADT 1 %		********* APPRAISAL ********* CODE
	BYPASS, DETOUR LENGTH 199 KM	(67)	STRUCTURAL EVALUATION 6
(12)	******** GEOMETRIC DATA *********		DECK GEOMETRY 4
(40)	LENGTH OF MAXIMUM SPAN 6.1 M	(69)	UNDERCLEARANCES, VERTICAL & HORIZONTAL N
	STRUCTURE LENGTH 14.0 M	(71)	WATER ADEQUACY 9
A	CURB OR SIDEWALK: LEFT 0.0 M RIGHT 0.0 M	(72)	APPROACH ROADWAY ALIGNMENT 8
	BRIDGE ROADWAY WIDTH CURB TO CURB 7.3 M	(36)	TRAFFIC SAFETY FEATURES 0000
	DECK WIDTH OUT TO OUT 8.2 M	(113)	SCOUR CRITICAL BRIDGES 8
	APPROACH ROADWAY WIDTH (W/SHOULDERS) 8.2 M		****** PROPOSED IMPROVEMENTS *******
	BRIDGE MEDIAN O	(75)	TYPE OF WORK- CODE
	SKEW 59 DEG (35) STRUCTURE FLARED NO		LENGTH OF STRUCTURE IMPROVEMENT M
C. (1) (1) (1) (1)	INVENTORY ROUTE MIN VERT CLEAR 99.99 M		BRIDGE IMPROVEMENT COST
	INVENTORY ROUTE TOTAL HORIZ CLEAR 7.3 M	1/2504(28/36/5)	ROADWAY IMPROVEMENT COST
(53)	MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M		TOTAL PROJECT COST
(54)	MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M		YEAR OF IMPROVEMENT COST ESTIMATE
	MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M		FUTURE ADT 4204
(56)	MIN LAT UNDERCLEAR LT 0.0 M		YEAR OF FUTURE ADT 2035
	*********** NAVIGATION DATA **********		
(38)	NAVIGATION CONTROL- NOT APPLICABLE CODE N	/001	**************************************
	PIER PROTECTION- CODE		INSPECTION DATE 12/15 (91) FREQUENCY 24 MO CRITICAL FEATURE INSPECTION: (93) CFI DATE
(39)	NAVIGATION VERTICAL CLEARANCE 0.0 M		FRACTURE CRIT DETAIL- NO MO A)
(116)	VERT-LIFT BRIDGE NAV MIN VERT CLEAR M		UNDERWATER INSP- NO MO B)
(40)	NAVIGATION HORIZONTAL CLEARANCE 0.0 M		OTHER SPECIAL INSP- NO MO C)