

DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

Bridge Number : 55C0371

Facility Carried: SEGERSTROM-SLATER

Location : 0.3 MI. W/O HARBOR BLVD.

City

X

Inspection Date : 05/16/2012

Inspection Type

Routine FC Underwater Special Other

Bridge Inspection Report

STRUCTURE NAME: SANTA ANA RIVER CHANNEL

CONSTRUCTION INFORMATION

Year Built : 1974 Year Widened: 1982 Length (m) : 100

Skew (degrees): 13 No. of Joints :

No. of Hinges :

Structure Description: Continuous 5-span CIP/RC T-beam (10 each) with RC pier walls and RC

open end seat abutments, all supported upon concrete piles.

Span Configuration :(W) 16.5 m, 3 @ 21.9 m, 16.5 m (E) c/c

LOAD CAPACITY AND RATINGS

Design Live Load: MS-18 OR HS-20

Inventory Rating: 59 Operating Rating: 98.2

Posting Load

metric tonnes metric tonnes

Calculation Method: LOAD FACTOR Calculation Method: LOAD FACTOR

Permit Rating : PPPPP

: Type 3: Legal

Type 3S2: Legal

Type 3-3:Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.1 m br, 1.5 m sw, 19.5 m, 1.5 m sw, 0.1 m br (N)

Total Width: 23.2 m Net Width: 19.5 m

No. of Lanes: 4

Rail Description: Type 11 (Misc).

Rail Code : 1000

Min. Vertical Clearance: Unimpaired

DESCRIPTION UNDER STRUCTURE

Channel Description: RC trapezoidal.

INSPECTION COMMENTARY

CONDITION OF STRUCTURE

There was 200 mm of water in the deep section of the concrete channel; all elements were

There are 2 spalls (200 mm \times 100 mm \times 20 mm) with exposed rebars at the inside face of south rail 15 m and 21 m from west end and many small spalls at the inside face of both rails.

There are unsealed transverse cracks in the deck that are moderate in size (0.5 - 2 mm) and density (300 mm spacing).

There are few transverse hairline cracks with light white efflorescence in span 2.

Printed on: Tuesday 06/12/2012 12:37 PM 55C0371/AAAG/23747

| ELEMENT INSPECTION RATINGS | | | | | | | | | |
|--------------------------------------|-----|-------|-------|-----------------------------|-------|-------|-------|-------|--|
| Elem | | Total | | Qty in each Condition State | | | | | |
| No. Element Description | Env | Qty | Units | St. 1 | St. 2 | St. 3 | St. 4 | St. 5 | |
| 12 Concrete Deck - Bare | 2 | 2320 | sq.m. | 2320 | 0 | 0 | 0 | 0 | |
| 110 Reinforced Conc Open Girder/Beam | 2 | 1000 | m. | 1000 | 0 | 0 | 0 | 0 | |
| 210 Reinforced Conc Pier Wall | 2 | 96 | m. | 96 | 0 | 0 | 0 | 0 | |
| 215 Reinforced Conc Abutment | 2 | 48 | m. | 48 | 0 | -0 | 0 | 0 | |
| 227 Reinforced Conc Submerged Pile | 2 | 104 | ea. | 104 | 0 | 0 | 0 | 0 | |
| 256 Slope Protection | 2 | 2 | ea. | 2 | 0 | 0 | 0 | 0 | |
| 302 Compression Joint Seal | 2 | 40 | m. | 40 | 0 | 0 | 0 | . 0 | |
| 304 Open Expansion Joint | 2 | 100 | m. | 100 | 0 | 0 | 0 | 0 | |
| 312 Enclosed/Concealed Bearing | 2 | 2 | ea. | 2 | 0 | 0 | 0 | 0 | |
| 335 Other Bridge Railing | 2 | 200 | m. | 200 | 0 | 0 | 0 | 0 | |
| 358 Deck Cracking | 2 | 1 | ea. | 0 | . 0 | 1 | 0 | | |
| 359 Soffit of Concrete Deck or Slab | . 2 | 1 | ea. | 0 | 1 | 0 | 0 | 0 | |

WORK RECOMMENDATIONS

RecDate: 05/16/2012

Action : Railing-Repair

Work By: LOCAL AGENCY

Status : PROPOSED

EstCost:

DistTarget:

EA:

StrTarget: 2 YEARS mm) with exposed rebars at the inside face of south rail 15 m and 21 m from west end and many small spalls at the

Repair the 2 spalls (200 mm x100 mm x 20

inside face of both rails.

RecDate: 06/07/2007

Action : Deck-Methacrylate

Work By: LOCAL AGENCY

Status : PROPOSED.

EstCost:

StrTarget: 2 YEARS

DistTarget:

Seal the deck with methacrylate.

Inspected By : MT.Zaarour/A.Shenouda

Mikhael T. Zaarour (Registered Civil Engineer)



STRUCTURE INVENTORY AND APPRAISAL REPORT

| (1 | ************************************** | | ************************************** |
|-------|--|-------------------|--|
| | STATE NAME- CALIFORNIA 069 STRUCTURE NUMBER 55C0371 | | STATUS |
| | STRUCTURE NUMBER 55C0371 INVENTORY ROUTE(ON/UNDER) - ON 1400M0290 | | HEALTH INDEX 100.0 |
| | HIGHWAY AGENCY DISTRICT 12 | | PAINT CONDITION INDEX = N/A |
| | | | ******** CLASSIFICATION ************************************ |
| | COUNTY CODE 059 (4) PLACE CODE 00000 FEATURE INTERSECTED- SANTA ANA RIVER CHANNEL | (112) | NIDIO DDIDOR I PNOMI |
| | | | HICHMAN CACKEM NOW ON MAG |
| | FACILITY CARRIED- SEGERSTROM-SLATER LOCATION- 0.3 MI. W/O HARBOR BLVD. | | FUNCTIONAL CLASS- MINOR ARTERIAL URBAN 16 |
| | MILEPOINT/KILOMETERPOINT 0 | | DEFENSE HIGHWAY- NOT STRAHNET 0 |
| | | | DADALLEL CODUCTUE |
| | LRS INVENTORY ROUTE & SUBROUTE | | DIRECTION OF TRAFFIC- 2 WAY 2 |
| | | | TEMPORARY STRUCTURE- |
| | 33 223 12 1111 32.3 526 | | DED TANDA WAY WAS ADDITED BY |
| 777 | LONGITUDE 117 DEG 55 MIN 32 SEC | | DEGLEMATED MATERIAL METHODA |
| | BORDER BRIDGE STATE CODE % SHARE % | | TOLL- ON FREE ROAD 3 |
| (99) | BORDER BRIDGE STRUCTURE NUMBER | | MAINTAIN- COUNTY HIGHWAY AGENCY 02 |
| | ****** STRUCTURE TYPE AND MATERIAL ****** | | OWNER- COUNTY HIGHWAY AGENCY 02 |
| (43) | STRUCTURE TYPE MAIN: MATERIAL- CONCRETE CONT | | HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5 |
| | TYPE- TEE BEAM CODE 204 | | ************************************** |
| (44) | STRUCTURE TYPE APPR:MATERIAL- OTHER/NA | | ********** CONDITION ********** CODE |
| | TYPE- OTHER/NA CODE 000 | | DECK 5 |
| | NUMBER OF SPANS IN MAIN UNIT 5 | | SUPERSTRUCTURE 7 |
| (46) | NUMBER OF APPROACH SPANS 0 | | SUBSTRUCTURE 7 |
| (107) | DECK STRUCTURE TYPE- CIP CONCRETE CODE 1 | | CHANNEL & CHANNEL PROTECTION 9 |
| (108) | WEARING SURFACE / PROTECTIVE SYSTEM: | (62) | CULVERTS |
| | TYPE OF WEARING SURFACE- NONE CODE 0 | | ****** LOAD RATING AND POSTING ****** CODE |
| | TYPE OF MEMBRANE- NONE CODE 0 | (31) | DESIGN LOAD- MS-18 OR HS-20 5 |
| () | TYPE OF DECK PROTECTION- NONE CODE 0 | (63) | OPERATING RATING METHOD- LOAD FACTOR 1 |
| | ******* AGE AND SERVICE ********* | | OPERATING RATING- 98.2 |
| (27) | YEAR BUILT 1974 | (65) | INVENTORY RATING METHOD- LOAD FACTOR 1 |
| | YEAR RECONSTRUCTED 1982 | (66) | INVENTORY RATING- 59 |
| (42) | TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5 | (70) | BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5 |
| (28) | UNDER- WATERWAY 5 LANES:ON STRUCTURE 04 UNDER STRUCTURE 00 | (41) | STRUCTURE OPEN, POSTED OR CLOSED- A |
| | AVERAGE DAILY TRAFFIC 30000 | | DESCRIPTION- OPEN, NO RESTRICTION |
| | YEAR OF ADT 2012 (109) TRUCK ADT 1 % | | ******* APPRAISAL ********* CODE |
| | BYPASS, DETOUR LENGTH 2 KM | | CTDICTIDAL DVALUATION |
| (=-/ | | | DECK GEOMETRY 7 |
| (40) | ********* GEOMETRIC DATA ********************************** | | UNDERCLEARANCES, VERTICAL & HORIZONTAL N |
| | LENGTH OF MAXIMUM SPAN 21.9 M | | WATER ADEQUACY 9 |
| | STRUCTURE LENGTH 100.0 M CURB OR SIDEWALK: LEFT 1.5 M RIGHT 1.5 M | | APPROACH ROADWAY ALIGNMENT 8 |
| | CURB OR SIDEWALK: LEFT 1.5 M RIGHT 1.5 M BRIDGE ROADWAY WIDTH CURB TO CURB 19.5 M | | TRAFFIC SAFETY FEATURES 1000 |
| | DECK WIDTH OUT TO OUT 23.2 M | | SCOUR CRITICAL BRIDGES 8 |
| | APPROACH ROADWAY WIDTH (W/SHOULDERS) 20.1 M | | ****** PROPOSED IMPROVEMENTS ******* |
| | BRIDGE MEDIAN- NO MEDIAN 0 | /25\ | |
| | SKEW 13 DEG (35) STRUCTURE FLARED NO | | TYPE OF WORK- CODE |
| | INVENTORY ROUTE MIN VERT CLEAR 99.99 M | | LENGTH OF STRUCTURE IMPROVEMENT M |
| | INVENTORY ROUTE TOTAL HORIZ CLEAR 19.5 M | | BRIDGE IMPROVEMENT COST |
| | MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M | | ROADWAY IMPROVEMENT COST |
| | MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M | | TOTAL PROJECT COST |
| | MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M | | YEAR OF IMPROVEMENT COST ESTIMATE |
| | MIN LAT UNDERCLEAR LT 0.0 M | (2006)2003 (2006) | FUTURE ADT 47242 |
| | *********** NAVIGATION DATA ********* | | YEAR OF FUTURE ADT 2029 |
| | NAVIGATION CONTROL- NOT APPLICABLE CODE N | | ************************************** |
| | PIER PROTECTION- CODE | | INSPECTION DATE 05/12 (91) FREQUENCY 24 MO |
| | NAVIGATION VERTICAL CLEARANCE 0.0 M | | CRITICAL FEATURE INSPECTION: (93) CFI DATE |
| | VERT-LIFT BRIDGE NAV MIN VERT CLEAR M | | FRACTURE CRIT DETAIL- NO MO A) |
| (40) | NAVIGATION HORIZONTAL CLEARANCE 0.0 M | | UNDERWATER INSP- NO MO B) OTHER SPECIAL INSP- NO MO C) |
| | | C) | OTHER DIBOTAL TROP- NO MO C) |