

DEPARTMENT OF TRANSPORTATION

Structure Maintenance & Investigations

Bridge Number : 55C0606

Facility Carried: OSO PARKWAY

Location : 0.6 MI E/O FELIPE ROAD

City

Inspection Date: 02/10/2013

Inspection Type

Bridge Inspection Report

Routine FC Underwater Special Other

X

STRUCTURE NAME: ARROYO TRABUCO

CONSTRUCTION INFORMATION

Year Built : 1991 Year Widened: N/A Length (m) : 202.7

Skew (degrees): 99 No. of Joints : No. of Hinges :

Structure Description: Continuous 5 span CIP/PS concrete box girder (11 cells) with RC 2-

column bents and RC open end seat abutments, all supported upon

concrete piles (Abutment 1 has steel piles).

Span Configuration : (W) 45.7 m, 3 @ 36.6 m, 45.7 m (E) c/c

LOAD CAPACITY AND RATINGS

Design Live Load: MS-18+MOD OR HS-20+MOD

Inventory Rating: RF=1.00 =>32.4 metric tons Operating Rating: RF=1.67 =>54.1 metric tons

Calculation Method: FIELD EVAL/ENG JUDGMENT Calculation Method: FIELD EVAL/ENG JUDGMENT

Permit Rating : PPPPP

Posting Load : Type 3: Legal

Type 3S2: Legal

Type 3-3:Legal

DESCRIPTION ON STRUCTURE

Deck X-Section: (S) 0.3 m br, 1.5 m sw, 13.4 m, 1.2 m cu med, 13.4 m, 1.5 m sw, 0.3 m br (N)

Total Width:

31.7 m

Net Width: 26.8 m

No. of Lanes: 6

Speed: 55 mph

Min. Vertical Clearance: Unimpaired

Rail Code: 0110

Rail Type Location Length (ft) Rail Modifications Type 26 Right/Left 1410

DESCRIPTION UNDER STRUCTURE

Channel Description: Natural earth open wash with a cobbled streambed.

INSPECTION COMMENTARY

REVISIONS

Element 104 (P/S Concrete Closed Box Girder): The quantities were modified as follows: from [St. 1 = 198, St. 2 = 5] to [St. 1 = 196, St. 2 = 7].

Element 302 (Compression Joint Seal): a quantity of 20 m was moved to St. 2.

The concrete deck cracks were sealed with methacrylate, so smart flag 358 (deck cracking) was modified from St. 3 to St. 1.

CONDITION OF STRUCTURE

There are 20 mm vertical offset in the concrete railings at the east abutment.

JOINTS

The compression joint seal above the west abutment was failed and worn out in many

Printed on: Monday

03/18/2013

03:32 PM

55C0606/AAAI/25488

INSPECTION COMMENTARY

locations.

DECK

The deck cracks were sealed with methacrylate.

SUPERSTRUCTURE

There are 5 cracks 1 mm width and +/- 1.0 m long in the soffit of the box girder at the south side in span #5; and one crack at span 3 and 4.

There is water dripping from the soffit vent hole in south side of span # 1.

SAFE LOAD CAPACITY

A Load Rating Summary Sheet is included with this bridge inspection report. The current rating has been assigned in accordance with SMI procedures.

CHANNEL/WATERWAY INVESTIGATION

There is 500 mm deep water in span 4, all substructure elements were inspected.

ELEMENT INSPECTION RATINGS								
Elem No. Element Description	Env	Total Qty	'Units	Qt St. 1	y in eac St. 2	ch Condi	tion Sta	te St. 5
12 Concrete Deck - Bare	2	6380	sq.m.	0	6380	0	0	0
104 P/S Conc Closed Web/Box Girder	2	203	m.	196	7	-0	0	*
205 Reinforced Conc Column or Pile Extension	2	8	ea.	8	0	0	0	. 0
215 Reinforced Conc Abutment	2	80	m.	80	0	0	0	0
225 Unpainted Steel Submerged Pile	2	1	ea.	1	0	0	0	0
227 Reinforced Conc Submerged Pile	2	1	ea.	1	0	0	0	0
300 Strip Seal Expansion Joint	2	80	m.	80	0	0	0	0
302 Compression Joint Seal	2	40	m.	20	20	0		
312 Enclosed/Concealed Bearing	2	1	ea.	1	0	0	0	0
321 Reinforced Conc Approach Slab w/ or w/o AC Ovly	2	12	ea.	12	0	0	0	0
331 Reinforced Conc Bridge Railing	2	430	m.	430	. 0	0	0	0
358 Deck Cracking	2	1	ea.	1	0	0	0	

WORK RECOMMENDATIONS

RecDate: 02/22/2011

EstCost:

The city should investigate the dripping

Action : Drainage Issue

StrTarget: 2 YEARS water through the bridge cell. DistTarget:

Work By: LOCAL AGENCY

EA:

Status : PROPOSED

Printed on: Monday

03/18/2013 03:32 PM

Ashraf Shenouda Team Leader :

Report Author : Ashraf Shenouda

Inspected By : A.Shenouda/KD.Henderson

Ashraf Shenouda (Registered Civil Engineer)

(Date)



STRUCTURE INVENTORY AND APPRAISAL REPORT

	**************************************			**************************************
(1	STATE NAME- CALIFORNIA 069			
	STRUCTURE NUMBER 55C0606			STATUS
(5)	INVENTORY ROUTE (ON/UNDER) - ON 140000000			HEALTH INDEX 87.3
	HIGHWAY AGENCY DISTRICT 12			PAINT CONDITION INDEX = N/A
(3)	COUNTY CODE 059 (4) PLACE CODE 00000			******* CLASSIFICATION ******** CODE
(6)	FEATURE INTERSECTED- ARROYO TRABUCO		100	NBIS BRIDGE LENGTH- YES Y
(7)	FACILITY CARRIED- OSO PARKWAY		(104)	HIGHWAY SYSTEM- ROUTE ON NHS 1
(9)	LOCATION- 0.6 MI E/O FELIPE ROAD		(26)	FUNCTIONAL CLASS- OTHER PRIN ART URBAN 14
(11)	MILEPOINT/KILOMETERPOINT 0		(100)	DEFENSE HIGHWAY- NOT STRAHNET 0
(12)	BASE HIGHWAY NETWORK- PART OF NET 1		(101)	PARALLEL STRUCTURE- NONE EXISTS N
	LRS INVENTORY ROUTE & SUBROUTE 00000000000		(102)	DIRECTION OF TRAFFIC- 2 WAY 2
0.000	LATITUDE 33 DEG 35 MIN 06 SEC		(103)	TEMPORARY STRUCTURE-
	LONGITUDE 117 DEG 38 MIN 09 SEC		(105)	FED.LANDS HWY- NOT APPLICABLE 0
2.000000000	BORDER BRIDGE STATE CODE % SHARE %		(110)	DESIGNATED NATIONAL NETWORK - NOT ON NET 0
	BONDEN BRIDGE BINIE CODE			TOLL- ON FREE ROAD 3
(99)	BORDER BRIDGE STRUCTURE NUMBER			MAINTAIN- COUNTY HIGHWAY AGENCY 02
	****** STRUCTURE TYPE AND MATERIAL *******			OWNER- COUNTY HIGHWAY AGENCY 02
(43)	STRUCTURE TYPE MAIN: MATERIAL- PRSTR CONC CONT			HISTORICAL SIGNIFICANCE- NOT ELIGIBLE 5
	TYPE- BOX BEAM OR GIRDER - MULTI CODE 605			
(44)	STRUCTURE TYPE APPR:MATERIAL- OTHER/NA			********** CONDITION ********** CODE
	TYPE- OTHER/NA CODE 000		(58)	DECK 6
(45)	NUMBER OF SPANS IN MAIN UNIT 5		(59)	SUPERSTRUCTURE 7
(46)	NUMBER OF APPROACH SPANS 0		(60)	SUBSTRUCTURE 7
(107)	DECK STRUCTURE TYPE- CIP CONCRETE CODE 1		7.000	CHANNEL & CHANNEL PROTECTION 9
	WEARING SURFACE / PROTECTIVE SYSTEM:		(62)	CULVERTS
	TYPE OF WEARING SURFACE- NONE CODE O			****** LOAD RATING AND POSTING ****** CODE
B)	TYPE OF MEMBRANE- NONE CODE O		(31)	DESIGN LOAD- MS-18+MOD OR HS-20+MOD 6
C)	TYPE OF DECK PROTECTION- NONE CODE 0			
	******* AGE AND SERVICE *********			OPERATING RATING METHOD- FIELD EVAL/ENG JUD 0 OPERATING RATING- 54.1
(27)	YEAR BUILT 1991	9.2		INVENTORY RATING METHOD- FIELD EVAL/ENG JUL 0
	YEAR RECONSTRUCTED 0000			INVENTORY RATING METHOD FIELD EVALVENG SOL U
of 100 to 100 for	TYPE OF SERVICE: ON- HIGHWAY-PEDESTRIAN 5			
,,	UNDER- WATERWAY 5			BRIDGE POSTING- EQUAL TO OR ABOVE LEGAL LOADS 5
(28)	LANES: ON STRUCTURE 06 UNDER STRUCTURE 00		(41)	STRUCTURE OPEN, POSTED OR CLOSED- A
(29)	AVERAGE DAILY TRAFFIC 27000			DESCRIPTION- OPEN, NO RESTRICTION
(30)	YEAR OF ADT 2003 (109) TRUCK ADT 1 %			******** APPRAISAL ********* CODE
(19)	BYPASS, DETOUR LENGTH 11 KM		(67)	STRUCTURAL EVALUATION 7
	**************************************		(68)	DECK GEOMETRY 7
(48)	LENGTH OF MAXIMUM SPAN 45.7 M		(69)	UNDERCLEARANCES, VERTICAL & HORIZONTAL N
	NAMES OF THE PROPERTY OF THE PARTY OF THE PA		(71)	WATER ADEQUACY 9
	STRUCTURE LENGTH 202.7 M CURB OR SIDEWALK: LEFT 1.5 M RIGHT 1.5 M		(72)	APPROACH ROADWAY ALIGNMENT 8
	BRIDGE ROADWAY WIDTH CURB TO CURB 26.8 M		(36)	TRAFFIC SAFETY FEATURES 0110
	DECK WIDTH OUT TO OUT 31.7 M		(113)	SCOUR CRITICAL BRIDGES 8
100000000000000000000000000000000000000	APPROACH ROADWAY WIDTH (W/SHOULDERS) 26.8 M			******* PROPOSED IMPROVEMENTS *******
	BRIDGE MEDIAN- CLOSED NON-MOUNTABLE 3		(75)	
	SKEW 99 DEG (35) STRUCTURE FLARED NO			TYPE OF WORK- CODE
	A CONTROL OF THE CONT			LENGTH OF STRUCTURE IMPROVEMENT M
	INVENTORY ROUTE MIN VERT CLEAR 99.99 M			BRIDGE IMPROVEMENT COST
	INVENTORY ROUTE TOTAL HORIZ CLEAR 13.4 M MIN VERT CLEAR OVER BRIDGE RDWY 99.99 M			ROADWAY IMPROVEMENT COST
	MIN VERT UNDERCLEAR REF- NOT H/RR 0.00 M		10000000000	TOTAL PROJECT COST
	MIN LAT UNDERCLEAR RT REF- NOT H/RR 0.0 M			YEAR OF IMPROVEMENT COST ESTIMATE
	MIN LAT UNDERCLEAR LT 0.0 M			FUTURE ADT 56200
	************ NAVIGATION DATA *********		(115)	YEAR OF FUTURE ADT 2035

	NAVIGATION CONTROL- NOT APPLICABLE CODE N		(90)	INSPECTION DATE 02/13 (91) FREQUENCY 24 MO
	PIER PROTECTION- CODE		(92)	CRITICAL FEATURE INSPECTION: (93) CFI DATE
	NAVIGATION VERTICAL CLEARANCE 0.0 M		A)	FRACTURE CRIT DETAIL- NO MO A)
	VERT-LIFT BRIDGE NAV MIN VERT CLEAR M NAVIGATION HORIZONTAL CLEARANCE 0.0 M		B)	UNDERWATER INSP- NO MO B)
(30)	U.U M		C)	OTHER SPECIAL INSP- NO MO C)