

Parcel ID Number

Google Street View Link

## **Access Compliance Report Public Rights-of-Way** (Island Curb Cuts)



Main Street: O\_NEILL\_DR Cross Street:O\_NEILL\_DR Location:

ADA ID: CCRK211102131219 Curb Cut Type: MedianRefuge2 Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 15

## **Codes/Mitigation Info/Possible Solution**



Possible Solutions: Remove & Replace Entire Refuge.

Surveyor Notes:

N/A

OC Std/PROW:

R302.6, STD 1115

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33

•	\$ 5000	Total Cost:			
	O_NEILL_DR	Street 1 Name	741-141-49		
ľ	N/A	Stop Condition-Street 1			
l	O_NEILL_DR	Street 2 Name			
l	N/A	Stop Condition-Street 2			
١	kviewpoint=33.55459934,-117.6453262				

## **Obstruction and Utility Measurement/Component Compliance**

Compliance Description	Data Co	mpliance Description	Data
Yes Obstructions Present?	No N/A	Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance								
	Com	pliance Description	Data	Com	pliance Description	Data		
	Yes	Refuge 1 Length (In)	75	N/A	Guttter 1 Ponding	N/A		
	Yes	Refuge 1 Width (In)	96	Yes	Gutter 1 Lip Ht (In)	0		
	Yes	Refuge 1 Slope (%)	3.3	N/A	Gutter 1 Slope (%)	N/A		
	Yes	Refuge 1 Cross Slope (%)	2.3	N/A	Gutter 1 Cross Slope (%)	N/A		
	N/A	Painted Cross Walk 1	Yes	N/A	DWS 1 Provided	N/A		
		Cross Walk 1 Direction	Е	N/A	DWS 1 Contrast	N/A		
		Cross Walk 1 Width (In)	144	N/A	DWS 1 Length (In)	N/A		
	Yes	Refuge Inside Cross Walk 1	Yes	N/A	DWS 1 Full Width	N/A		
		Road 1 Slope (%)	1.5	N/A	DWS 1 Offset (In)	N/A		
		Road 1 Cross Slope (%)	2.8			N/A		
	Yes	Refuge 2 Length (In)	134	N/A	Guttter 2 Ponding	N/A		
	Yes	Refuge 2 Width (In)	96	Yes	Gutter 2 Lip Ht (In)	0		
	Yes	Refuge 2 Slope (%)	3.3	N/A	Gutter 2 Slope (%)	N/A		
	No	Refuge 2 Cross Slope (%)	5.3	N/A	Gutter 2 Cross Slope (%)	N/A		
)	N/A	Painted Cross Walk 2	Yes	N/A	DWS 2 Provided	N/A		
		Cross Walk 2 Direction	W	N/A	DWS 2 Contrast	N/A		
2		Cross Walk 2 Width (In)	144	N/A	DWS 2 Length (In)	N/A		
١.	Yes	Refuge Inside Cross Walk 2	Yes	N/A	DWS 2 Full Width	N/A		
2		Road 2 Slope (%)	1.9	N/A	DWS 2 Offset (In)	N/A		
١.		Road 2 Cross Slope (%)	3.4					
	Yes	Overall Surface Condition: Acce	ptable					
			Į.	•				