

Access Compliance Report Public Rights-of-Way (Island Curb Cuts)



15

Main Street: REATA_RD Cross Street: REATA_RD Location:

ADA ID: CCRK211118133317 Curb Cut Type: MedianRefuge2

Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Install Detectable Warning System. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R305, R304.5.3, STD 1115

Total Cost:

\$ 1704

Parcel ID Number	741-59

Google Street View Link

 91-30
 Street 1 Name
 REATA_RD

 Stop Condition-Street 1
 N/A

 Street 2 Name
 REATA_RD

Stop Condition-Street 2

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.52260655,-117.62711803}$

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	pliance	Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities	Present?	No
	Obstruction Types	N/A		Utility T	ypes	
	Obstruction Dimensions	N/A				N/A



Field Measurements/Component Compliance							
	Com	pliance Description	Data	Com	pliance Description	Data	
	Yes	Refuge 1 Length (In)	125	Yes	Guttter 1 Ponding	No	
	Yes	Refuge 1 Width (In)	96	Yes	Gutter 1 Lip Ht (In)	0	
	Yes	Refuge 1 Slope (%)	1.1	Yes	Gutter 1 Slope (%)	2	
	Yes	Refuge 1 Cross Slope (%)	2.4	No	Gutter 1 Cross Slope (%)	2.3	
	N/A	Painted Cross Walk 1	Yes	No	DWS 1 Provided	No	
		Cross Walk 1 Direction	W	N/A	DWS 1 Contrast	N/A	
		Cross Walk 1 Width (In)	145	N/A	DWS 1 Length (In)	N/A	
	Yes	Refuge Inside Cross Walk 1	Yes	N/A	DWS 1 Full Width	N/A	
		Road 1 Slope (%)	2.1	N/A	DWS 1 Offset (In)	N/A	
		Road 1 Cross Slope (%)	3.3			N/A	
	Yes	Refuge 2 Length (In)	125	Yes	Guttter 2 Ponding	No	
	Yes	Refuge 2 Width (In)	96	Yes	Gutter 2 Lip Ht (In)	0	
	Yes	Refuge 2 Slope (%)	0.2	Yes	Gutter 2 Slope (%)	2	
	Yes	Refuge 2 Cross Slope (%)	2.4	No	Gutter 2 Cross Slope (%)	3.7	
1704	N/A	Painted Cross Walk 2	Yes	No	DWS 2 Provided	No	
		Cross Walk 2 Direction	Ε	N/A	DWS 2 Contrast	N/A	
A_RD		Cross Walk 2 Width (In)	144	N/A	DWS 2 Length (In)	N/A	
N/A	Yes	Refuge Inside Cross Walk 2	Yes	N/A	DWS 2 Full Width	N/A	
A_RD		Road 2 Slope (%)	3.8	N/A	DWS 2 Offset (In)	N/A	
N/A		Road 2 Cross Slope (%)	2.9				
	Yes	Overall Surface Condition: Acce	ptable				
			1				