

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: CLUB TERRACE DR Cross Street: YORBA_LINDA_BLVD Location: SW

ADA ID: RPAT210923082118 Ramp Type: Type 4 - Parallel **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 0

Codes/Mitigation Info/Possible Solution

Codes/Mitigation into	Possible Solution
	Possible Solutions:
	Remove & Replac
YORBA_LINDA_BLYD	
	Surveyor Notes:
E E	N/A
	OC Std/PROW:
	R304.2.2, STD 111
	Total Cost:

Remove & Replace Curb Slope.

R304.2.2, STD 1115

252

Parcel ID Number 348-051-01 Ramp Island Or Median None Ramp Orientation NonDiag Google Street View Link:

Street 1 Name CLUB_TERRACE_DR Stop Condition-Street 1 StopSign Street 2 Name YORBA_LINDA_BLVD Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.88852424,-117.8001483

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Desc	cription Data
Yes Obstructions Present?	No N/A Utilities Prese	nt? No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance									
- 1	Compliance Description		Data	Compliance Description		Description	Data		
	N/A	Ramp Length LT (in)	101	N/A	Ramp L	ength RT (in)	91		
	Yes	Ramp Width LT (in)	53	Yes	Ramp V	Vidth RT (in)	53		
	Yes	Ramp Run Slope LT (%)	6.9	Yes	Ramp R	tun Slope RT (%)	6.6		
	Yes	Ramp Cross Slope LT (%)	0.8	Yes	Ramp C	cross Slope RT (%)	0.9		
	N/A	Landing Present	Yes	Yes	DWS Pr	rovided	Yes		
	N/A	Landing Length (in)	54	Yes	DWS C	ontrast	Yes		
	Yes	Landing Width (in)	60	Yes	DWS Le	ength (in)	36		
	Yes	Landing Run Slope (%)	1.2	Yes	DWS Fu	ıll Width	Yes		
	Yes	Landing Cross Slope (%)	0.6		DWS O	ffset Type	Single		
	N/A	Landing Movement Obstructed?	No	Yes	DWS O	ffset Left (in)	0		
		Landing Movement Type	Curb	Yes	DWS O	ffset Right (in)	N/A		
	N/A	Landing Shared	No						
	N/A	Clear Space	N/A						
	N/A	Clear Space To Crosswalk (in)	N/A						
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	N/A		
		Crossing 1 Direction	Е		Crossin	g 2 Direction	N/A		
R		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
n	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Ir	nside Crosswalk 2	N/A		
D		Crossing 1 Slope (%)	3.2		Crossin	g 2 Slope (%)	N/A		
Α		Crossing 1 Cross Slope (%)	3.2		Crossin	g 2 Cross Slope (%)	N/A		
	Yes	Gutter Ponding	No	No	Curb Slo	оре	10.1		
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	N/A		
_	Yes	Gutter Run Slope (%)	4		Road C	ross Slope (%)	N/A		
<u>а</u>	Yes	Gutter Cross Slope (%)	1.4	Yes	Perpend	dicular Joint Present	Yes		
0	Yes	Overall Surface Condition Accep	otable						
		Cross Gutter Present?	No		Spandr	el Present?	No		
Α		Replace Cross Gutter?	N/A		Replace	e Spandrel?	N/A		