

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A **Cross Street: ESPERANZA RD** Location: NW

ADA ID: RPAT210923134822 Ramp Type:Type 1 - Perpendicular **Initial Pass/Fail: Pass**

Overall Compliance: No

Severity Score:

Codes/Mitigation Info/Possible Solution



Remove & Replace Entire Ramp. Remove & Replace Gutter.

Surveyor Notes:

Possible Solutions:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R304.5.4, STD 1115

Total Cost:

3332

Parcel ID Number	349-693-38
Ramp Island Or Median	None
Ramp Orientation	NonDiag
Google Street View Link:	

Street 1 Name N/A Stop Condition-Street 1 Signal Street 2 Name ESPERANZA_RD Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.8628304,-117.7900008

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	oliance Description	Data
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	l		N/A



Field Measurements/Component Compliance								
	Compliance Description		Data	Com	pliance Description	Data		
	N/A	Ramp Length (in)	68	N/A	Flare Type LT			
	Yes	Ramp Width (in)	49			Sloped		
	Yes	Ramp Run Slope (%)	8.1	Yes	Flare Slope LT (%)	6		
	Yes	Ramp Cross Slope (%)	0.2	N/A	Flare Traversable LT	Yes		
	N/A	Landing Present	Yes	N/A	Flare Type RT			
	N/A	Landing Length (in)	46			Sloped		
	Yes	Landing Width (in)	50	Yes	Flare Slope RT (%)	7.6		
	Yes	Landing Run Slope (%)	1.9	N/A	Flare Traversable RT	Yes		
	Yes	Landing Cross Slope (%)	1	Yes	DWS Provided	Yes		
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Contrast	Yes		
		Landing Moveme stgliyalepost and	curb	Yes	DWS Length (in)	36		
	N/A	Landing Shared	No	Yes	DWS Full Width	Yes		
	N/A	Clear Space	N/A	Yes	DWS Offset Left (in)	0		
	N/A	Clear Space To Crosswalk (in)	N/A	Yes	DWS Offset Right (in)	N/A		
2	N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A		
		Crossing 1 Direction	Е		Crossing 2 Direction	N/A		
Α		Marked Crosswalk 1 Width (in)	120		Marked Crosswalk 2 Width (in)	N/A		
al	Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	N/A		
D		Crossing 1 Slope (%)	1.1		Crossing 2 Slope (%)	N/A		
Α		Crossing 1 Cross Slope (%)	1.4		Crossing 2 Cross Slope (%)	N/A		
	Yes	Gutter Ponding	No	No	Curb Slope	5.6		
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A		
	No	Gutter Run Slope (%)	6.5		Road Cross Slope (%)	N/A		
<u>а</u> о	Yes	Gutter Cross Slope (%)	1.5					
	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joint Present	Yes		
		Cross Gutter Present?	No		Spandrel Present?	No		
Α		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A		
	1							