

Obstruction Types

Obstruction Dimensions

Access Compliance Report Public Rights-of-Way (Curb Ramps)



No

N/A

Main Street: S_ESPLANADE_ST	Cross Street: E_VINE_ST	Location:	NE
ADA ID DDATO40000445000	 Lateral Dana (Fatta Dana)	 	

Overall Compliance: No ADA ID: RPAT210927115008 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Pass Severity Score: **Codes/Mitigation Info/Possible Solution** Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data Ramp Length RT (in) Remove & Replace Gutter. N/A Ramp Length LT (in) 119 72 Ramp Width LT (in) Ramp Width RT (in) 48 48 Ramp Run Slope RT (%) Ramp Run Slope LT (%) 7.3 4.9 Ramp Cross Slope LT (%) Ramp Cross Slope RT (%) 0.6 1.2 Landing Present Yes DWS Provided Yes Survevor Notes: **DWS Contrast** Landing Length (in) 48 Yes 36 N/A Landing Width (in) 48 DWS Length (in) Landing Run Slope (%) Yes DWS Full Width Yes 0.7 Landing Cross Slope (%) 2 **DWS Offset Type** Single N/A Landing Movement Obstructed? No Yes DWS Offset Left (in) OC Std/PROW: Curb DWS Offset Right (in) N/A Landing Movement Type Landing Shared No R304.5.3, STD 1115 Clear Space Yes Clear Space To Crosswalk (in) 48 Total Cost: 252 Marked Crosswalk 1 No Marked Crosswalk 2 No Crossing 1 Direction w Crossing 2 Direction S Parcel ID Number 093-101-32 Street 1 Name S ESPLANADE ST N/A Marked Crosswalk 1 Width (in) Marked Crosswalk 2 Width (in) N/A Ramp Island Or Median None Stop Condition-Street 1 NoControl N/A Ramp Inside Crosswalk 1 N/A Ramp Inside Crosswalk 2 N/A Diag Street 2 Name E VINE ST 4.5 1.5 Ramp Orientation Crossing 1 Slope (%) Crossing 2 Slope (%) Google Street View Link: Stop Condition-Street 2 StopSign Crossing 1 Cross Slope (%) 3 Crossing 2 Cross Slope (%) 4.5 Yes Gutter Ponding Yes Curb Slope 3.8 http://www.google.com/maps/@?api=1&map action=pano&viewpoint=33.79057327,-117.80944973 No Gutter Lip Height (in) 0 Road Run Slope (%) 1.4 **Obstruction and Utility Measurement/Component Compliance** Gutter Run Slope (%) 4.7 5.4 Road Cross Slope (%) Compliance Description Data Compliance Description Data Gutter Cross Slope (%) 2.4 Perpendicular Joint Present Yes Obstructions Present? **Utilities Present?** No No

N/A

Yes Overall Surface Condition Acceptable

No

N/A

Spandrel Present?

Replace Spandrel?

Cross Gutter Present?

Replace Cross Gutter?



N/A

N/A

Utility Types