

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: MALENA_DRCross Street: RAINIER_DRLocation:NEADA ID: RPAT210930120713Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: PassOverall Compliance: NoSeverity Score:20

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Gutter Ponding Observed.

Surveyor Notes:

Unable to collect curb slope due to ponding

OC Std/PROW:

R204.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R302.7, STD 1115

Total Cost: \$ 6412

Parcel ID Number	Street 1 Name
Ramp Island Or Median	Stop Condition-Street 1
Ramp Orientation	Street 2 Name
Google Street View Link:	Stop Condition-Street 2

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.77040819,-117.82356357}$

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance								
Compliance Description		Data	Compliance Description		Data			
Two New	N/A	Ramp Length (in)	122	N/A	Flare Type LT			
utter Ponding	Yes	Ramp Width (in)	48			Sloped		
	Yes	Ramp Run Slope (%)	7	N/A	Flare Slope LT (%)	6.9		
	Yes	Ramp Cross Slope (%)	0.1	N/A	Flare Traversable LT	No		
	N/A	Landing Present	No	N/A	Flare Type RT			
	N/A	Landing Length (in)	N/A			Sloped		
ponding	No	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	5		
	No	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	No		
	No	Landing Cross Slope (%)	N/A	No	DWS Provided	No		
	N/A	Landing Movement Obstructed?	No	N/A	DWS Contrast	N/A		
		Landing Movement Type	N/A	N/A	DWS Length (in)	N/A		
04.3.2-Para,	N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A		
	N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	N/A		
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Offset Right (in)	N/A		
\$ 6412	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No		
		Crossing 1 Direction	W		Crossing 2 Direction	S		
MALENA_DR		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A		
NoControl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A		
RAINIER_DR		Crossing 1 Slope (%)	4.8		Crossing 2 Slope (%)	4.8		
NoControl		Crossing 1 Cross Slope (%)	0.1		Crossing 2 Cross Slope (%)	4		
	No	Gutter Ponding	Yes	N/A	Curb Slope	-9999		
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.3		
	Yes	Gutter Run Slope (%)	4.1		Road Cross Slope (%)	6.2		
Data	Yes	Gutter Cross Slope (%)	8.0					
No	Yes	Overall Surface Condition: Accep	otable	No	Perp Joint Present	No		
		Cross Gutter Present?	No		Spandrel Present?	No		
N/A		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A		