

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: MALENA\_DR Cross Street: WHITNEY\_DR Location: SW

ADA ID: RPAT211001113152 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 22

**Codes/Mitigation Info/Possible Solution** 



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R204.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, STD 1115

Total Cost: \$ 6160

Parcel ID Number 395-202-15 Street 1 Name MALENA\_DR
Ramp Island Or Median None Stop Condition-Street 1 NoControl
Ramp Orientation Diag Street 2 Name WHITNEY\_DR
Google Street View Link: Stop Condition-Street 2 NoControl

 $\underline{http://www.google.com/maps/@?api=1\&map\_action=pano\&viewpoint=33.77110673,-117.82374379}$ 

## **Obstruction and Utility Measurement/Component Compliance**

Com	pliance Description	Data	Com	pliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities	Present?	No
	Obstruction Types	N/A		Utility T	ypes	
	Obstruction Dimensions	N/A	l			N/A



Field Measurements/Component Compliance											
-	Com	Compliance Description		Com	pliance	Description	Data				
	N/A	Ramp Length (in)	129	N/A	Flare Typ	oe LT					
	Yes	Ramp Width (in)	52				Sloped				
	Yes	Ramp Run Slope (%)	7.6	N/A	Flare Slo	pe LT (%)	7.6				
	Yes	Ramp Cross Slope (%)	0.7	N/A	Flare Tra	versable LT	No				
	N/A	Landing Present	No	N/A	Flare Typ	pe RT					
	N/A	Landing Length (in)	N/A				Sloped				
	No	Landing Width (in)	N/A	N/A	Flare Slo	pe RT (%)	12.1				
	No	Landing Run Slope (%)	N/A	N/A	Flare Tra	versable RT	No				
	No	Landing Cross Slope (%)	N/A	No	DWS Pro	ovided	No				
	N/A	Landing Movement Obstructed?	No	N/A	DWS Co	ntrast	N/A				
		Landing Movement Type	N/A	N/A	DWS Lei	ngth (in)	N/A				
	N/A	Landing Shared	N/A	N/A	DWS Fu	ll Width	N/A				
	N/A	Clear Space	Yes	N/A	DWS Off	set Left (in)	N/A				
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Off	set Right (in)	N/A				
)	N/A	Marked Crosswalk 1	No	N/A	Marked (	Crosswalk 2	No				
		Crossing 1 Direction	Е		Crossing	2 Direction	N				
2		Marked Crosswalk 1 Width (in)	N/A		Marked (	Crosswalk 2 Width (in)	N/A				
ı	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In:	side Crosswalk 2	N/A				
۱		Crossing 1 Slope (%)	2.5		Crossing	2 Slope (%)	1.6				
ı		Crossing 1 Cross Slope (%)	1.2		Crossing	2 Cross Slope (%)	1.5				
	Yes	Gutter Ponding	No	No	Curb Slo	рре	9.3				
	Yes	Gutter Lip Height (in)	0		Road Ru	ın Slope (%)	0.4				
	Yes	Gutter Run Slope (%)	1.4		Road Cro	oss Slope (%)	0.9				
•	Yes	Gutter Cross Slope (%)	0.9								
1	Yes	Overall Surface Condition: Accep	ptable	No	Perp Joi	nt Present	No				
		Cross Gutter Present?	Yes		Spandre	Present?	Yes				
١		Replace Cross Gutter?	No		Replace	Spandrel?	No				