

ADA ID: RPAT211019145118

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: EL_CARMEN_AVE Cross Street: S_ESPANITA_ST Location: NW

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No Severity Score:

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Landing. Remove & Replace Gutter. Utility Present.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.1, R304.5.3, STD 1115

Total Cost: \$ 783

Parcel ID Number	093-332-21	Street 1 Name	EL_CARMEN_AVE
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl
Ramp Orientation	Diag	Street 2 Name	S_ESPANITA_ST
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.79728736,-117.80404345

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data	Compliance Description	Data
Yes Obstructions Present?	No	N/A Utilities Present?	Yes
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		Street Sign



Field Measurements/Component Compliance									
	Compliance Description		Data	Compliance Description			Data		
	N/A	Ramp Length (in)	80	N/A	Flare Ty	pe LT			
	Yes	Ramp Width (in)	48				Sloped		
	Yes	Ramp Run Slope (%)	3.4	N/A	Flare Slo	ppe LT (%)	4.5		
	Yes	Ramp Cross Slope (%)	1.3	N/A	Flare Traversable LT		No		
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT			
	N/A	Landing Length (in)	48				Sloped		
	Yes	Landing Width (in)	48	N/A	Flare Slo	ppe RT (%)	7.6		
	Yes	Landing Run Slope (%)	1.2	N/A	Flare Tra	aversable RT	No		
	No	Landing Cross Slope (%)	2.3	Yes	DWS Pr	ovided	Yes		
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Co	ontrast	Yes		
		Landing Movement Type	Curb	Yes	DWS Le	ngth (in)	36		
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes		
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0		
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A		
3	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No		
		Crossing 1 Direction	S		Crossing	2 Direction	E		
E		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
ol	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A		
Т		Crossing 1 Slope (%)	3.9		Crossing	g 2 Slope (%)	1.4		
ol		Crossing 1 Cross Slope (%)	0		Crossing	2 Cross Slope (%)	2		
	Yes	Gutter Ponding	No	Yes	Curb Slo	ppe	4.9		
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	1		
	Yes	Gutter Run Slope (%)	0.3		Road Cr	oss Slope (%)	1.9		
a	No	Gutter Cross Slope (%)	2.8						
S	Yes	es Overall Surface Condition: Acceptable		Yes	Perp Jo	nt Present	Yes		
_		Cross Gutter Present?	Yes		•	I Present?	Yes		
n		Replace Cross Gutter?	No		Replace	Spandrel?	No		