

ADA ID: RPAT211019145717

Access Compliance Report Public Rights-of-Way (Curb Ramps)



NE

6

Main Street: S_ESPANITA_ST Cross Street: E EL CARMEN AVE Location:

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:



IUII	11110/1	Casinie	Solution	
				_

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, STD 1115

Total Cost: 6160

Parcel ID Number	093-331-07	Street 1 Name
Ramp Island Or Median	None	Stop Condition-
Ramp Orientation	Diag	Street 2 Name
Google Street View Link:		Stop Condition-

S ESPANITA ST -Street 1 **NoContro** E_EL_CARMEN_AVE -Street 2 **NoContro**

http://www.google.com/maps/@?api=1&map action=pano&viewpoint=33.79725587,-117.80385526

Obstruction and Utility Measurement/Component Compliance

Compliance Description Data		Compliance Description	Data
Yes Obstructions Present?	No	N/A Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance							
	Com	pliance Description	Data	Com	pliance	Description	Data
	N/A	Ramp Length (in)	72	N/A	Flare Ty	pe LT	
	Yes	Ramp Width (in)	48				Sloped
	Yes	Ramp Run Slope (%)	7.9	N/A	Flare Slo	ppe LT (%)	3.7
	Yes	Ramp Cross Slope (%)	0.9	N/A	Flare Tra	aversable LT	No
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT	
	N/A	Landing Length (in)	45				Sloped
	Yes	Landing Width (in)	48	N/A	Flare Slo	ppe RT (%)	6.2
	Yes	Landing Run Slope (%)	0.5	N/A	Flare Tra	aversable RT	No
	Yes	Landing Cross Slope (%)	0.4	Yes	DWS Pr	ovided	Yes
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Co	ontrast	Yes
		Landing Movement Type	Curb	Yes	DWS Le	ngth (in)	36
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A
60	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No
		Crossing 1 Direction	W		Crossing	2 Direction	S
т		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A
ol	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A
Έ		Crossing 1 Slope (%)	0.4		Crossing	g 2 Slope (%)	3.8
ol		Crossing 1 Cross Slope (%)	0.7		Crossing	g 2 Cross Slope (%)	1.2
	Yes	Gutter Ponding	No	No	Curb Slo	ppe	5.8
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	0.5
	Yes	Gutter Run Slope (%)	4.2		Road Cr	oss Slope (%)	1.6
ta Io	Yes	Gutter Cross Slope (%)	1.1				
10	Yes	Overall Surface Condition: Acce	ptable	Yes	Perp Joi	nt Present	Yes
/Α		Cross Gutter Present?	Yes		Spandre	I Present?	Yes
~		Replace Cross Gutter?	No	l	Replace	Spandrel?	No