

ADA ID: RPAT211020093149

Access Compliance Report Public Rights-of-Way (Curb Ramps)



SW

Main Street: S CHURCH ST **Cross Street: EL CARMEN AVE** Location:

Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

10 **Severity Score:**

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter. Utility Present.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R304.5.4, STD 1115

Total Cost: 6412

Parcel ID Number 093-343-03 Street 1 Name S CHURCH ST Stop Condition-Street 1 Ramp Island Or Median None **NoControl** Ramp Orientation Diag Street 2 Name **EL_CARMEN_AVE** Google Street View Link: Stop Condition-Street 2 **NoControl**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.79713634,-117.80686119

Obstruction and Utility Measurement/Component Compliance

Compliance Description Data		Compliance Description	<u>Data</u>	
Yes	Obstructions Present?	No	N/A Utilities Present?	Yes
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		Street Light



Field Measurements/Component Compliance											
- 1	Com	pliance Description	Data	ta Compliance Description							
	N/A	Ramp Length (in)	67	N/A	Flare Ty	pe LT					
	Yes	Ramp Width (in)	48				Sloped				
	Yes	Ramp Run Slope (%)	6.6	N/A	Flare Slo	ppe LT (%)	5.6				
	Yes	Ramp Cross Slope (%)	0.8	N/A	Flare Tra	aversable LT	No				
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT					
	N/A	Landing Length (in)	47				Sloped				
	Yes	Landing Width (in)	49	N/A	Flare Slo	ppe RT (%)	6.1				
	Yes	Landing Run Slope (%)	1.7	N/A	Flare Tra	aversable RT	No				
	Yes	Landing Cross Slope (%)	0.6	Yes	DWS Pr	ovided	Yes				
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Co	ontrast	Yes				
		Landing Movement Type	Curb	Yes	DWS Le	ngth (in)	36				
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes				
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0				
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A				
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No				
		Crossing 1 Direction	Е		Crossing	g 2 Direction	N				
т		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A				
οl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A				
E		Crossing 1 Slope (%)	5.2		Crossing	g 2 Slope (%)	0.5				
ol		Crossing 1 Cross Slope (%)	1.3		Crossing	g 2 Cross Slope (%)	4.7				
	Yes	Gutter Ponding	No	No	Curb Slo	рре	7.9				
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	0.7				
_	No	Gutter Run Slope (%)	7.5		Road Cr	oss Slope (%)	5.5				
<u>а</u>	Yes	Gutter Cross Slope (%)	0.4								
S	Yes	Yes Overall Surface Condition: Accep		Yes	Perp Joi	nt Present	Yes				
		Cross Gutter Present?	No		Spandre	I Present?	No				
nt		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A				