

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)




Main Street: YORBA LINDA BLVD **Cross Street: HAMER DR** Location: NW

Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass ADA ID: RPAT211112145107

**Overall Compliance: No** 

0 **Severity Score:** 

## **Codes/Mitigation Info/Possible Solution**





Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R304.2.2-Perp, R304.3.2-Para,

Total Cost: 6160

Parcel ID Number 336-505-19 Ramp Island Or Median None Ramp Orientation Diag Google Street View Link:

Street 1 Name YORBA LINDA BLVD Stop Condition-Street 1 **NoControl** Street 2 Name HAMER DR Stop Condition-Street 2 StopSign

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.88950162,-117.8496796

## **Obstruction and Utility Measurement/Component Compliance**

Com	pliance Description	Data	Com	pliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities	Present?	No
	Obstruction Types	N/A		Utility T	ypes	
	Obstruction Dimensions	N/A	J			N/A



Field Measurements/Component Compliance											
- 1	Com	pliance Description	Data	Com	pliance	Description	Data				
	N/A	Ramp Length (in)	48	N/A	Flare Ty	pe LT					
	Yes	Ramp Width (in)	48				Sloped				
	Yes	Ramp Run Slope (%)	7.4	N/A	Flare Slo	ppe LT (%)	4				
	Yes	Ramp Cross Slope (%)	0.1	N/A	Flare Tra	aversable LT	No				
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT					
	N/A	Landing Length (in)	55				Sloped				
	Yes	Landing Width (in)	48	N/A	Flare Slo	ppe RT (%)	3.6				
	No	Landing Run Slope (%)	2.2	N/A	Flare Tra	aversable RT	No				
	Yes	Landing Cross Slope (%)	0.9	Yes	DWS Pr	ovided	Yes				
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Co	ontrast	Yes				
		Landing Movement Type	Curb	Yes	DWS Le	ngth (in)	36				
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes				
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0				
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A				
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No				
		Crossing 1 Direction	S		Crossing	g 2 Direction	E				
D		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A				
οl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A				
R		Crossing 1 Slope (%)	4.1		Crossing	g 2 Slope (%)	1.7				
n		Crossing 1 Cross Slope (%)	0.8		Crossing	g 2 Cross Slope (%)	1.2				
	Yes	Gutter Ponding	No	No	Curb Slo	рре	7.7				
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	7.1				
	Yes	Gutter Run Slope (%)	2.5		Road Cr	oss Slope (%)	0.1				
<u>a</u>	Yes	Gutter Cross Slope (%)	0.1								
0	Yes	Overall Surface Condition: Accep	ptable	Yes	Perp Joi	nt Present	Yes				
		Cross Gutter Present?	Yes		Spandre	I Present?	Yes				
Α		Replace Cross Gutter?	No		Replace	Spandrel?	No				