

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: PERDIDO_ST		Cross Street: PALAIS_RD		Location:	SW
ADA ID: RPAT211119103701	Ramp Type: Type 4 - Parallel	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score:	5
On don ///	list most on Inda/Danathala Onlystian	Fia	Id Managements/Oamenana	. O	

ADA ID: RPAT211119103701	Ramp Tv	/pe: Type 4 - Parallel	In	itial Pa	ass/F	ail: Pass Overall Co	mplia	nce:	No Severity Score:	5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
Possible Solutions:			Com	oliance Description	Data		pliance Description	Data		
		Remove & Replace Gutter.				Ramp Length LT (in)	80	N/A		81
	-	remove a replace cation			Yes	Ramp Width LT (in)	54	Yes	Ramp Width RT (in)	54
					Yes	Ramp Run Slope LT (%)	7.3		Ramp Run Slope RT (%)	5.3
	_ 5				Yes	Ramp Cross Slope LT (%)	1.5	Yes	Ramp Cross Slope RT (%)	0
6 6					N/A	Landing Present	Yes	Yes	DWS Provided	Yes
PALAIS_RD	ASS.	Surveyor Notes:			N/A	Landing Length (in)	53	Yes	DWS Contrast	Yes
		N/A			Yes	Landing Width (in)	48	Yes	DWS Length (in)	36
					Yes	Landing Run Slope (%)	1	Yes	DWS Full Width	Yes
					Yes	Landing Cross Slope (%)	0.9		DWS Offset Type	Single
					N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
i i		OC Std/PROW:				Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
J 3 1		R304.5.4, STD 1115			N/A	Landing Shared	No			
					N/A	Clear Space	Yes			
					N/A	Clear Space To Crosswalk (in)	48			
		Total Cost:	\$	252	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No
						Crossing 1 Direction	Ε		Crossing 2 Direction	N
Parcel ID Number	127-382-01	Street 1 Name	PERDID	O_ST		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A
Ramp Island Or Median	None	Stop Condition-Street 1	NoC	ontrol	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2	N/A
Ramp Orientation	Diag	Street 2 Name	PALAI	S_RD		Crossing 1 Slope (%)	5.5		Crossing 2 Slope (%)	2.7
Google Street View Link:		Stop Condition-Street 2	NoC	ontrol		Crossing 1 Cross Slope (%)	2.5		Crossing 2 Cross Slope (%)	2.2
http://www.google.com/maps/@?api=1↦_action=pano&viewpoint=33.8136171,-117.9628813				Yes	Gutter Ponding	No	Yes	Curb Slope	1.5	
Obstruction and Utility Measurement/Component Compliance			Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	0.7		
Compliance Description	•	Compliance Description		Data	No	Gutter Run Slope (%)	5.3		Road Cross Slope (%)	3.8
Yes Obstructions Present?	No.	N/A Utilities Present?		No No	Yes	Gutter Cross Slope (%)	0.9	Yes	Perpendicular Joint Present	Yes
Obstruction Types	N/A	Utility Types		NO	Yes	Overall Surface Condition Acce	ptable			
Obstruction Dimensions	N/A	1		N/A		Cross Gutter Present?	No		Spandrel Present?	No
SSS GOLOTI DIMOTOSOTIO	IVA					Replace Cross Gutter?	No	I	Replace Spandrel?	No
The state of the s	ET S. D.									