

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Main Street: MARIAN_AVE	Ci	ross Street: THISTLE_RD		Location:	NW
ADA ID: RPAT211130132618	Ramn Type: Type 6 - Directional 1	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score:	2

Main Street: MARIAN_AVE		Cross Street: THISTLE_RD				Location:	NW		
ADA ID: RPAT211130132618	Ramp Ty	pe: Type 6 - Directional 1	Initial F	Pass/l	Fail: Fail Overall C	omplia	nce:	No Severity Score:	2
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Com	pliance Description	Data	Com	pliance Description	Data
		Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	105	N/A	Flare Type LT	
				Yes	Ramp Width (in)	59			N/A
				Yes	Ramp Run Slope (%)	1.4	N/A	Flare Slope LT (%)	N/A
				Yes	Ramp Cross Slope (%)	2	N/A	Flare Traversable LT	N/A
				N/A	Grade Break	N/A	N/A	Flare Type RT	
是		Surveyor Notes:		N/A	Grade Break Slope (%)	N/A			N/A
		N/A		N/A	Grade Break Cross Slope (%)	N/A	N/A	Flare Slope RT (%)	N/A
CA DE LOS CASA					Addl Para Ramp Left?	No	N/A	Flare Traversable RT	N/A
MARIAL AND E	7.10				Addl Para Ramp Right?	No	N/A	DWS Provided	N/A
	<u>6</u>			N/A	Landing Present	N/A	N/A	DWS Contrast	N/A
	MARIAN_AVE	OC Std/PROW:		N/A	Landing Length (in)	N/A	N/A	DWS Length (in)	N/A
		STD 1115		N/A	Landing Width (in)	N/A	N/A	DWS Full Width	N/A
	<u>6.</u>			N/A	Landing Run Slope (%)	N/A		DWS Offset Type	N/A
				N/A	Landing Cross Slope (%)	N/A	N/A	DWS Left Offset (in)	N/A
	(4)	Total Cost:	\$ 3080	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Right Offset (in)	N/A
		•			Landing Movement Type	N/A			
Parcel ID Number	127-091-04	Street 1 Name	MARIAN_AVE	N/A	Landing Shared	N/A			
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl	N/A	Marked Crosswalk 1	No	N/A	Clear Space	N/A
Ramp Orientation	NonDiag	Street 2 Name	THISTLE_RD		Crossing 1 Direction	S	N/A	Clear Space To Crosswalk (in)	N/A
Google Street View Link:		Stop Condition-Street 2	N/A		Marked Crosswalk 1 Width (in)	N/A			
http://www.google.com/maps/@?api=1↦_action=pano&viewpoint=33.82813316,-117.96135313			N/A	Ramp Inside Crosswalk 1	N/A				
Objetoventian					Crossing 1 Slope (%)	2.1			
	-	rement/Component Compliance	Dete		Crossing 1 Cross Slope (%)	1.3			
Yes Obstructions Present?	No	N/A Utilities Present?	<u>Data</u> No	N/A	Gutter Ponding	N/A	Yes	Curb Slope	2.4
			NO	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A
Obstruction Types Obstruction Dimensions	N/A N/A	Utility Types	N/A	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	N/A
Obstruction Dimensions	N/A		N/A	N/A	Gutter Cross Slope (%)	N/A		Parallel Ramp Side	N/A
		at them, will be a		Yes	Overall Surface Condition Acco	eptable	Yes	Perp Joint Present	Yes
		The state of the s			Cross Gutter Present?	Yes		Spandrel Present?	Yes

No

Replace Spandrel?

No

Replace Cross Gutter?