

Obstructions Present?

Obstruction Types

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: LULLABY_LN Cross Street: PERDIDO_ST Location: SE

Ramp Type: Type 4 - Parallel Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 5 ADA ID: RPAT220203155811 **Codes/Mitigation Info/Possible Solution** Field Measurements/Component Compliance Possible Solutions: Compliance Description Data Compliance Description Data Ramp Length RT (in) N/A Ramp Length LT (in) Remove & Replace Gutter. 87 83 Ramp Width LT (in) Ramp Width RT (in) 53 Ramp Run Slope RT (%) Ramp Run Slope LT (%) 7.8 6.8 Ramp Cross Slope LT (%) Ramp Cross Slope RT (%) 1.2 0.8 Landing Present Yes DWS Provided Yes Surveyor Notes: **DWS Contrast** Landing Length (in) 53 Yes 36 N/A Landing Width (in) 48 DWS Length (in) Landing Run Slope (%) Yes DWS Full Width Yes 1.4 Landing Cross Slope (%) 0.1 **DWS Offset Type** Single N/A Landing Movement Obstructed? No Yes DWS Offset Left (in) OC Std/PROW: Curb DWS Offset Right (in) N/A Landing Movement Type Landing Shared No R302.7, R304.5.4, STD 1115 Clear Space Yes N/A Clear Space To Crosswalk (in) 48 Total Cost: 252 Marked Crosswalk 1 No Marked Crosswalk 2 No Crossing 1 Direction Ν Crossing 2 Direction w Parcel ID Number 127-394-01 Street 1 Name N/A **LULLABY LN** Marked Crosswalk 1 Width (in) Marked Crosswalk 2 Width (in) N/A **NoControl** N/A Ramp Inside Crosswalk 1 Ramp Island Or Median None Stop Condition-Street 1 N/A Ramp Inside Crosswalk 2 N/A Diag Street 2 Name PERDIDO ST 6.1 N/A Ramp Orientation Crossing 1 Slope (%) Crossing 2 Slope (%) Google Street View Link: Stop Condition-Street 2 NoControl Crossing 1 Cross Slope (%) 0.4 Crossing 2 Cross Slope (%) N/A **Gutter Ponding** Yes Curb Slope 5.1 http://www.google.com/maps/@?api=1&map action=pano&viewpoint=33.81111367,-117.96269388 Yes Gutter Lip Height (in) 0 Road Run Slope (%) N/A **Obstruction and Utility Measurement/Component Compliance** Gutter Run Slope (%) 6.4 Road Cross Slope (%) N/A Compliance Description Data Compliance Description Data

No

N/A

Gutter Cross Slope (%)

Cross Gutter Present?

Replace Cross Gutter?

Yes Overall Surface Condition Acceptable

1.3

No

N/A

Perpendicular Joint Present

Spandrel Present?

Replace Spandrel?

Yes

No

N/A



N/A

No

N/A

Utilities Present?

Utility Types