

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: E YORBA LINDA BLVD **Cross Street: MCCORMACK LN** NE Location: ADA ID: RPAT220207132030 Ramp Type:Type 1 - Perpendicular **Initial Pass/Fail: Pass Overall Compliance: No Severity Score:** 2

Codes/Mitigation Info/Possible Solution



Possible Solutions: Restripe Crosswalk. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R207.1, R302.7, R304.5.3, STD 1115

Total Cost: 4252

Parcel ID Number Ramp Island Or Median None Ramp Orientation NonDiag Google Street View Link:

336-515-08 Street 1 Name E YORBA LINDA BLVD Stop Condition-Street 1 Signal Street 2 Name MCCORMACK_LN Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.8895247,-117.84819069

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance										
- [Compliance Description		Data	Compliance Description			Data			
	N/A	Ramp Length (in)	107	N/A	Flare Ty	pe LT				
	Yes	Ramp Width (in)	49				Sloped			
	Yes	Ramp Run Slope (%)	5.3	N/A	Flare Slo	ppe LT (%)	10.8			
	Yes	Ramp Cross Slope (%)	0.9	N/A	Flare Traversable LT		No			
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT				
	N/A	Landing Length (in)	53				Sloped			
	Yes	Landing Width (in)	49	N/A	Flare Slo	ppe RT (%)	8.7			
	Yes	Landing Run Slope (%)	1.2	N/A	Flare Tra	aversable RT	No			
	Yes	Landing Cross Slope (%)	0.6	Yes	DWS Pr	ovided	Yes			
	N/A	Landing Movement Obstructed?	No	Yes	DWS Co	ontrast	Yes			
		Landing Movement Type	N/A	Yes	DWS Le	ngth (in)	36			
	N/A	Landing Shared	Yes	Yes	DWS Fu	ll Width	Yes			
	N/A	Clear Space	N/A	Yes	DWS Of	fset Left (in)	0			
	N/A	Clear Space To Crosswalk (in)	N/A	Yes	DWS Of	fset Right (in)	N/A			
2	N/A	Marked Crosswalk 1	Yes	N/A	Marked	Crosswalk 2	N/A			
		Crossing 1 Direction	NW		Crossing	2 Direction	N/A			
D		Marked Crosswalk 1 Width (in)	130		Marked	Crosswalk 2 Width (in)	N/A			
al	No	Ramp Inside Crosswalk 1	No	Yes	Ramp In	side Crosswalk 2	N/A			
N		Crossing 1 Slope (%)	6.4		Crossing	g 2 Slope (%)	N/A			
A		Crossing 1 Cross Slope (%)	0.9		Crossing	g 2 Cross Slope (%)	N/A			
	No	Gutter Ponding	Yes	Yes	Curb Slo	рре	4.6			
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	N/A			
	Yes	Gutter Run Slope (%)	2.3		Road Cr	oss Slope (%)	N/A			
<u>a</u>	No	Gutter Cross Slope (%)	2.8							
0	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joi	nt Present	Yes			
		Cross Gutter Present?	No		Spandre	I Present?	No			
A		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A			