

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: N/A Cross Street: YORBA\_LINDA\_BLVD Location: SW

ADA ID: RPAT220221112615 Ramp Type:Type 1 - Perpendicular Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 22

**Codes/Mitigation Info/Possible Solution** 



Possible Solutions:

Remove & Replace Entire Ramp. Grind Gutter
Lip.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R302.7, R302.7.2, STD 1115

Total Cost: \$ 3230

Parcel ID Number	348-023-08
Ramp Island Or Median	None
Ramp Orientation	NonDiag
Google Street View Link:	

Street 1 Name N/A
Stop Condition-Street 1 NoControl
Street 2 Name YORBA\_LINDA\_BLVD
Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.88856543,-117.79764924

## **Obstruction and Utility Measurement/Component Compliance**

Com	pliance Description	Data	Com	pliance Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	J		N/A







Field Measurements/Component Compliance								
	Compliance Description			Com	pliance	Description	Data	
	N/A	Ramp Length (in)	112	N/A	Flare Typ	e LT		
	Yes	Ramp Width (in)	48				None	
	Yes	Ramp Run Slope (%)	8.3	N/A	Flare Slop	pe LT (%)	N/A	
	Yes	Ramp Cross Slope (%)	1.2	N/A	Flare Trav	versable LT	N/A	
	N/A	Landing Present	Yes	N/A	Flare Typ	e RT		
	N/A	Landing Length (in)	25				Sloped	
	Yes	Landing Width (in)	48	Yes	Flare Slop	oe RT (%)	10	
	No	Landing Run Slope (%)	2.2	N/A	Flare Trav	versable RT	Yes	
	No	Landing Cross Slope (%)	2.5	No	DWS Pro	vided	No	
	N/A	Landing Movement Obstructed?	No	N/A	DWS Cor	ntrast	N/A	
		Landing Movement Type	N/A	N/A	DWS Len	gth (in)	N/A	
	N/A	Landing Shared	No	N/A	DWS Full	Width	N/A	
	N/A	Clear Space	N/A	N/A	DWS Offs	set Left (in)	N/A	
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offs	set Right (in)	N/A	
0	N/A	Marked Crosswalk 1	No	N/A	Marked C	rosswalk 2	N/A	
		Crossing 1 Direction	E		Crossing	2 Direction	N/A	
Α		Marked Crosswalk 1 Width (in)	N/A		Marked C	rosswalk 2 Width (in)	N/A	
ol	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Ins	ide Crosswalk 2	N/A	
D		Crossing 1 Slope (%)	4.7		Crossing	2 Slope (%)	N/A	
Α		Crossing 1 Cross Slope (%)	0.6		Crossing	2 Cross Slope (%)	N/A	
	No	Gutter Ponding	Yes	Yes	Curb Slop	pe	1.1	
	No	Gutter Lip Height (in)	0.5		Road Ru	n Slope (%)	N/A	
_	Yes	Gutter Run Slope (%)	4		Road Cro	ss Slope (%)	N/A	
<u>а</u>	Yes	Gutter Cross Slope (%)	1.5					
0	Yes	Yes Overall Surface Condition: Accep		Yes	Perp Joir	t Present	Yes	
		Cross Gutter Present?	No		Spandrel	Present?	No	
A		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A	