

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Main Street: ESPERANZA_RD				Location:	N			
	_	_	_					

Main Street: ESPERANZA_RD			Cross Street: N/A					Location:	N
ADA ID: RPAT220221121714	Ramp Ty	vpe: Type 4 - Parallel	Initial Pass/Fail: Pass Overall Compliance:				No Severity Score:	0	
Codes/Mi	/Possible Solution	Field Measurements/Component Compliance							
2		Possible Solutions:		Com	pliance Description	Data	Com	pliance Description	Data
3 .3	- A MA	Gutter Ponding Observed.		N/A	Ramp Length LT (in)	98	N/A	Ramp Length RT (in)	120
10.5				Yes	Ramp Width LT (in)	58	Yes	Ramp Width RT (in)	58
3				Yes	Ramp Run Slope LT (%)	7.9	Yes	Ramp Run Slope RT (%)	7.4
	a Kes			Yes	Ramp Cross Slope LT (%)	0.2	Yes	Ramp Cross Slope RT (%)	0.3
	F Washington			N/A	Landing Present	Yes	Yes	DWS Provided	Yes
		Surveyor Notes:		N/A	Landing Length (in)	66	Yes	DWS Contrast	Yes
		N/A		Yes	Landing Width (in)	48	Yes	DWS Length (in)	36
<u>C.</u>				Yes	Landing Run Slope (%)	0.2	Yes	DWS Full Width	Yes
				Yes	Landing Cross Slope (%)	0.2		DWS Offset Type	Single
ESPERANZA RD				N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)	0
		OC Std/PROW:			Landing Movement Type	Curb	Yes	DWS Offset Right (in)	N/A
		R302.7, STD 1115		N/A	Landing Shared	No			
	Andrew Commencer of the			N/A	Clear Space	N/A			
	THE STATE OF THE S			N/A	Clear Space To Crosswalk (in)	N/A			
TO THE REAL PROPERTY.	AND THE PROPERTY OF THE PARTY O	Total Cost:	\$ 252	N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A
		•			Crossing 1 Direction	S		Crossing 2 Direction	N/A
Parcel ID Number	349-411-01	Street 1 Name	ESPERANZA_RD		Marked Crosswalk 1 Width (in)	120		Marked Crosswalk 2 Width (in)	N/A
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl	Yes	Ramp Inside Crosswalk 1	Yes	N/A	Ramp Inside Crosswalk 2	N/A
Ramp Orientation	NonDiag	Street 2 Name	N/A		Crossing 1 Slope (%)	4.1		Crossing 2 Slope (%)	N/A
Google Street View Link:		Stop Condition-Street 2	N/A		Crossing 1 Cross Slope (%)	2		Crossing 2 Cross Slope (%)	N/A
http://www.google.com/maps/@?api=1↦_action=pa	No	Gutter Ponding	Yes	Yes	Curb Slope	7.2			
.	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A			
Obstruction ar	Data	Yes	Gutter Run Slope (%)	4.8		Road Cross Slope (%)	N/A		
Compliance Description	Data	Compliance Description	Data	Yes	Gutter Cross Slope (%)	1.7	Yes	Perpendicular Joint Present	Yes
Yes Obstructions Present?	No	N/A Utilities Present?	No	Yes	Overall Surface Condition Acce	eptable			
Obstruction Types	N/A	Utility Types			Cross Gutter Present?	No		Spandrel Present?	No

N/A

Replace Cross Gutter?

N/A

Replace Spandrel?



Obstruction Dimensions

N/A