

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



 Main Street: CASTLEFIELD\_DR
 Cross Street: CEDARLAWN\_DR
 Location:
 NW

ADA ID: RPRK210917130912 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Co

Overall Compliance: No

Severity Score:

## Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Slope. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.3, STD 1115

Total Cost: \$ 504

		i e e e e e e e e e e e e e e e e e e e	
Parcel ID Number	340-252-19	Street 1 Name	CASTLEFIELD_DR
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl
Ramp Orientation	Diag	Street 2 Name	CEDARLAWN_DR
Google Street View Link:		Stop Condition-Street 2	NoControl

 $\underline{http://www.google.com/maps/@?api=1\&map\_action=pano\&viewpoint=33.88662571,-117.84891799}$ 

## **Obstruction and Utility Measurement/Component Compliance**

Compliance Description Dat		Compliance Description	Data
Yes Obstructions Present?	No	N/A Utilities Present?	No
Obstruction Types	N/A	Utility Types	
Obstruction Dimensions	N/A		N/A







Field Measurements/Component Compliance										
	Compliance Description		Data	Compliance Description			Data			
	N/A	Ramp Length (in)	120	N/A	Flare Ty	pe LT				
	Yes	Ramp Width (in)	48				Sloped			
	Yes	Ramp Run Slope (%)	7.3	N/A	Flare Slo	ope LT (%)	4.1			
	Yes	Ramp Cross Slope (%)	0.8	N/A	Flare Traversable LT		No			
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT				
	N/A	Landing Length (in)	50				Sloped			
	Yes	Landing Width (in)	48	N/A	Flare Slo	ope RT (%)	6.5			
	Yes	Landing Run Slope (%)	1	N/A	Flare Tra	aversable RT	No			
	Yes	Landing Cross Slope (%)	0.2	Yes	DWS Pr	ovided	Yes			
	N/A	Landing Movement Obstructed?	No	Yes	DWS Co	ontrast	Yes			
		Landing Movement Type	N/A	Yes	DWS Le	ngth (in)	36			
	N/A	Landing Shared	No	Yes	DWS Fu	II Width	Yes			
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	0			
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A			
4	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No			
		Crossing 1 Direction	S		Crossing	g 2 Direction	E			
R		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A			
ı	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A			
R		Crossing 1 Slope (%)	3.3		Crossing	g 2 Slope (%)	9			
ı		Crossing 1 Cross Slope (%)	1.8		Crossing	g 2 Cross Slope (%)	1.6			
	Yes	Gutter Ponding	No	No	Curb Slo	ope	9.3			
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	1.1			
	Yes	Gutter Run Slope (%)	0.6		Road Cr	oss Slope (%)	3			
<u>a</u>	No	Gutter Cross Slope (%)	3.5							
0	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joi	int Present	Yes			
		Cross Gutter Present?	Yes		Spandre	l Present?	Yes			
A		Replace Cross Gutter?	No		Replace	Spandrel?	No			