

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: VAN_BUREN_ST Cross Street: MADISON_AVE Location: SW

ADA ID: RPRK211001195220 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 35

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.5.1, R304.5.3, STD 1115

Total Cost: \$ 6160

Parcel ID Number	097-123-19	Street
Ramp Island Or Median	None	Stop C
Ramp Orientation	Diag	Street
Google Street View Link:		Stop C

19 Street 1 Name VAN_BUREN_ST

10 Stop Condition-Street 1 StopSign

11 StopSign

12 Street 2 Name MADISON_AVE

13 Stop Condition-Street 2 NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.7483131,-117.98647816

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Compliance Description	Data
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance								
	Com	pliance Description	Data	Compliance Description			Data	
	N/A	Ramp Length (in)	102	N/A	Flare Ty	pe LT		
	No	Ramp Width (in)	36				N/A	
	No	Ramp Run Slope (%)	12.4	N/A	Flare Slo	ope LT (%)	N/A	
	No	Ramp Cross Slope (%)	2.3	N/A	Flare Tra	aversable LT	N/A	
	N/A	Landing Present	N/A	N/A	Flare Ty	pe RT		
	N/A	Landing Length (in)	N/A				N/A	
	N/A	Landing Width (in)	N/A	N/A	Flare Slo	ope RT (%)	N/A	
	N/A	Landing Run Slope (%)	N/A	N/A	Flare Tra	aversable RT	N/A	
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Pr	ovided	N/A	
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Co	ontrast	N/A	
		Landing Movement Type	N/A	N/A	DWS Le	ngth (in)	N/A	
	N/A	Landing Shared	N/A	N/A	DWS Fu	ll Width	N/A	
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A	
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Of	fset Right (in)	N/A	
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No	
		Crossing 1 Direction	Е		Crossing	g 2 Direction	N	
Т		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A	
n	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A	
E		Crossing 1 Slope (%)	5.1		Crossing	g 2 Slope (%)	1.4	
l		Crossing 1 Cross Slope (%)	5.1		Crossing	g 2 Cross Slope (%)	0.4	
	N/A	Gutter Ponding	N/A	No	Curb Slo	рре	10.4	
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	0.3	
_	N/A	Gutter Run Slope (%)	N/A		Road Cr	oss Slope (%)	4.7	
<u>a</u>	N/A	Gutter Cross Slope (%)	N/A					
0	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Jo	int Present	Yes	
_		Cross Gutter Present?	No		Spandre	l Present?	Yes	
Α		Replace Cross Gutter?	N/A		Replace	Spandrel?	No	