

Access Compliance Report Public Rights-of-Way (Curb Ramps)



SE

Main Street: ROCKWELL AVE **Cross Street: CEDARWOOD AVE**


Location:

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Fail ADA ID: RPRK211005175221

Overall Compliance: No

15 **Severity Score:**

Codes/Mitigation Info/Possible Solution





Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, STD 1115

Total Cost:

Parcel ID Number Ramp Island Or Median None Ramp Orientation Diag Google Street View Link:

142-052-28 Street 1 Name **ROCKWELL AVE** Stop Condition-Street 1 **NoControl** Street 2 Name CEDARWOOD AVE Stop Condition-Street 2 **NoControl**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.73903003,-117.99330486

Obstruction and Utility Measurement/Component Compliance

Compliance Description Data			Compliance Description	Data
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance										
	Compliance Description		Data	ata Compliance Description						
N	N/A	Ramp Length (in)	89	N/A	Flare Type LT					
	Yes	Ramp Width (in)	48			N/A				
	No	Ramp Run Slope (%)	11.7	N/A	Flare Slope LT (%)	N/A				
	Yes	Ramp Cross Slope (%)	0.1	N/A	Flare Traversable LT	N/A				
	N/A	Landing Present	N/A	N/A	Flare Type RT					
	N/A	Landing Length (in)	N/A			N/A				
	N/A	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	N/A				
	N/A	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	N/A				
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Provided	N/A				
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Contrast	N/A				
		Landing Movement Type	N/A	N/A	DWS Length (in)	N/A				
	N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A				
	N/A	Clear Space	Yes	N/A	DWS Offset Left (in)	N/A				
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A				
6160	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2	No				
		Crossing 1 Direction	N		Crossing 2 Direction	W				
L_AVE		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)	N/A				
ontrol	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp Inside Crosswalk 2	N/A				
_AVE		Crossing 1 Slope (%)	7.2		Crossing 2 Slope (%)	2.1				
ontrol		Crossing 1 Cross Slope (%)	2.4		Crossing 2 Cross Slope (%)	1.6				
	N/A	Gutter Ponding	N/A	No	Curb Slope	13.7				
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	4.4				
Data	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	3.3				
Data	N/A	Gutter Cross Slope (%)	N/A							
No	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joint Present	Yes				
N/A		Cross Gutter Present?	Yes		Spandrel Present?	Yes				
N/A		Replace Cross Gutter?	No	J	Replace Spandrel?	No				