

Access Compliance Report Public Rights-of-Way (Curb Ramps)



SE

Main Street: VINEWOOD LN **Cross Street: SLEEPY HOLLOW LN**

Location:

Severity Score: ADA ID: RPRK211021134838 Ramp Type: Type 4 - Parallel **Initial Pass/Fail: Pass Overall Compliance: No** 20

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New **Directional Ramps or Equivalent. Gutter Ponding** Observed.

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R305, R302.7, STD 1115

Total Cost: 4252

Parcel ID Number 759-262-69 Street 1 Name VINEWOOD LN Stop Condition-Street 1 Ramp Island Or Median None **NoControl** Ramp Orientation Diag Street 2 Name SLEEPY_HOLLOW_LN Google Street View Link: Stop Condition-Street 2 NoControl

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.57018005,-117.63431175

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	oliance Description	<u>Data</u>	١
Yes	Obstructions Present?	No	N/A	Utilities Present?	No	١,
	Obstruction Types	N/A		Utility Types		
	Obstruction Dimensions	N/A	J		N/A	



Field Measurements/Component Compliance											
- 1	Compliance Description		Data	Com	Compliance Description		Data				
	N/A	Ramp Length LT (in)	115	N/A	Ramp L	ength RT (in)	114				
	Yes	Ramp Width LT (in)	53	Yes	Ramp W	/idth RT (in)	53				
	Yes	Ramp Run Slope LT (%)	7.1	Yes	Ramp R	un Slope RT (%)	3.4				
	Yes	Ramp Cross Slope LT (%)	0.6	Yes	Ramp C	ross Slope RT (%)	0.4				
	N/A	Landing Present	No	No	DWS Pr	ovided	No				
	N/A	Landing Length (in)	N/A	N/A	DWS Co	ontrast	N/A				
	No	Landing Width (in)	N/A	N/A	DWS Le	ngth (in)	N/A				
	No	Landing Run Slope (%)	N/A	N/A	DWS Fu	ıll Width	N/A				
	No	Landing Cross Slope (%)	N/A		DWS Of	fset Type	N/A				
	N/A	Landing Movement Obstructed?	No	N/A	DWS Of	fset Left (in)	N/A				
		Landing Movement Type	Curb	N/A	DWS Of	fset Right (in)	N/A				
	N/A	Landing Shared	N/A								
	N/A	Clear Space	Yes								
	N/A	Clear Space To Crosswalk (in)	48								
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No				
		Crossing 1 Direction	N		Crossing	g 2 Direction	W				
N		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A				
ol	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp In	side Crosswalk 2	N/A				
N		Crossing 1 Slope (%)	3.7		Crossin	g 2 Slope (%)	2.9				
ol		Crossing 1 Cross Slope (%)	1.5		Crossin	g 2 Cross Slope (%)	1.6				
	No	Gutter Ponding	Yes	Yes	Curb Slo	ppe	5.2				
	Yes	Gutter Lip Height (in)	0		Road Ru	un Slope (%)	0.4				
_	Yes	Gutter Run Slope (%)	0.7		Road Cr	ross Slope (%)	0.6				
<u>а</u>	Yes	Gutter Cross Slope (%)	0.1	No	Perpend	licular Joint Present	No				
0	Yes Overall Surface Condition Acceptable										
		Cross Gutter Present?	Yes		Spandre	el Present?	Yes				
A		Replace Cross Gutter?	No		Replace	e Spandrel?	No				