

Access Compliance Report Public Rights-of-Way (Curb Ramps)



<u>Data</u>

108

62

4.5

0.3

Yes

Yes

36

Yes Single

N/A

No

N/A

N/A

3.8

0.5

6.7

0.4

0.7

Yes

No

N/A

Main Street: MEDANO_ST	Cross Street: TOPAZ_ST	Location:	SW

ADA ID: RPRK211124135815	Ramp Ty	vpe: Type 4 - Parallel	Initial P	ass/l	Fail: Pass Overall Co	mplia	nce:	Yes Severity Score:
Codes/Mi	Field Measurements/Component Compliance							
		Possible Solutions:		Com	pliance Description	Data	Com	pliance Description
		N/A		N/A	Ramp Length LT (in)	113	N/A	Ramp Length RT (in)
				Yes	Ramp Width LT (in)	62	Yes	Ramp Width RT (in)
				Yes	Ramp Run Slope LT (%)	6.8	Yes	Ramp Run Slope RT (%)
				Yes	Ramp Cross Slope LT (%)	0.7	Yes	Ramp Cross Slope RT (%)
				N/A	Landing Present	Yes	Yes	DWS Provided
		Surveyor Notes:		N/A	Landing Length (in)	62	Yes	DWS Contrast
		N/A		Yes	Landing Width (in)	48	Yes	DWS Length (in)
6 6	ALL S			Yes	Landing Run Slope (%)	0.3	Yes	DWS Full Width
				Yes	Landing Cross Slope (%)	0.4		DWS Offset Type
				N/A	Landing Movement Obstructed?	No	Yes	DWS Offset Left (in)
		OC Std/PROW:			Landing Movement Type	Curb	Yes	DWS Offset Right (in)
192		N/A		N/A	Landing Shared	No		
				N/A	Clear Space	Yes		
6.				N/A	Clear Space To Crosswalk (in)	48		
S. S.	SUERILE_ST	Total Cost:	\$ 0	N/A	Marked Crosswalk 1	No	N/A	Marked Crosswalk 2
		•			Crossing 1 Direction	E		Crossing 2 Direction
Parcel ID Number	125-352-11	Street 1 Name	MEDANO_ST		Marked Crosswalk 1 Width (in)	N/A		Marked Crosswalk 2 Width (in)
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Inside Crosswalk 2
Ramp Orientation	Diag	Street 2 Name	TOPAZ_ST		Crossing 1 Slope (%)	1.7		Crossing 2 Slope (%)
Google Street View Link:		Stop Condition-Street 2	StopSign		Crossing 1 Cross Slope (%)	0.4		Crossing 2 Cross Slope (%)
http://www.google.com/maps/@?api=1↦_action=pano&viewpoint=33.54852356,-117.59933207		Yes	Gutter Ponding	No	Yes	Curb Slope		
		Yes	Gutter Lip Height (in)	0		Road Run Slope (%)		
		rement/Component Compliance		Yes	Gutter Run Slope (%)	1		Road Cross Slope (%)
Compliance Description	Data	Compliance Description	Data	Yes	Gutter Cross Slope (%)	0.4	Yes	Perpendicular Joint Present
Yes Obstructions Present?	No	N/A Utilities Present?	No	Yes	Overall Surface Condition Acce	ptable		
Obstruction Types	N/A	Utility Types			Cross Gutter Present?	No		Spandrel Present?
Obstruction Dimensions	N/A		N/A		Replace Cross Gutter?	N/A		Replace Spandrel?
7								