

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: ANDAZA_STCross Street: ESENCIA_DRLocation:EADA ID: RPRK211129122240Ramp Type:Type 1 - PerpendicularInitial Pass/Fail: PassOverall Compliance: NoSeverity Score:2

Codes/Mitigation Info/Possible Solution



Possible Solutions:
Remove & Replace Entire Ramp.

Surveyor Notes:
N/A

OC Std/PROW:
R304.2.2, R304.5.3, STD 1115

Total Cost: \$ 3080

Parcel ID Number 755-321-02
Ramp Island Or Median None
Ramp Orientation NonDiag
Google Street View Link:

755-321-02 Street 1 Name ANDAZA_ST
None Stop Condition-Street 1 NoControl
NonDiag Street 2 Name ESENCIA_DR
Stop Condition-Street 2 N/A

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.53400251,-117.60075678

Obstruction and Utility Measurement/Component Compliance

Compliance Description	Data Compliance Description	Data
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A







Field Measurements/Component Compliance									
	Compliance Description			Data Compliance Description					
	N/A	Ramp Length (in)	74	N/A	Flare Type LT				
	Yes	Ramp Width (in)	60			Sloped			
	Yes	Ramp Run Slope (%)	7.9	N/A	Flare Slope LT (%)	11.4			
	Yes	Ramp Cross Slope (%)	1.9	N/A	Flare Traversable LT	No			
	N/A	Landing Present	Yes	N/A	Flare Type RT				
	N/A	Landing Length (in)	59			Sloped			
	Yes	Landing Width (in)	66	N/A	Flare Slope RT (%)	9.6			
	Yes	Landing Run Slope (%)	0.7	N/A	Flare Traversable RT	No			
	No	Landing Cross Slope (%)	2.4	Yes	DWS Provided	Yes			
	N/A	Landing Movement Obstructed?	No	Yes	DWS Contrast	Yes			
		Landing Movement Type	N/A	Yes	DWS Length (in)	36			
	N/A	Landing Shared	No	Yes	DWS Full Width	Yes			
	N/A	Clear Space	N/A	Yes	DWS Offset Left (in)	0			
	N/A	Clear Space To Crosswalk (in)	N/A	Yes	DWS Offset Right (in)	N/A			
80	N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A			
		Crossing 1 Direction	NW		Crossing 2 Direction	N/A			
ST		Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	N/A			
rol	Yes	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	N/A			
DR		Crossing 1 Slope (%)	2.8		Crossing 2 Slope (%)	N/A			
/A		Crossing 1 Cross Slope (%)	1.2		Crossing 2 Cross Slope (%)	N/A			
	Yes	Gutter Ponding	No	No	Curb Slope	5.1			
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A			
	Yes	Gutter Run Slope (%)	3.7		Road Cross Slope (%)	N/A			
<u>ita</u>	Yes	Gutter Cross Slope (%)	0.7						
No	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joint Present	Yes			
		Cross Gutter Present?	No		Spandrel Present?	No			
/A		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A			
_									