

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: APRENDER_STCross Street: ANDAZA_STLocation:SEADA ID: RPRK211202133327Ramp Type:Type 1 - PerpendicularInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:2

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

N/A

OC Std/PROW:

R304.5.3, STD 1115

Total Cost: \$ 3080

Parcel ID Number	755-301-37	
Ramp Island Or Median	None	
Ramp Orientation	NonDiag	
Google Street View Link:		

Street 1 Name

APRENDER_ST

Stop Condition-Street 1

Street 2 Name

ANDAZA_ST

Stop Condition-Street 2

N/A

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.53700733,-117.59656185}$

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	pliance Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	l		N/A



Field Measurements/Component Compliance								
	Com	pliance Description	Data	Com	pliance Description	Data		
	N/A	Ramp Length (in)	84	N/A	Flare Type LT			
	Yes	Ramp Width (in)	60			N/A		
	Yes	Ramp Run Slope (%)	7.1	N/A	Flare Slope LT (%)	N/A		
	No	Ramp Cross Slope (%)	2.5	N/A	Flare Traversable LT	N/A		
	N/A	Landing Present	N/A	N/A	Flare Type RT			
	N/A	Landing Length (in)	N/A			N/A		
	N/A	Landing Width (in)	N/A	N/A	Flare Slope RT (%)	N/A		
	N/A	Landing Run Slope (%)	N/A	N/A	Flare Traversable RT	N/A		
	N/A	Landing Cross Slope (%)	N/A	N/A	DWS Provided	N/A		
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Contrast	N/A		
		Landing Movement Type	N/A	N/A	DWS Length (in)	N/A		
	N/A	Landing Shared	N/A	N/A	DWS Full Width	N/A		
	N/A	Clear Space	N/A	N/A	DWS Offset Left (in)	N/A		
	N/A	Clear Space To Crosswalk (in)	N/A	N/A	DWS Offset Right (in)	N/A		
0	N/A	Marked Crosswalk 1	Yes	N/A	Marked Crosswalk 2	N/A		
		Crossing 1 Direction	N		Crossing 2 Direction	N/A		
Т		Marked Crosswalk 1 Width (in)	144		Marked Crosswalk 2 Width (in)	N/A		
ı	N/A	Ramp Inside Crosswalk 1	Yes	Yes	Ramp Inside Crosswalk 2	N/A		
Т		Crossing 1 Slope (%)	2.8		Crossing 2 Slope (%)	N/A		
4		Crossing 1 Cross Slope (%)	8.0		Crossing 2 Cross Slope (%)	N/A		
	N/A	Gutter Ponding	N/A	N/A	Curb Slope	1.7		
	Yes	Gutter Lip Height (in)	0		Road Run Slope (%)	N/A		
	N/A	Gutter Run Slope (%)	N/A		Road Cross Slope (%)	N/A		
<u>a</u>	N/A	Gutter Cross Slope (%)	N/A					
0	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Joint Present	Yes		
		Cross Gutter Present?	No		Spandrel Present?	No		
4		Replace Cross Gutter?	N/A		Replace Spandrel?	N/A		