

Access Compliance Report Public Rights-of-Way (Curb Ramps)



SW

16

Main Street: SILVER FOX RD Cross Street: COPA DE ORO DR Location:

ADA ID: RPRK211206175210

Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:

| Codes/Mitigation Info/Possible Solution |
|---|
|---|



Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R204.3, R304.2.1, R305, R304.5.4, R304.5.3, STD 1115

Total Cost: 6412

Parcel ID Number 086-181-01 Ramp Island Or Median None Ramp Orientation Diag Google Street View Link:

Street 1 Name SILVER_FOX_RD Stop Condition-Street 1 **NoControl** Street 2 Name COPA_DE_ORO_DR Stop Condition-Street 2 **NoControl**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.78112374,-118.0800343

Obstruction and Utility Measurement/Component Compliance

| Com | pliance Description | Data | Com | pliance Description | <u>Data</u> |
|-----|------------------------|------|-----|---------------------|-------------|
| Yes | Obstructions Present? | No | N/A | Utilities Present? | No |
| | Obstruction Types | N/A | | Utility Types | |
| | Obstruction Dimensions | N/A | J | | N/A |



| Field Measurements/Component Compliance | | | | | | | | | | | |
|---|------------------------|----------------------------------|--------|-----|-----------|------------------------|--------|--|--|--|--|
| - [| Compliance Description | | Data | Com | pliance | Description | Data | | | | |
| | N/A | Ramp Length (in) | 82 | N/A | Flare Ty | pe LT | | | | | |
| | Yes | Ramp Width (in) | 54 | | | | Sloped | | | | |
| | Yes | Ramp Run Slope (%) | 5.6 | N/A | Flare Slo | ope LT (%) | 3.8 | | | | |
| | Yes | Ramp Cross Slope (%) | 1.7 | N/A | Flare Tra | aversable LT | No | | | | |
| | N/A | Landing Present | Yes | N/A | Flare Ty | pe RT | | | | | |
| | N/A | Landing Length (in) | 49 | | | | Sloped | | | | |
| | Yes | Landing Width (in) | 54 | N/A | Flare Slo | ope RT (%) | 9.8 | | | | |
| | Yes | Landing Run Slope (%) | 0.6 | N/A | Flare Tra | aversable RT | No | | | | |
| | Yes | Landing Cross Slope (%) | 1.9 | No | DWS Pr | ovided | No | | | | |
| | N/A | Landing Movement Obstructed? | Yes | N/A | DWS Co | ontrast | N/A | | | | |
| | | Landing Movement Type Bu | ushes | N/A | DWS Le | ngth (in) | N/A | | | | |
| | N/A | Landing Shared | No | N/A | DWS Fu | ll Width | N/A | | | | |
| | N/A | Clear Space | Yes | N/A | DWS Of | fset Left (in) | N/A | | | | |
| | N/A | Clear Space To Crosswalk (in) | 48 | N/A | DWS Of | fset Right (in) | N/A | | | | |
| 2 | N/A | Marked Crosswalk 1 | No | N/A | Marked | Crosswalk 2 | No | | | | |
| | | Crossing 1 Direction | Ε | | Crossing | g 2 Direction | N | | | | |
| D | | Marked Crosswalk 1 Width (in) | N/A | | Marked | Crosswalk 2 Width (in) | N/A | | | | |
| ı | N/A | Ramp Inside Crosswalk 1 | N/A | Yes | Ramp In | side Crosswalk 2 | N/A | | | | |
| R | | Crossing 1 Slope (%) | 8 | | Crossing | g 2 Slope (%) | 3 | | | | |
| ı | | Crossing 1 Cross Slope (%) | 3.5 | | Crossing | g 2 Cross Slope (%) | 1.5 | | | | |
| | Yes | Gutter Ponding | No | No | Curb Slo | ope | 10.9 | | | | |
| | Yes | Gutter Lip Height (in) | 0 | | Road R | un Slope (%) | 0.5 | | | | |
| | No | Gutter Run Slope (%) | 6.3 | | Road Cr | oss Slope (%) | 4.6 | | | | |
| <u>a</u> | No | Gutter Cross Slope (%) | 2.8 | | | | | | | | |
| 0 | Yes | Overall Surface Condition: Accep | otable | No | Perp Joi | int Present | No | | | | |
| | | Cross Gutter Present? | No | | Spandre | l Present? | No | | | | |
| A | | Replace Cross Gutter? | N/A | | Replace | Spandrel? | N/A | | | | |