

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: TIGERTAIL_DR Cross Street: FOSTER_RD Location: NW

ADA ID: RPRK211207124905 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New
Directional Ramps or Equivalent. Remove &
Replace Gutter.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.2, R304.2.1, R304.5.3, STD 1115

Total Cost: \$ 6412

Parcel ID Number	086-461-13
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name
TIGERTAIL_DR
Stop Condition-Street 1
StopSign
Street 2 Name
Stop Condition-Street 2
NoControl

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.77720717,-118.08350626}$

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	pliance Description	<u>Data</u>
Yes	Obstructions Present?	No	N/A	Utilities Present?	No
	Obstruction Types	N/A		Utility Types	
	Obstruction Dimensions	N/A	l		N/A



Field Measurements/Component Compliance									
	Com	pliance Description	Data	Com	pliance	Description	Data		
	N/A	Ramp Length (in)	78	N/A	Flare Ty	pe LT			
	Yes	Ramp Width (in)	48				Sloped		
	Yes	Ramp Run Slope (%)	7.5	N/A	Flare Slo	ope LT (%)	9.6		
	Yes	Ramp Cross Slope (%)	1.9	N/A	Flare Tra	aversable LT	No		
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT			
	N/A	Landing Length (in)	55				Sloped		
	Yes	Landing Width (in)	48	N/A	Flare Slo	ope RT (%)	6.3		
	Yes	Landing Run Slope (%)	0.7	N/A	Flare Tra	aversable RT	No		
	No	Landing Cross Slope (%)	2.4	Yes	DWS Pr	ovided	Yes		
	N/A	Landing Movement Obstructed?	Yes	Yes	DWS Co	ontrast	Yes		
		Landing Movement Type	Wall	Yes	DWS Le	ngth (in)	36		
	N/A	Landing Shared	No	Yes	DWS Fu	ll Width	Yes		
	N/A	Clear Space	Yes	Yes	DWS Of	fset Left (in)	1		
	N/A	Clear Space To Crosswalk (in)	48	Yes	DWS Of	fset Right (in)	N/A		
2	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No		
		Crossing 1 Direction	S		Crossing	g 2 Direction	E		
R		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
n	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A		
D		Crossing 1 Slope (%)	7.9		Crossing	g 2 Slope (%)	6.4		
ol		Crossing 1 Cross Slope (%)	2.4		Crossing	g 2 Cross Slope (%)	0.8		
	Yes	Gutter Ponding	No	No	Curb Slo	ope	5.5		
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	3.6		
<u>a</u> o	Yes	Gutter Run Slope (%)	4.5		Road Cr	oss Slope (%)	8.1		
	No	Gutter Cross Slope (%)	2.8						
	Yes	Overall Surface Condition: Accep	otable	Yes	Perp Jo	int Present	Yes		
۱		Cross Gutter Present?	No		Spandre	l Present?	No		
Α		Replace Cross Gutter?	N/A		Replace	Spandrel?	N/A		
	1								