

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



SE

25

Main Street: COPA\_DE\_ORO\_DR

Cross Street: BELLWOOD\_RD

Location:

ADA ID: RPRK211207134210

Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No

Severity Score:

## Codes/Mitigation Info/Possible Solution



Possible Solutions:

Remove & Replace Curb Ramp With Two New
Directional Ramps or Equivalent.

Surveyor Notes:

N/A

OC Std/PROW:

R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.3, R304.2.3, R305, STD 1115

Total Cost: \$ 6160

Parcel ID Number	086-245-05	Street 1 Name	COPA_DE_ORO_DR
Ramp Island Or Median	None	Stop Condition-Street 1	NoControl
Ramp Orientation	Diag	Street 2 Name	BELLWOOD_RD
Google Street View Link:		Stop Condition-Street 2	NoControl

http://www.google.com/maps/@?api=1&map\_action=pano&viewpoint=33.780583,-118.08129979

## **Obstruction and Utility Measurement/Component Compliance**

Compliance Description	Data Compliance Description	<u>Data</u>
Yes Obstructions Present?	No N/A Utilities Present?	No
Obstruction Types	N/A Utility Types	
Obstruction Dimensions	N/A	N/A



Field Measurements/Component Compliance									
	Compliance Description		Data	a Compliance Description			Data		
o New	N/A	Ramp Length (in)	131	N/A	Flare Ty	pe LT			
	Yes	Ramp Width (in)	48				Sloped		
	Yes	Ramp Run Slope (%)	4.7	No	Flare Slo	ope LT (%)	16.4		
	Yes	Ramp Cross Slope (%)	1	N/A	Flare Tra	aversable LT	Yes		
	N/A	Landing Present	No	N/A	Flare Ty	pe RT			
	N/A	Landing Length (in)	N/A				Sloped		
	No	Landing Width (in)	N/A	N/A	Flare Sl	ope RT (%)	19.7		
	No	Landing Run Slope (%)	N/A	N/A	Flare Tra	aversable RT	No		
	No	Landing Cross Slope (%)	N/A	No	DWS Pr	ovided	No		
	N/A	Landing Movement Obstructed?	No	N/A	DWS Co	ontrast	N/A		
		Landing Movement Type	N/A	N/A	DWS Le	ength (in)	N/A		
, R304.5.3,	N/A	Landing Shared	N/A	N/A	DWS Fu	ıll Width	N/A		
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A		
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Of	fset Right (in)	N/A		
\$ 6160	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No		
		Crossing 1 Direction	W		Crossing	g 2 Direction	N		
E_ORO_DR		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A		
NoControl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	iside Crosswalk 2	N/A		
LWOOD_RD		Crossing 1 Slope (%)	6.6		Crossing	g 2 Slope (%)	4.4		
NoControl		Crossing 1 Cross Slope (%)	1.3		Crossing	g 2 Cross Slope (%)	1.5		
	Yes	Gutter Ponding	No	Yes	Curb Slo	ope	3.5		
	Yes	Gutter Lip Height (in)	0		Road R	un Slope (%)	1.2		
Data	Yes	Gutter Run Slope (%)	1.3		Road Cr	ross Slope (%)	1.7		
Data	Yes	Gutter Cross Slope (%)	1.3						
No	Yes	Yes Overall Surface Condition: Accep		Yes	Perp Jo	int Present	Yes		
N/A		Cross Gutter Present?	Yes		Spandre	el Present?	Yes		
N/A		Replace Cross Gutter?	No		Replace	Spandrel?	No		