

ADA ID: RPRK211216122013

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Main Street: BLUME DR **Cross Street: CHRISTY LN** 

SE Location: Ramp Type: Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 12

**Codes/Mitigation Info/Possible Solution** 



Possible Solutions:

Remove & Replace Curb Ramp With Two New **Directional Ramps or Equivalent. Gutter Ponding** 

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.2.2-Perp, R304.3.2-Para, R305, R302.7, STD 1115

Total Cost: 6412

Parcel ID Number **086-231-05** Street 1 Name Ramp Island Or Median None Stop Condition-Street 1 Ramp Orientation Diag Street 2 Name Google Street View Link: Stop Condition-Street 2

 $\underline{http://www.google.com/maps/@?api=1\&map\_action=pano\&viewpoint=33.78300958,-118.08365621}$ 

## **Obstruction and Utility Measurement/Component Compliance**

Compliance Description Data		Compliance Description	Data	
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance											
	Com	pliance Description	Data	Com	pliance	Description	Data				
Two New	N/A	Ramp Length (in)	81	N/A	Flare Ty	pe LT					
itter Ponding	Yes	Ramp Width (in)	48				Sloped				
	Yes	Ramp Run Slope (%)	6.9	N/A	Flare Slo	ppe LT (%)	5				
	Yes	Ramp Cross Slope (%)	0.4	N/A	Flare Tra	aversable LT	No				
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT					
	N/A	Landing Length (in)	48				Sloped				
	Yes	Landing Width (in)	48	N/A	Flare Slo	ppe RT (%)	3.5				
	No	Landing Run Slope (%)	2.6	N/A	Flare Tra	aversable RT	No				
	Yes	Landing Cross Slope (%)	8.0	No	DWS Pro	ovided	No				
	N/A	Landing Movement Obstructed?	No	N/A	DWS Co	ontrast	N/A				
		Landing Movement Type	N/A	N/A	DWS Le	ngth (in)	N/A				
a, R305,	N/A	Landing Shared	No	N/A	DWS Fu	ll Width	N/A				
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A				
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Off	fset Right (in)	N/A				
\$ 6412	N/A	Marked Crosswalk 1	No	N/A	Marked (	Crosswalk 2	No				
		Crossing 1 Direction	N		Crossing	g 2 Direction	W				
BLUME_DR		Marked Crosswalk 1 Width (in)	N/A		Marked (	Crosswalk 2 Width (in)	N/A				
NoControl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A				
CHRISTY_LN		Crossing 1 Slope (%)	5.7		Crossing	g 2 Slope (%)	4.9				
NoControl		Crossing 1 Cross Slope (%)	0.2		Crossing	g 2 Cross Slope (%)	0.4				
	No	Gutter Ponding	Yes	Yes	Curb Slo	рре	1.5				
	Yes	Gutter Lip Height (in)	0		Road Ru	un Slope (%)	0.2				
	Yes	Gutter Run Slope (%)	1.4		Road Cr	oss Slope (%)	0				
Data	Yes	Gutter Cross Slope (%)	0								
No	Yes	Overall Surface Condition: Accep	otable	No	Perp Joi	nt Present	No				
		Cross Gutter Present?	Yes		Spandre	I Present?	Yes				
N/A		Replace Cross Gutter?	No		Replace	Spandrel?	No				
The second secon											