

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: ACECA_DR Cross Street: NORGROVE_LN Location: NW

ADA ID: RPRK211216132457 Ramp Type:Type 1 - Perpendicular Diagonal Initial Pass/Fail: Pass

Overall Compliance: No Sev

Severity Score: 12

Codes/Mitigation Info/Possible Solution

	Codes/Mitigation Info/P
	I NORGE
	NORGROVE LN
Acec	5

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Grind Gutter Lip.

Surveyor Notes:

N/A

OC Std/PROW:

R204.3, R304.2.2-Perp, R304.3.2-Para, R305, R302.7, R302.7.2, STD 1115

Total Cost: \$ 6310

Parcel ID Number	086-322-17	Street 1 Name	
Ramp Island Or Median	None	Stop Condition-Street 1	
Ramp Orientation	Diag	Street 2 Name	NOR
Google Street View Link:		Stop Condition-Street 2	

 $\underline{http://www.google.com/maps/@?api=1\&map_action=pano\&viewpoint=33.79112914,-118.08100559}$

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Compliance Description	Data
Yes	Obstructions Present?	No	N/A Utilities Present?	No
	Obstruction Types	N/A	Utility Types	
	Obstruction Dimensions	N/A		N/A



Field Measurements/Component Compliance							
	Compliance Description		Data	Com	Compliance Description		
Two New	N/A	Ramp Length (in)	81	N/A	Flare Ty	pe LT	
nd Gutter	Yes	Ramp Width (in)	48				Sloped
	Yes	Ramp Run Slope (%)	8	N/A	Flare Slo	ope LT (%)	4.7
	Yes	Ramp Cross Slope (%)	1.3	N/A	Flare Tra	aversable LT	No
	N/A	Landing Present	Yes	N/A	Flare Ty	pe RT	
	N/A	Landing Length (in)	49				Sloped
	Yes	Landing Width (in)	48	N/A	Flare Slo	ope RT (%)	5.5
	No	Landing Run Slope (%)	2.2	N/A	Flare Tra	aversable RT	No
	Yes	Landing Cross Slope (%)	1.6	No	DWS Pr	ovided	No
	N/A	Landing Movement Obstructed?	No	N/A	DWS Co	ontrast	N/A
		Landing Movement Type	N/A	N/A	DWS Le	ength (in)	N/A
, R305,	N/A	Landing Shared	No	N/A	DWS Fu	ıll Width	N/A
	N/A	Clear Space	Yes	N/A	DWS Of	fset Left (in)	N/A
	N/A	Clear Space To Crosswalk (in)	48	N/A	DWS Of	fset Right (in)	N/A
\$ 6310	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No
		Crossing 1 Direction	S		Crossing	g 2 Direction	E
ACECA_DR		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A
NoControl	N/A	Ramp Inside Crosswalk 1	N/A	Yes	Ramp In	side Crosswalk 2	N/A
ORGROVE_LN		Crossing 1 Slope (%)	6.8		Crossing	g 2 Slope (%)	1.2
NoControl		Crossing 1 Cross Slope (%)	0.2		Crossing	g 2 Cross Slope (%)	3.2
	No	Gutter Ponding	Yes	Yes	Curb Slo	ope	3.4
	No	Gutter Lip Height (in)	0.25		Road R	un Slope (%)	0.8
	Yes	Gutter Run Slope (%)	0.2		Road Cr	ross Slope (%)	2
<u>Data</u>	Yes	Gutter Cross Slope (%)	8.0				
No	Yes	Overall Surface Condition: Acce	eptable	No	Perp Jo	int Present	No
		Cross Gutter Present?	Yes		Spandre	el Present?	Yes
N/A		Replace Cross Gutter?	No	l	Replace	Spandrel?	No
The second secon	•						