

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Main Street: VAN_BUREN_ST **Cross Street: MCFADDEN AVE** NE Location: ADA ID: RPRK220202115149 Ramp Type: Type 4 - Parallel Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 15

Codes/Mitigation Info/Possible Solution



Possible Solutions: Remove & Replace Curb Ramp With Two New **Directional Ramps or Equivalent. Grind Gutter**

Surveyor Notes:

N/A

OC Std/PROW:

R304.3.2, R302.7.2, STD 1115

Total Cost: 4150

Parcel ID Number	107-171-03
Ramp Island Or Median	None
Ramp Orientation	Diag
Google Street View Link:	

Street 1 Name VAN_BUREN_ST Stop Condition-Street 1 StopSign MCFADDEN_AVE Street 2 Name Stop Condition-Street 2 **NoControl**

http://www.google.com/maps/@?api=1&map_action=pano&viewpoint=33.73759657,-117.98618864

Obstruction and Utility Measurement/Component Compliance

Com	pliance Description	Data	Com	pliance	Description	Data
Yes	Obstructions Present?	No	N/A	Utilities	Present?	No
	Obstruction Types	N/A		Utility T	ypes	
	Obstruction Dimensions	N/A	l			N/A



Field Measurements/Component Compliance								
	Com	pliance Description	Data	Com	pliance	Description	Data	
	N/A	Ramp Length LT (in)	64	N/A	Ramp L	ength RT (in)	91	
	Yes	Ramp Width LT (in)	118	Yes	Ramp V	/idth RT (in)	119	
	No	Ramp Run Slope LT (%)	8.7	Yes	Ramp R	un Slope RT (%)	5.1	
	Yes	Ramp Cross Slope LT (%)	1.9	Yes	Ramp C	ross Slope RT (%)	1.5	
	N/A	Landing Present	N/A	N/A	DWS Pr	rovided	N/A	
	N/A	Landing Length (in)	N/A	N/A	DWS Co	ontrast	N/A	
	N/A	Landing Width (in)	N/A	N/A	DWS Le	ength (in)	N/A	
	N/A	Landing Run Slope (%)	N/A	N/A	DWS Fu	ıll Width	N/A	
	N/A	Landing Cross Slope (%)	N/A		DWS Of	fset Type	N/A	
	N/A	Landing Movement Obstructed?	N/A	N/A	DWS Of	ffset Left (in)	N/A	
		Landing Movement Type	N/A	N/A	DWS Of	ffset Right (in)	N/A	
	N/A	Landing Shared	N/A					
	N/A	Clear Space	Yes					
	N/A	Clear Space To Crosswalk (in)	N/A					
0	N/A	Marked Crosswalk 1	No	N/A	Marked	Crosswalk 2	No	
		Crossing 1 Direction	W		Crossing	g 2 Direction	S	
Т		Marked Crosswalk 1 Width (in)	N/A		Marked	Crosswalk 2 Width (in)	N/A	
n	N/A	Ramp Inside Crosswalk 1	N/A	N/A	Ramp Ir	nside Crosswalk 2	N/A	
Ε		Crossing 1 Slope (%)	3.6		Crossing	g 2 Slope (%)	6.7	
ol		Crossing 1 Cross Slope (%)	2.3		Crossing	g 2 Cross Slope (%)	0.3	
	N/A	Gutter Ponding	N/A	N/A	Curb Slo	оре	1.6	
	No	Gutter Lip Height (in)	0.5		Road R	un Slope (%)	0.2	
	N/A	Gutter Run Slope (%)	N/A		Road Co	ross Slope (%)	1.9	
a	N/A	Gutter Cross Slope (%)	N/A	Yes	Perpend	licular Joint Present	Yes	
0	Yes	Overall Surface Condition Accep	otable					
		Cross Gutter Present?	Yes		Spandr	el Present?	Yes	
Α		Replace Cross Gutter?	No		Replace	e Spandrel?	No	
	1							